

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)		Date Received 05/05/2025		AI Number	
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual) R							
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation) ER							
III. FACILITY DESCRIPTION (Include building name, number and floor or room number)							
Bldg. Name: HARRISON COUNTY COURTHOUSE							
Address 1801 23RD AVENUE							
City: GULFPORT				State: MS		Zip: 39502	
Site Location: 1ST FLOOR				Tel: 228-867-0136			
Building Size 69,000 SQ. FT.				# of Floors: 2		Age in Years: 48	
Present Use: COURTHOUSE				Prior Use: COURTHOUSE			
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)							
OWNER NAME: HARRISON COUNTY							
Address: 1801 23RD AVENUE							
City: GULFPORT				State: MS		Zip: 39502	
Contact: CHRIS ATHERTON				Tel: 228-861-3386			
ASBESTOS REMOVAL CONTRACTOR: WILLIAM S. FOLKS, GUARANTEE ENVIRONMENTAL SERVICES, LLC							
Address: 16248 PERKINS ROAD							
City: BATON ROUGE				State: LA		Zip: 70810	
Contact: SHANNON RIVETT				Tel: 225-753-8682 EXT. 227			
Certification Number: ABC-00011409				Expiration Date: 07/18/2025			
OTHER OPERATOR: GUARANTEE RESTORATION SERVICES, LLC							
Address: 16248 PERKINS ROAD							
City: BATON ROUGE				State: LA		Zip: 70810	
Contact: DARRICK SHANK				Tel: 225-753-8682			
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES							
WAS ASBESTOS PRESENT? (Yes/No): YES				Inspection Date: 4/15/25			
Inspector: DILLON PEARSON		Certification Number: ABI-00013290			Expiration Date: 12/18/2025		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:							
samples were taken of drywall, joint compound on 2nd floor and were negative. Samples of were taken of vinyl plank floor, VACT & mastic on the 1st floor and sent to eurofins lab where they used polarized light method for testing. See report analysis for details. Vinyl plank floor, VACT and mastic were all positive for asbestos.							
VII. QUANTITY OF RACM TO BE REMOVED: 25 cu. yds. 15,035 sq. ft. of flooring & mastic							
Pipes (LN FT):		Surface Area (SQ FT): 15035			Volume of Facility Components (CU FT):		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: n/a							
Category I:				Category II:			
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 5/12/25				Complete: 5/26/25			
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start:				Complete:			

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

utilize wet removal techniques to keep materials wet so there is no airborne release

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Double bag asbestos, wet methods, enviromental controls utilizing HEPA filtered air scrubbers in containment area.

XIII. WASTE TRANSPORTER #1

Name: Waste Pro USA

Address: 4205 Beasley Road

City: Gautier

State: MS

Zip: 39553

Contact Person: Renee

Tel: 228-818-5393

WASTE TRANSPORTER #2

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: Pecan Grove Landfill-Waste Management of MS, Inc.

Address: 9685 Firetower Road

City: Pass Christian

State: MS

Zip: 39571

Contact Person: Sam Williams

Tel: 228-475-9750

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY): 04/10/25 5:00 pm

Description of the sudden unexpected event:

courthouse flooded from 2nd floor clean water source bathroom down to the 1st floor

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

Please see 3rd page.


XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

Stop work, verify suspect material is RACM or not, obtain additional permits if necessary

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Shannon Rivett

Type or Print Name


(Signature of Owner/Operator)

4/17/25

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Shannon Rivett

Type or Print Name


(Signature of Owner/Operator)

4/17/25

(Date)