
## Mississippi Office of Pollution Control Lead-Based Paint Abatement/Renovation Notification





MDEO	Use Only:						
Ema	il Mail Hand Del	Postmark (mail only ivery		e Received 3/27/2024	Al Number		
	moon an applicable 003	nt Renovation tes for the type of Notific fication was also subm	ation: 🖿 Owice	:	on: 1973 Cancellation Emergency		
I.	City: Yazoo City		Zip Code:	39194 Coun	ty: Yazoo		
II.		R INFORMATION ashington West 13th St			ate: MS ZIP: 39194		
III.	ABATEMENT/RENOVATION CONTRACTOR INFORMATION  Name of Certified Lead Abatement/Renovator Firm: Kevin Armstrong  Firm Certification Number: PBR-00012238 Telephone Number: (501) 318-7783 Exp. Date: 07/05/2024  Address of Certified Firm: 22201 Vance Road						
	City: Lonsdale		ate: AR	Zij	o Code: 72087		
	Certification Number Test Method Used &	Inspector/Risk AssessoExp. I	oate: Equipment:_	Date Inspec	tion Conducted:		
V.	GENERAL CONTR Name of Firm: Window	ACTOR (Other)					
	Contact Person: Christ		· · · · · · · · · · · · · · · · · · ·	phone Number:(5	<sup>501</sup> ) 760-0292		
	PROJECT DATES Lead Project Start: 04 Abatement/Renovation	/01 /2024 n to be done during wha	Lead Proj t time? 🔲 Da	ect Stop: <u>04 /</u> 0	01 /2024 ) Evening (5 p.m. – 8 p.m		
VII.	DESCRIPTION OF	PROCEDURES TO BI	E USED (CH	ECK ALL THA	T APPLY)		
İ	Wet Sanding Containment Other – Explain	☐ Component Removal	al	Heat Gun Negative Air	Encapsulation Enclosure		

## VIII. DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING COMPONENTS TO BE AFFECTED)

Retro Fit Pocket Replacement of Existing Windows with New Vinyl Windows

	WASTE TRANSPORTER						
	Name: Kevin Armstrong						
	Full Mailing Address: 22201 Vance Road						
	City: Lonsdale	State: AR	Zip Code: 72087				
	Contact: Kevin Armstrong	_ Telephone Numbe	r: ( <sup>501</sup> )318-7783				
X.	WASTE LEAD DISPOSAL SITE						
	Site Name: The Faircloth Rubbish Landfill						
	Physical Address: 1312 Springridge Road						
	Full Mailing Address:						
	City: Clinton	State: MS	Zip Code:				
XI.	DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD						
	Site Name:						
	Physical Address:						
	Full Mailing Address:						
	City:	State:	Zip Code:				
	Contact Person:  NOTE: All debris (other than lead) should go	_ Telephone Numbe	er: ()_				
	NOTE: All debris (other than lead) should go	to an authorized Rubb	ish Site, or to a permitted sanitary landfill.				
XII.	ABATEMENT						
	A certified supervisor is required for each abated during the post-abatement cleanup and clearance being conducted, the certified supervisor shall be able to be present at the work site in no more than	e of work areas. At all consite or available by	other times when abatement activities are				
XIII.	RENOVATION						
	A certified renovator is required for each renova are posted, while the required work area contain performed. The certified renovator must regular available either onsite or by telephone at all time	ment is being establish rly direct work being p	ed, and while required work area cleaning is erformed by other individuals and must be				
XIV.	CERTIFICATION OF ACCURACY						
	I certify that all of the above information is corre	ect.	<b>3</b> .				
	Print Kevin Armstrong Sign	iature IVIN (	WMOMNY Date 03/27/2024				
	Print total value of g	I ALUID TO THE					
	Contact information for return mail or questions						
	Contact information for return mail or questions Mailing Address: 22201 Vance Road						
	Contact information for return mail or questions Mailing Address: 22201 Vance Road City: Lonsdale	concerning the inform	R Zip Code: 72087				
	Contact information for return mail or questions Mailing Address: 22201 Vance Road	concerning the inform State: A Telephone N	ation on this Notice				

Lead Notifications

P.O. Box 2261, Jackson, MS 39225