## Mississippi Office of Pollution Control Lead-Based Paint Abatement/Renovation Notification





Emai	Mail Hand Delivery	04-13-2024	Date Received	Al Number			
			04-15-2024				
Project	Type: Abatement	Renovation Dat	e of Building Construction	on: 1950			
Please c	heck all applicable boxes for	the type of Notification:	Original Revision	Cancellation Emergency			
	check if asbestos notificati	on was also submitted	for this project:				
I.	PROJECT/SITE INFOR	_					
	Target Housing: Child-Occupied Facility:	]					
	Physical Address Project Site: 1452 Watkins Street						
	City: Natchez		Zip Code: 39120 Cour	nty: Adams			
	Number of Units to be Abated/Renovated in the Building: replacing 10 windows						
II.	BUILDING OWNER INFORMATION						
	Mr./Mrs.:Roderick Ransom						
	Address of Owner: 1452 W	atkins Street C	ity: Natchez S	tate: MS ZIP: 39120			
	Telephone Number: (601)4						
III.	ABATEMENT/RENOV	ATION CONTRACTO	OR INFORMATION				
	Name of Certified Lead Abatement/Renovator Firm: Gary Ogle						
	Firm Certification Number: PBR-00010175 Telephone Number: (601) 862-8033 Exp. Date: 03/28/2024						
	Address of Certified Firm:		//	12-19-2024			
			MS Z	in Code: 39047			
IV.	INSPECTION INFORM						
17.	Name of Renovator/Inspector/Risk Assessor Conducting Inspection:						
				ction Conducted:			
	Test Method Used & Manufacturer of Testing Equipment:						
	For Paint Chip Analysis, Name of Laboratory: Certification Number:						
V.	GENERAL CONTRACT						
**	Name of Firm: Windows US						
	Firm Mailing Address: PO Box 222, Royal, AR 71968						
	Contact Person: Christine V		Telephone Number:	(501) 760-0292			
VI.	PROJECT DATES						
V 1.		22 /2024	Lead Project Stop: 04	/22 /2024			
				n.) Evening (5 p.m. – 8 p.r			
		S	□Night (8 p.m. – 5 a				
VII	DESCRIPTION OF PRO	CEDUDES TO DE U		•			
V 11.	DESCRIPTION OF PRO	r te					
	Wet Sanding  ☐ Containment	Component Removal Strip and Removal	☐ Heat Gun☐ Negative Air	Encapsulation Enclosure			
	Other – Explain	p with removal		Dictosure			

## VIII. DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING COMPONENTS TO BE AFFECTED)

Retro Fit Pocket Replacement of Existing Windows with New Vinyl Windows

Full Mailing Address: 126 Cape Charles  City: Brandon State: MS Zip Code: 39047  Contact: Gary Ogle Telephone Number: (601) 862-8033  X. WASTE LEAD DISPOSAL SITE  Site Name: Canton Sanitary Landfill  Physical Address: 303 Soldiers Colony Road  Full Mailing Address:  City: Canton State: MS Zip Code: 39046	IX.	WASTE TRANSPORTER Name: Gary Ogle					
City: Brandon State: MS Zip Code: 39047 Contact: Gary Ogle Telephone Number: (601) 862-8033  X. WASTE LEAD DISPOSAL SITE Site Name: Canton Sanitary Landfill Physical Address: 303 Soldiers Colony Road Full Mailing Address: City: Canton State: MS Zip Code: 39046  XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address: Full Mailing Address: City: State: Zip Code: Contact Person: Telephone Number: (1) NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.  XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area containment is being established, and while required work area containment is being established, and while required work area containment is being established, and while required work area containment is being established, and while required work area containment is being established. And while required work area containment is being established, and while required work area containment is being established. And while required work area containment is being established, and while required work area containment is being established. And while required work area containment is being established. And while required work area containment is being established. And while required work area containment is being established. And while required work area containment is being established. And while required work area containment is being establis							
X. WASTE LEAD DISPOSAL SITE Site Name: Canton Sanitary Landfill Physical Address: 303 Soldiers Colony Road Full Mailing Address: City: Canton State: MS Zip Code: 39046  XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address: City: State: Zip Code: Contact Person: Telephone Number: () NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.  XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII.RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Gary Ogle Signature Date 04/13/2024  Contact information for return mail or questions concerning the information on this Notice Mailing Address: 126 Cape Charles City: Brandon State: MS Zip Code: 39047 Contact: Gary Ogle Telephone Number: (601) 862-8033 Email: 9ary.ogle@windowsusa.com		1,230	State: MS	7in Code: 39047			
X. WASTE LEAD DISPOSAL SITE  Site Name: Canton Sanitary Landfill  Physical Address: 303 Soldiers Colony Road  Full Mailing Address:  City: Canton State: MS Zip Code: 39046  XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD  Site Name:  Physical Address:  Full Mailing Address:  City:  State:  Zip Code:  Zip Code:  Contact Person:  NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.  XII. ABATEMENT  A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII. RENOVATION  A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified supervisor must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY  I certify that all of the above information is correct.  Print Gary Ogle Signature  Date 04/13/2024  Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon  Contact: Gary Ogle Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com			Telephone Number: (	601 \ 862-8033			
Site Name: Canton Sanitary Landfill Physical Address: 303 Soldiers Colony Road Full Mailing Address: City: Canton State: MS Zip Code: 38046  XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address: Full Mailing Address: City: State: Zip Code: Contact Person: Telephone Number: Description of the sense of the sens	• •		_ receptione (valider. (				
Physical Address: 303 Soldiers Colony Road  Full Mailing Address:	Χ.						
Full Mailing Address: City: Canton State: MS Zip Code: 39046  XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address: Full Mailing Address: City: State: Zip Code: Contact Person: NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.  XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Gary Ogle Signature Date 04/13/2024  Contact information for return mail or questions concerning the information on this Notice Mailing Address: 126 Cape Charles City: Brandon State: MS Zip Code: 39047  Contact: Gary Ogle Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com			•				
City: Canton State: MS Zip Code: 39046  XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD  Site Name:							
Site Name:  Physical Address:  Full Mailing Address:  City:  State:  Zip Code:  Contact Person:  NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.  XII. ABATEMENT  A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII. RENOVATION  A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY  I certify that all of the above information is correct.  Print Gary Ogle Signature  Signature  Date  04/13/2024  Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon  State: MS Zip Code: 39047  Contact: Gary Ogle Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com		Full Mailing Address:					
Site Name:  Physical Address:  Full Mailing Address:  City:  State:  Zip Code:  Contact Person:  NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.  XII. ABATEMENT  A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII. RENOVATION  A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY  I certify that all of the above information is correct.  Print Gary Ogle Signature  Outed: Signature  Date  04/13/2024  Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon  State: MS Zip Code: 39047  Contact: Gary Ogle Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com		City: Canton	State: MS	Zip Code: 39046			
Physical Address:  Full Mailing Address:  City:  State:  Zip Code:  Contact Person:  NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.  XII. ABATEMENT  A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII. RENOVATION  A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY  I certify that all of the above information is correct.  Print Gary Ogle  Signature  Date  04/13/2024  Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon  State: MS  Zip Code: 39047  Contact: Gary Ogle  Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com	XI.	DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD					
Physical Address:  Full Mailing Address:  City:  State:  Zip Code:  Contact Person:  NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.  XII. ABATEMENT  A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII. RENOVATION  A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY  I certify that all of the above information is correct.  Print Gary Ogle  Signature  Date  04/13/2024  Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon  State: MS  Zip Code: 39047  Contact: Gary Ogle  Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com		Site Name:		40/6000			
Full Mailing Address:  City:  State:  Zip Code:  Contact Person:  NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.  XII. ABATEMENT  A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII. RENOVATION  A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct.  Print Gary Ogle  Signature  Date  04/13/2024  Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon  State: MS  Zip Code: 39047  Contact: Gary Ogle  Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com							
City:							
Contact Person:							
NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.  XII. ABATEMENT  A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII.RENOVATION  A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY  I certify that all of the above information is correct.  Print Gary Ogle  Signature  Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon  State: MS  Zip Code: 39047  Contact: Gary Ogle  Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com							
A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII.RENOVATION  A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY  I certify that all of the above information is correct.  Print Gary Ogle  Signature  Signature  Date  04/13/2024  Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon  State: MS  Zip Code: 39047  Contact: Gary Ogle  Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com		NOTE: All debris (other than lead) should go	to an authorized Rubbish	Site, or to a permitted sanitary landfill.			
during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.  XIII. RENOVATION  A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY  I certify that all of the above information is correct.  Print Gary Ogle  Signature  Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon  State: MS  Zip Code: 39047  Contact: Gary Ogle  Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com	XII.	ABATEMENT					
A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY  I certify that all of the above information is correct.  Print Gary Ogle  Signature  Signature  Out/13/2024  Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon  State: MS  Zip Code: 39047  Contact: Gary Ogle  Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com		during the post-abatement cleanup and clearance being conducted, the certified supervisor shall b	ce of work areas. At all oth e onsite or available by tele	er times when abatement activities are			
are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.  XIV. CERTIFICATION OF ACCURACY  I certify that all of the above information is correct.  Print Gary Ogle  Signature  Outling Address: 126 Cape Charles  City: Brandon  State: MS  Zip Code: 39047  Contact: Gary Ogle  Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com	XIII	RENOVATION					
I certify that all of the above information is correct.  Print Gary Ogle Signature Gary Ogle Date 04/13/2024  Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon State: MS Zip Code: 39047  Contact: Gary Ogle Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com		are posted, while the required work area contain performed. The certified renovator must regula	nment is being established, arly direct work being perfo	and while required work area cleaning is ormed by other individuals and must be			
Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon  Contact: Gary Ogle  Email: gary.ogle@windowsusa.com  Signature  Mull of Use 104/13/2024  Date 04/13/2024  Date 04/13/2024  Telephone Number: (601) 862-8033	XIV	CERTIFICATION OF ACCURACY					
Contact information for return mail or questions concerning the information on this Notice  Mailing Address: 126 Cape Charles  City: Brandon State: MS Zip Code: 39047 —  Contact: Gary Ogle Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com		I certify that all of the above information is corr	ect.	7-6			
Mailing Address: 126 Cape Charles  City: Brandon  Contact: Gary Ogle  Email: gary.ogle@windowsusa.com  State: MS  Sip Code: 39047  Telephone Number: (601) 862-8033		Print Gary Ogle Sig	nature MMG C	Date 04/13/2024			
City: Brandon State: MS Zip Code: 39047  Contact: Gary Ogle Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com		Contact information for return mail or question	s concerning the information	on on this Notice			
City: Brandon State: MS Zip Code: 39047  Contact: Gary Ogle Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com							
Contact: Gary Ogle Telephone Number: (601) 862-8033  Email: gary.ogle@windowsusa.com			State: MS	Zip Code: 39047			
Email: gary.ogle@windowsusa.com							
	Refer	***	ation fee. Notification fe	e must be submitted with notification			

EMAIL TO: notifications@mdeq.ms.gov

MAIL COPY TO: Mississippi Department of Environmental Quality

P.O. Box 2261, Jackson, MS 39225

**Lead Notifications**