MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: Email □Mail □Hand Delivery	Postmark (ma	il only)	Date Re	eceived 4/01/2024	Al Number 30829	
	I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Original					
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation						
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):						
Bldg. Name: Building 6901, Bryan Hall						
Address: Hercules Street						
_{City:} Keesler Air Force Base		State: MS		zip: 39534		
Site Location: Building 6901				Tel:		
Building Size: 110,000 sq ft		# of Floors: 2		Age in Years:40+		
Present Use: Vacant		Prior Use: Educational Building				
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)						
OWNER NAME: Keesler Air Force Base						
Address: 508 L Street						
City: Keesler AFB		State: MS		_{Zip:} 39534		
Contact: Robin Sykes				Tel: (228)481-4874		
ASBESTOS REMOVAL CONTRACTOR: Global Contracting, LLC						
Address: 226 Harry Sones Road						
_{City:} Carriere		State: MS		zip: 39426		
Contact: Eddie Blossman				Tel: (601)795-3401		
Certification Number: ABC-00001162		Expiration Date: January 9, 2024 01/06/2		9, 2024 01/06/2025		
OTHER OPERATOR: Southern Contracting, LLC						
Address: 777 Alloy Dr.						
City: Newbern		State: TN		z _{ip:} 38059		
Contact: Clint Cutrer				_{Tel:} (228)343-1158		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No):						
WAS ASBESTOS PRESENT? (Yes/No): Yes Inspec			Inspection			
Inspector: Charles D. Bingham Certification Number: ABI-00001348 Expiration Date: 02/09/2024 07/25/2025						
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Vinyl Floor tile and adhesives HVAC Duct components Thermal Piping Insulation (TSI) thermal Duct Insulation Suspended Ceiling Tiles Misc. Adhesives and Sealants						
Samples were analyzed by PLM with dispersion staining according to EPA Method 600/R-93/116 VII. QUANTITY OF RACM TO BE REMOVED:						
VII. QUANTITY OF RACM TO BE REMOVED: 150,000 sq ft of sheet rock, 5000 sq ft of floor tile and mastic, 1,000 ln ft of TSI						
Pipes (LN FT): 1,000 In ft	Surface Area (S	_{Q FT):} 155,000 s	q ft \	Volume of Facility Co	mponents (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:						
Category I: Category II:						
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 04/15/2024 Complete: 11/30/2024						
x. scheduled dates demo/renovation (MM/DD/YY) Start: 04/15/2024 Complete: 11/30/2024						

Removal of approximately 1,000 In ft of Thermal Systems Insucompound.	는데은	MOM SOUR MANE TOTALISM				
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERI DEMOLITION OR RENOVATION SITE:	NG CONTROLS TO BE USED	TO PREVENT EMISSIONS OF ASBESTOS AT THE				
Negative pressure containments, wet remo	oval, glove-bag remo	val, area and clearance monitoring.				
XIII. WASTE TRANSPORTER #1						
Name: Complete Environmental						
Address: 37 David Swan Lane						
City: Purivis	State: MS	z _{ip:} 39475				
Contact Person: Kevin Ivey		Tel: (601)794-2704				
WASTE TRANSPORTER #2						
Name:	r.					
Address:						
City:	State:	Zip:				
Contact Person:		Tel:				
XIV. WASTE DISPOSAL SITE						
Name: Pine Belt Regional Landfill						
Address: Hwy 29 North, 2 miles North of Hwy 42						
City: Runnelstown	State: MS	_{Zip:} 39401				
Contact Person: Tony Harrison		_{Tel:} (601)545-6642				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENC	CY, PLEASE IDENTIFY THE	AGENCY BELOW:				
Name:	Title:					
Authority:						
Date of Order (MM/DD/YY):	Date Ordered to	Begin (MM/DD/YY):				
XVI. FOR EMERGENCY RENOVATIONS:						
Date and Hour of Emergency (MM/DD/YY):						
Description of the sudden unexpected event:						
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:						
Explanation of the transfer database and all of the transfer of the transfer database and the tr						
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:						
Stop work immediately, contact regulatory	authorities wait for a	pproval of resume work.				
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.						
Type or Print Name	(Signature of Owner/Operator) 4/1/2024 (Date)					
EDDIE BLOSSMAN 4/1/2024						
Type or Print Name	(Signature of Owner/Operator)	(Date)				