
The submittal of this form is required to receive coverage and





RE-COVERAGE FORM

MINING STORM WATER, DEWATERING AND NO DISCHARGE GENERAL PERMIT

GENERAL PERMIT: MSR32 2 5 7 9. This coverage number must be completed for the referenced mining activity or this form will be considered incomplete and will be returned. The coverage number can be found at the bottom left corner of your previous Certificate of Coverage.

at the bottom of this form within 30 da Please indicate the activities to be cover	red by this Do Coversor	F	
		Form (check all that	apply).
X Storm Water Discharges Associat	ed with Mining	Mine Dewaterin	ng
Wastewater Recirculation System	with No Discharge		
The appropriate section of this form recirculation system with no discharge	must be completed if and/or discharge impor	the applicant propos inded mine water (dew	ses to operate a wastewate vatering).
If the company seeking coverage is a co attach proof of its registration with the This registration or Certificate of Good submittal of this coverage form. Cover	Mississippi Secretary of Standing must be dated	State and/or its Certi	ficate of Good Standing.
			THE RESIDENCE OF THE PARTY OF T
Mississippi Secretary of State.			
vississippi secretary of State.			not applicable)
ALL INFORMATION MU		indicate "N/A" where	not applicable)
ALL INFORMATION MU	ST BE COMPLETED	indicate "N/A" where	not applicable)
ALL INFORMATION MU APPLICANT IS THE OWNER OPERATOR CONTACT PERSON: Towny Jo	ST BE COMPLETED OF APPLICANT INFORM X OPERATOR	indicate "N/A" where	not applicable)
ALL INFORMATION MU APPLICANT IS THE OWNER OPERATOR CONTACT PERSON: SCRSWMA	APPLICANT INFORM APPLICANT INFORM OPERATOR DE Harvey	indicate "N/A" where	not applicable)
ALL INFORMATION MU APPLICANT IS THE OWNER DEPERATOR CONTACT PERSON: TOWNY JO DEPERATOR COMPANY NAME: SCRSWMA DEPERATOR STREET OR P. O. BOX: P. O. B	APPLICANT INFORM OPERATOR DE Harvey Box 308	indicate "N/A" where ATION (Must check one or both)	
ALL INFORMATION MU APPLICANT IS THE OWNER DEPERATOR CONTACT PERSON: Tommy Jo DEPERATOR COMPANY NAME: SCRSWMA DEPERATOR STREET OR P. O. BOX: P. O. B DEPERATOR CITY: Mendenhall	APPLICANT INFORM APPLICANT INFORM OPERATOR DE Harvey Box 308	Indicate "N/A" where ATION (Must check one or both) TATE: MS	ZIP: 39114
ALL INFORMATION MU APPLICANT IS THE OWNER OPERATOR CONTACT PERSON: Towny Jo OPERATOR COMPANY NAME: SCRSWMA OPERATOR STREET OR P. O. BOX: P. O. B OPERATOR CITY: Mendenhall OPERATOR PHONE #: (601) 847-2626	APPLICANT INFORM APPLICANT INFORM OPERATOR OPERATOR E	indicate "N/A" where ATION (Must check one or both)	ZIP: 39114
ALL INFORMATION MU APPLICANT IS THE OWNER OPERATOR CONTACT PERSON: Towny Jo OPERATOR COMPANY NAME: SCRSWMA OPERATOR STREET OR P. O. BOX: P. O. B OPERATOR CITY: Mendenhall OPERATOR PHONE #: (601) 847-2626	APPLICANT INFORM APPLICANT INFORM OPERATOR OPERATOR E	Indicate "N/A" where ATION (Must check one or both) TATE: MS	ZIP: 39114
ALL INFORMATION MU APPLICANT IS THE OWNER DEPERATOR CONTACT PERSON: TOMMY JO DEPERATOR STREET OR P. O. BOX: P. O. B DEPERATOR CITY: Mendenhall DEPERATOR PHONE #: (601) 847-2626 DEPERATOR CONTACT PERSON: Tommy Joe H. WINER COMPANY: SCRSWMA	APPLICANT INFORM OPERATOR OPERATOR OPERATOR OPERATOR E arvey	Indicate "N/A" where ATION (Must check one or both) TATE: MS	ZIP: 39114
ALL INFORMATION MU APPLICANT IS THE OWNER DEPERATOR CONTACT PERSON: Tommy Jo DEPERATOR COMPANY NAME: SCRSWMA DEPERATOR STREET OR P. O. BOX: P. O. B DEPERATOR CITY: Mendenhall	APPLICANT INFORM OPERATOR OPERATOR OPERATOR OPERATOR E arvey	Indicate "N/A" where ATION (Must check one or both) TATE: MS	ZIP: 39114
ALL INFORMATION MU APPLICANT IS THE OWNER DEPERATOR CONTACT PERSON: TOMMY JO DEPERATOR STREET OR P. O. BOX: P. O. B DEPERATOR CITY: Mendenhall DEPERATOR PHONE #: (601) 847-2626 DEPERATOR CONTACT PERSON: Tommy Joe H. WINER COMPANY: SCRSWMA	APPLICANT INFORM OPERATOR OPERATOR OPERATOR OPERATOR E arvey	indicate "N/A" where ATION (Must check one or both) TATE: MS MAIL: tjharvey@co.s	ZIP: 39114

IF CHECKED YES TO MINE DEWATERING, FILL OUT BELOW

	, FILL OUT BELOW
IS MINE COVERED UNDER VALID NPDES DISCHARGE PERMIT FOR MINE DEWA	TERING? YES NO
ESTIMATED DEWATERING VOLUME:(GAL/DAY)	
NAME AND ADDRESS OF THE RECIPIENT OF THE DISCHARGE MONITORING RE	PORTS (DMRs), IF DIFFERENT FROM SIGNATORY:
I certify under penalty of law that this document and all attachments were prepared under me to assure that qualified personnel properly gathered and evaluated the information submitted system, or those persons directly responsible for gathering the information, the information submitted system. I am aware that there are significant penalties for submitting false information violations. Authorized Signature Authorized Signature	based on my inquiry of the person or persons who manage the ibmitted is, to the best of my knowledge and belief, true, accurate, including the possibility of fine and imprisonment for knowing
To many Joe Harvey Char Printed Name Title	127,2018 ucen Clerk
This application shall be signed according to the General Permit, Act 15, T-4 as follows: For a corporation, by a responsible corporate officer. For a partnership, by a general partner. For a sole proprietorship, by the proprietor. For a municipal, state or other public facility, by either a principal executive officer, the mayor, or ranking elected official.	Please submit this form to: Chief, Environmental Permits Division MDEQ, Office of Pollution Control P.O. Box 2261 Lockson, Mississippi 30225

MINE INFORMATION

MINE SITE NAME: SCRSWMA Pit # 1						
CONTACT NAME & POSITION:						
CONTACT PHONE NUMBER: () MINE PHYSICAL SITE ADDRESS (IF NOT AVAILABLE INDICATE NEAREST NAMED ROAD):						
CITY: Pinola COUNTY: Simpson	ZIP: 39	149				
ATTACH A USGS QUAD MAP, EXTENDING ½ MILE BEYOND FACILITY, OUTLINING THE the Mississippi Office of Geology. For information call 601-961-5523). 5 1/2 of the NE1/4 OF SE 1/4 OF SECTION 31 , TOWNSHIP 1 North , R	MINE BOUNDARIES (Maj					
LATITUDE: 31 DEGREES 52 MINUTES 43 SECONDS LONGITUDE: 89 D	EGREES 55 MINUTES 0	7 SECONDS				
LAT & LONG DATA SOURCE (GPS (PLEASE GPS ENTRANCE GATE) OR MAP INTERPOLA						
TOTAL ACREAGE: 3.9 ac ± MATERIAL TO BE MINED: BOTTOW						
ESTIMATED START DATE: 2018-05-01 ESTIMATED END DA						
1/11	YYYY-MM-DD					
SIC CODE 1411 NAICS CODE						
STORM WATER POLLUTION PREVENTION PLA	N (SWPPP)					
THE GENERAL PERMIT REQUIRES THE SWPPP TO BE ONSITE OR LOCALLY AVAILABLE CONTROLLING STORM WATER POLLUTANTS. ACCORDINGLY, IN ADDITION TO THE PERMPS (SEE BELOW) ARE REQUIRED TO BE IN THE SWPPP.	E, UP-TO-DATE AND EFFI ROJECT'S CURRENT BMI	ECTIVE IN PS, TWO (2) SPECIFIC				
IS A COPY OF THE SWPPP AT THE PERMITTED SITE OR LOCALLY AVAILABLE?	X YES	NO				
DOES SWPPP CONTAIN AN UP-TO-DATE ASSESSMENT OF POTENTIAL STORM WATER POLLUTANT SOURCES AND IDENTIFY BMPS TO EFFECTIVELY CONTROL THEM?	XYES	NO				
IF A SEDIMENTATION BASIN IS A PROJECT BMP, DOES IT DISCHARGE ONLY FROM THE SURFACE OF THE BASIN? IF <u>NO</u> , THE BASIN MUST HAVE A SURFACE DISCHARGE IMME FROM THE DATE OF RECOVERAGE.		N.A. NO				
IF TRUCK TRAFFIC LEAVES MINING SITE AND MOVES DIRECTLY ONTO PAVED PUBLIC IS A CONSTRUCTION EXIT AN INSTALLED BMP? IF <u>NO</u> , A CONSTRUCTION EXIT MUST EINSTALLED IMMEDIATELY OF THE DATE OF RECOVERAGE. IF A MINE IS CURRENTLY INACTIVE, BUT IS SUBMITTING A RECOVERAGE FORM, THE CONSTRUCTION EXIT MUST INSTALLED IMMEDIATELY OF THE MINE BECOMING ACTIVE.	E	N.A. NO				
IS A WASTEWATER RECIRCULATION SYSTEM WITH NO DISCHARGE USED ON THE FAC	HLITY? YES	XNO				
IS MINE DEWATERING PRESENT ON SITE?	YES	XNO				
IF CHECKED YES TO WASTERWATER RECIRCULATION SYSTEM WITH N	O DISCHARGE, FILL OU	T BELOW				
IS MINE COVERED UNDER VALID "NO DISCHARGE" STATE OPERATING PERMIT?	YES	□NO				
PERMIT NO. MS						
DISTANCE BETWEEN RECIRCULATION POND(S) AND PROPERTY LINE: (FT (MUST BE AT LEAST 150 FEET)						
NUMBER OF RECIRCULATION POND(S):						
STORAGE CAPACITY OF EACH RECIRCULATION POND:		(FT³)				

