Mississippi Office of Pollution Control Lead-Based Paint Abatement/Renovation Notification





Email	See Only: ☐Mail ☐Hand Delivery	Postmark (mail only)	08-07-2024	Al Number	
Please ch	Type: Abatement eck all applicable boxes for heck if asbestos notification	the type of Notification:	■ Original □Revision	ction: 1960 Cancellation Emergency	-
I.	PROJECT/SITE INFORT Target Housing:				
	Physical Address Project S City: Holly Springs Number of Units to be Abate	State: MS Zi			_, _
II.	BUILDING OWNER IN Mr./Mrs.: Mary Ruth Stre	FORMATION	, <u> </u>		_
	Address of Owner: 345 N F Telephone Number: (662)2		:Holly Springs	State:_MSZIP:_38635	-
III.	ABATEMENT/RENOV. Name of Certified Lead Firm Certification Numbe Address of Certified Firm	Abatement/Renovator Fir: PBR-00011864 Telepho	rm: Trey Barkley	8-5455 Exp. Date: 02-05-2025	- ;04-30-2025 -
			S	Zip Code: 38652	-
IV.	Certification Number:	ector/Risk Assessor Con Exp. Date:	Date In	spection Conducted:	<u>.</u>
				tion Number:	
V.	GENERAL CONTRACT Name of Firm: Windows U Firm Mailing Address: PC	SA Box 222 Royal, AR			<u>-</u>
	Contact Person: Christine V	Valker	Telephone Numb	per:(501)760-0292	R
VI.			ead Project Stop: 08		
	Abatement/Renovation to	be done during what time		p.m.) Evening (5 p.m. – 8 5 a.m.) Weekend	p.m.)
VII.	DESCRIPTION OF PRO Wet Sanding Containment Other – Explain	CEDURES TO BE USE Component Removal Strip and Removal	Heat Gun Negative Ai	Encapsulation	

VIII.DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING COMPONENTS TO BE AFFECTED)

Retro Fit Pocket Replacement of Existing Windows with New Vinyl Windows

	Name: Trey Barkley				
	Full Mailing Address: 1158 CR 77				
	City: New Albany	State: MS	Zip C	ode: 38652	2
	Contact: Trey Barkley	Telephone Number	: (<u>662</u>) 598	3-5455	
X.	WASTE LEAD DISPOSAL SITE				
	Site Name: Canton Sanitary Landfill				
	Physical Address: 303 Soldiers Colony	Rd			
	Full Mailing Address:				
	City: Canton				6
XI.	DISPOSAL SITE FOR DEBRIS OTH	HER THAN LEAD			
	Site Name:				
	Physical Address:				
	Full Mailing Address:				
	City:				
			- 5		
	Contact Person:	Telephone Numbe	r: ()_		
	Contact Person:	Telephone Numbe go to an authorized Rubbi	r: ()_ sh Site, or	to a permitt	ed sanitary landfill.
XII.	Contact Person: NOTE: All debris (other than lead) should ABATEMENT	Telephone Numbe go to an authorized Rubbi	r: ()_ sh Site, or	to a permitt	ed sanitary landfill.
XII.		atement project and shall l ance of work areas. At all ll be onsite or available by	oe onsite du other times	ring all wor when abate	k site preparation an
	ABATEMENT A certified supervisor is required for each ab during the post-abatement cleanup and clear being conducted, the certified supervisor shall	atement project and shall l ance of work areas. At all ll be onsite or available by	oe onsite du other times	ring all wor when abate	k site preparation an
	ABATEMENT A certified supervisor is required for each ab during the post-abatement cleanup and clear being conducted, the certified supervisor shall able to be present at the work site in no more	ratement project and shall be ance of work areas. At all libe onsite or available by a than 2 hours. The area of	oe onsite du other times telephone, p oe physically ed, and whi erformed by	ring all wor when abate pager, or and y present while required y other indiv	k site preparation an ement activities are swering service, and the required signs work area cleaning is
XIII	ABATEMENT A certified supervisor is required for each ab during the post-abatement cleanup and clear being conducted, the certified supervisor shall able to be present at the work site in no more A.RENOVATION A certified renovator is required for each renare posted, while the required work area con performed. The certified renovator must reg	ratement project and shall he ance of work areas. At all libe onsite or available by a than 2 hours. The action project and shall be tainment is being established all are being project are being project.	oe onsite du other times telephone, p oe physically ed, and whi erformed by conducted.	ring all wor when abate pager, or an y present while required y other indiv	k site preparation an ement activities are swering service, and the required signs work area cleaning is
XIII	ABATEMENT A certified supervisor is required for each ab during the post-abatement cleanup and clear being conducted, the certified supervisor shall able to be present at the work site in no more A.RENOVATION A certified renovator is required for each ren are posted, while the required work area comperformed. The certified renovator must reg available either onsite or by telephone at all t	ratement project and shall he ance of work areas. At all libe onsite or available by a than 2 hours. The action project and shall be tainment is being established all are being project are being project.	oe onsite du other times telephone, p oe physically ed, and whi erformed by conducted.	ring all wor when abate pager, or an y present while required y other indiv	k site preparation and ment activities are swering service, and the required signs work area cleaning is viduals and must be
XIII	ABATEMENT A certified supervisor is required for each ab during the post-abatement cleanup and clear being conducted, the certified supervisor shall able to be present at the work site in no more standard to be present at the work site in no more standard to be present at the work are in no more standard to be present at the work are ach renare posted, while the required work area comperformed. The certified renovator must regavailable either onsite or by telephone at all the certify that all of the above information is contact the certify that all of the above information is contact.	ratement project and shall leance of work areas. At all leance of work areas. At all leance of work areas. At all leance of works. The consideration project and shall be tainment is being establishing and shall be tainment is being establishing the consideration are being leance.	oe onsite du other times telephone, p oe physically ed, and whi erformed by conducted.	ring all wor when abate pager, or an y present while required y other indiv	k site preparation an ement activities are swering service, and the required signs work area cleaning is
XIII	ABATEMENT A certified supervisor is required for each ab during the post-abatement cleanup and clear being conducted, the certified supervisor shall able to be present at the work site in no more. RENOVATION A certified renovator is required for each renare posted, while the required work area comperformed. The certified renovator must regavailable either onsite or by telephone at all the certify that all of the above information is contact information for return mail or questions.	ratement project and shall be ance of work areas. At all ll be onsite or available by a than 2 hours. The available by the a	be onsite du other times telephone, p be physically ed, and whi erformed by conducted.	ring all wor when abate pager, or and y present while required y other indiv	k site preparation and ment activities are swering service, and the required signs work area cleaning is viduals and must be
XIII	ABATEMENT A certified supervisor is required for each ab during the post-abatement cleanup and clear being conducted, the certified supervisor shal able to be present at the work site in no more. CRENOVATION A certified renovator is required for each ren are posted, while the required work area comperformed. The certified renovator must reg available either onsite or by telephone at all to certify that all of the above information is contact information for return mail or quest Mailing Address: 1158 CR 77	ratement project and shall be ance of work areas. At all ll be onsite or available by a than 2 hours. The encyation project and shall be tainment is being established all lighter work being primes renovations are being orrect. Signature	be onsite du other times telephone, p oe physically ed, and whi erformed by conducted.	ring all wor when abate pager, or and y present while required y other indivi-	the site preparation and ement activities are swering service, and then the required signs work area cleaning is viduals and must be service.
XIII	ABATEMENT A certified supervisor is required for each ab during the post-abatement cleanup and clear being conducted, the certified supervisor shall able to be present at the work site in no more. RENOVATION A certified renovator is required for each renare posted, while the required work area comperformed. The certified renovator must regavailable either onsite or by telephone at all to the certify that all of the above information is contact information for return mail or quest Mailing Address: 1158 CR 77 City: New Albany	atement project and shall be ance of work areas. At all ll be onsite or available by than 2 hours. novation project and shall be tainment is being established ularly direct work being primes renovations are being orrect. Signature State:	be onsite du other times telephone, p be physically ed, and whi erformed by conducted.	ring all wor when abate pager, or and y present while required y other indivi-	the site preparation and the ment activities are swering service, and then the required signs work area cleaning is viduals and must be the order of
XIII	ABATEMENT A certified supervisor is required for each ab during the post-abatement cleanup and clear being conducted, the certified supervisor shall able to be present at the work site in no more. RENOVATION A certified renovator is required for each renare posted, while the required work area comperformed. The certified renovator must regavailable either onsite or by telephone at all to the certify that all of the above information is contact information for return mail or quest Mailing Address: 1158 CR 77 City: New Albany	ratement project and shall be ance of work areas. At all ll be onsite or available by a than 2 hours. The encyation project and shall be tainment is being established all lighter work being primes renovations are being orrect. Signature	be onsite du other times telephone, p be physically ed, and whi erformed by conducted.	ring all wor when abate pager, or and y present while required y other indivi-	the site preparation and the ment activities are swering service, and then the required signs work area cleaning is viduals and must be the order of

Lead Notifications

MAIL TO: Mississippi Department of Environmental Quality

P.O. Box 2261, Jackson, MS 39225