



MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 6/10/2025	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual) ^O				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation) ^R				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number)				
Bldg. Name: Cook Elementary School				
Address: 2217 Seveth St N				
City: Columbus	State: MS	Zip: 39705	County: Lowndes	
Site Location: restroom x-160 and x161		Tel: 662-241-7180		
Building Size: unknown	# of Floors:	Age in Years:		
Present Use: school	Prior Use: school			
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Columbus Municipal School District				
Address: 2630 McArthur Dr.				
City: Columbus	State: MS	Zip: 39705		
Contact: Dr Stanley Ellis		Tel: 662-241-7400		
ASBESTOS REMOVAL CONTRACTOR: Southeast Environmental Group, Inc.				
Address: P.O. Box 433/ 296B 2nd Ave				
City: York	State: AL	Zip: 36925		
Contact: Johnny Rodgers		Tel: 205-392-9308		
Certification Number: ABC-00001906		Expiration Date: 05/20/2026		
OTHER OPERATOR:				
Address:				
City:	State:	Zip:		
Contact:		Tel:		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): yes				
WAS ASBESTOS PRESENT? (Yes/No): yes		Inspection Date: 10/30/2023		
Inspector: Willie Nester	Certification Number: ABI-00002244	Expiration Date: 01/24/2025 1/09/2026		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: The 9x9 floor tile and mastic and the mastic under the 12x12 floor tile 5, 8 and 6 % chrysotile respectively. The material is classified as Category 1, non-friable ACM. Analysis by Polarized Light Microscopy (PLM).				
VII. QUANTITY OF RACM TO BE REMOVED:				
Pipes (LN FT):	Surface Area (SQ FT): 120 sq ft	Volume of Facility Components (CU FT):		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:		Category II:		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 06/18/2025		Complete: 07/18/2025		
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: n/a		Complete: n/a		

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED: Removal of materials containing ACM will be performed by trained and certified personnel. The ACM will be kept wet throughout the process. The work area will be protected and sealed by using the capsule concept to assure the least to no particles escape.		
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: the non-friable ACM will be removed by competent personnel that is trained and knowledgeable in the removal, handling, and disposal of ACM. All work will be done to comply with Federal, State, and local regulations. The work will be protected and sealed by using the capsule concept to assure the least to no particle escape. The concept of "keep it wet" will be used throughout the asbestos removal process.		
XIII. WASTE TRANSPORTER #1		
Name: Johnny Rodgers		
Address: 296B 2nd Ave		
City: York	State: AL	Zip: 36925
Contact Person: Bertha Rodgers		Tel: 205-392-9308
WASTE TRANSPORTER #2		
Name:		
Address:		
City:	State:	Zip:
Contact Person:		Tel:
XIV. WASTE DISPOSAL SITE		
Name: Kemper County Landfill		
Address: 21211 Hwy 16 East		
City: Dekalb	State: MS	Zip: 39328
Contact Person: Jimmy Thomas		Tel: 601-743-4310
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:		
Name:		Title:
Authority:		
Date of Order (MM/DD/YY):		Date Ordered to Begin (MM/DD/YY):
XVI. FOR EMERGENCY RENOVATIONS:		
Date and Hour of Emergency (MM/DD/YY):		
Description of the sudden unexpected event:		
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:		
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER: MDEQ will be immediately notified. The unexpected asbestos will be properly handled in the same way as the original.		
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.		
Bertha Rodgers Type or Print Name	 (Signature of Owner/Operator)	6/10/25 (Date)
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:		
Bertha Rodgers Type or Print Name	 (Signature of Owner/Operator)	6/10/25 (Date)