

STATE OF MISSISSIPPI DEMOLITION/RENOVATION NOTIFICATION FORM

Please type or print legibly.

Incomplete notices will not meet notification requirements.

I. TYPE OF NOTICE: (X) Original ( ) Revision ( ) Canceled ( ) Annual ( ) Info. Only

II. TYPE OF PROJECT: ( ) Renovation (X) Demolition ( ) Ordered Demolition ( ) Emergency Renovation

III. SITE INFORMATION: Name: Description: Residential Address: 1541 W Capitol Street City: Jackson County: Hinds State: MS Zip: 39203 Contact Person: Coretta Laird Telephone: 601-960-1054

IV. OWNER INFORMATION: Name: Calvary Baptist Church Inc Full Mailing Address: 1300 W Capitol Street Contact Person: Coretta Laird Telephone: 601-960-1054

V. ASBESTOS REMOVAL CONTRACTOR: Name: Bestway Certification No.: ABC 40292 Exp. Date: 11-14-17 Full Mailing Address: bestwayjackson@yahoo.com Contact Person: Mr. Aaron Lee Telephone: 601-383-3237

VI. CONTRACTOR (Other): Name: ACA Demolition & Project Group, LLC Full Mailing Address: 120 Hillcroft Place, Jackson, MS 39211 Contact Person: Elton Smith Telephone: 601-238-0627

VII. ASBESTOS REMOVAL PROJECT DATES (MM/DD/YY): Removal Project Start: 1/31/2017 Removal Project Stop: 1/31/2017

VIII. DEMOLITION/RENOVATION PROJECT DATES (MM/DD/YY): Project Start: 2/01/2017 Project Stop: 2/04/2017 Prep. Date: 2/01/2017

IX. BUILDING INFORMATION: Bldg. Size (SQ FT)- 2,400 Bldg. Size (LN FT) No. of Floors 1 Age in Years: 92 Present Use: Vacant Prior Use: Residential

X. ASBESTOS INSPECTION: Was site inspected to determine presence of asbestos? (X) yes ( ) no Inspection Date: 04/28/16 Asbestos Present? (X) yes ( ) no Inspector: Lewis Younger Cert. No.: ABI00001761 Exp. Date: 07/17/2016 Identify suspect materials sampled: Laboratory Analysis: TEM PLM X Other Name of Laboratory: EMSL Analytical Inc

XI. QUANTITY OF RACM TO BE REMOVED: Pipes (LN FT) Surface Area (SQ FT) Volume of Facility Components (CU FT) N/A

XII. QUANTITY OF NONFRIABLE ASBESTOS - NOT REMOVED X TO BE REMOVED: Category I: Category II: 20% chrysotile 15% crocidolite Front Porch Vent Pipe

XIII. WASTE TRANSPORTER: Name: Republic services Full Mailing Address: 1035 Old Brandon Rd, Flowood, MS 39232 Contact Person: Scott Telephone: 601-939-2221

RECEIVED JAN 19 2017 Dept. of Environmental Quality

STATE OF MISSISSIPPI DEMOLITION/RENOVATION FORM - CONTINUED

XIV. WASTE ASBESTOS DISPOSAL SITE: Name: Little Dixie Landfill (Republic services)
Physical Location: 1716 E. County Line Rd, Ridgeland, MS 39157
Full Mailing Address: " " " " " " "
Contact Person: Shane Henderson Telephone: 601-982-9488
\* All asbestos waste should go to a permitted sanitary landfill.

XV. DISPOSAL SITE FOR DEMOLITION DEBRIS (Other than asbestos):
Name: Little Dixie Landfill (Republic services)
Physical Location: 1716 E. County Line Rd, Ridgeland MS 39157
Full Mailing Address: " " " " " " "
Contact Person: Shane Telephone: 601-982-9488
\* All demolition debris (other than asbestos) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.

XVI. REMOVAL/DEMOLITION PROCEDURES TO BE USED (Check all that apply):
Strip & Removal [ ] Double Bagging [X] Mechanical Chipping [ ] Component Removal [X]
Wrecking Ball [ ] Gross Demolition [ ] Remove Intact [X] Bulldozer [ ]
[X] Containment [X] Glove Bag [ ] Explode [ ] Negative Air [ ]
[X] Wet Method [ ] Roofing Saw [ ] Other - Explain Below: [ ]

XVII. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK:
Track Hoe - Demo Structure
Skid Steer - " " " and clean-up
Structure debris will be loaded into 30yd containers
Roll-off Tote will haul it to Landfill

XVIII. PROCEDURES TO BE FOLLOWED IF UNEXPECTED ACM IS FOUND OR NONFRIABLE ACM BECOMES CRUMBLER, PULVERIZED, OR REDUCED TO A POWDER OR SMALL PIECES:

\* Will MDEQ be notified of any significant changes? (X) yes ( ) no

XIX. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, IDENTIFY THE AGENCY BELOW:
Name: Coretta Laird Title: Supervisor
Authority: Commander Jaye Coleman
Date of Order: Date Demolition to Begin: / /

XX. EMERGENCY DEMOLITION/RENOVATIONS: Date of Emergency: / / , Time:
Description of the sudden, unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or unreasonable financial burden:

XXI. When asbestos-containing material is present, an individual trained in the provisions of the regulation (40 CFR 61 Subpart M) will be on site during the demolition or renovation and evidence that the required training has been accomplished by this person will be available for inspection during normal business hours.

I certify that all of the above information is correct.

Elton Smith
Type or Print Name and Title

Elton Smith
Signature

1/12/2017
Date

MAIL TO: Office of Pollution Control Physical Address 515 Amite Street
P.O. Box 2261 Jackson, MS 39201
Jackson, MS 39225 (601) 961-5171