

STATE OF MISSISSIPPI DEMOLITION/RENOVATION NOTIFICATION FORM

Please type or print legibly

Incomplete notices will not meet notification requirements

I. TYPE OF NOTICE: () Original () Revision () Canceled
() Annual (x) Info. Only

II. TYPE OF PROJECT: (x) Renovation () Demolition
() Ordered Demolition () Emergency Renovation

III. SITE INFORMATION: Name: MS Delta Electric
Description: Electric Plant
Address: 1700 US-82, Greenwood, MS 38930
City: Greenwood County: Leflore State: MS Zip: 38930
Contact Person: Plant Manager Telephone: (662) 453-6352

IV. OWNER INFORMATION: Same as above

Full Mailing Address:

Contact Person:

Telephone:

V. ASBESTOS REMOVAL CONTRACTOR: Name: Anderson Environmental
Certification No.: C-00002173 Exp. Date: 10/17
Full Mailing Address: P.O. Box 16891
Contact Person: Daryl Anderson Telephone: 601-940-4644

VI. CONTRACTOR (Other): Dixie Roofing
Full Mailing Address: 1936 HWY 51 Winona MS 3967
Contact Person: Ricky Bingham Telephone: 662-283-4463

VII. ASBESTOS REMOVAL PROJECT DATES (MM/DD/YY):
Removal Project Start: 2-14-17 Removal Project Stop: 3-30-17

VIII. DEMOLITION/RENOVATION PROJECT DATES (MM/DD/YY):
Project Start: 1-14-17 Project Stop: 4-01-17 Prep. Date:

IX. BUILDING INFORMATION Bldg. Size(SQ FT): 10,000sf Bldg. Size(LN FT):
No. of Floors: 2 Age in Years: 40yrs
Present Use: Plant Prior Use: Plant

X. ASBESTOS INSPECTION: Roof Presumed Asbestos

Was site inspected to determine presence of asbestos? (x) yes () no
Inspection Date: Asbestos Present? (x) yes () no
Inspector: Cert. No.: Exp. Date:
Identify suspect materials sampled:
Laboratory Analysis: Other
Name of Laboratory:

XI. QUANTITY OF RACM TO BE REMOVED:

Pipes (LN FT): Surface Area (SQ FT)

Volume of Facility Components (CU FT):

XII. QUANTITY OF NONFRIABLE ASBESTOS- 10,000sf built-up roofing TO BE REMOVED

Category I: Category II:

Roof Removed Non-regulated

XIII. WASTE TRANSPORTER: Name: Anderson Environmental
Full Mailing Address: P.O. Box 16891 Jackson, MS 39236
Contact Person: Daryl Anderson Telephone: 601-940-4644

XIV. WASTE ASBESTOS DISPOSAL SITE: Name: Leflore Co landfill

Dept. of Environmental Quality

JAN 23 2017

RECEIVED

Physical Location: 15200 Hwy 49E Schlater, MS 38952

Full Mailing Address: Greenwood, MS

Contact Person: Kelly

*All asbestos waste should go to a permitted sanitary landfill.

XV. DISPOSAL SITE FOR DEMOLITION DEBRIS (Other than asbestos):

Physical Location: Same

Full Mailing Address:

Contact Person:

*All demolition debris (other than asbestos) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.

XVI. REMOVAL/DEMOLITION PROCEDURES TO BE USED (Check all that apply):

- | | | | |
|--|---|---|--|
| <input type="checkbox"/> Strip & Removal | <input type="checkbox"/> Double Bagging | <input type="checkbox"/> Mechanical Chipping | <input type="checkbox"/> Component Removal |
| <input type="checkbox"/> Wrecking Ball | <input type="checkbox"/> Gross Demolition | <input type="checkbox"/> Remove Intact | <input type="checkbox"/> Bulldozer |
| <input type="checkbox"/> Containment | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Explode | <input type="checkbox"/> Negative Air |
| <input checked="" type="checkbox"/> Wet Method | <input type="checkbox"/> Roofing Saw | <input type="checkbox"/> Other-Explain Below: | |

XVII. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK:

Roof removal and replacement to be done non-regulated

XVIII. PROCEDURES TO BE FOLLOWED IF UNEXPECTED ACM IS FOUND OR NONFRIABLE ACM BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO A POWDER OR SMALL PIECES:

Halt all work notify the proper authority.

*Will MDEQ be notified of any significant changes? (x)yes () no

XIX. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, IDENTIFY THE AGENCY BELOW:

Name: _____ Title: _____
 Authority: _____
 Date of Order _____ Date Demolition to Begin: _____

XX. EMERGENCY DEMOLITION/RENOVATIONS: Date of Emergency: Time:

Description of the sudden, unexpected event: _____

 Explanation of how the event caused unsafe conditions or would cause equipment damage or unreasonable financial burden: _____

XXI. When asbestos-containing material is present, an individual trained in the provisions of the regulation (40 CFR 61 Part M) will be on site during the demolition or renovation and evidence that the required training has been accomplished by this person will be available for inspection during normal business hours.

I certify that all of the above information is correct>

Daryl Anderson
Type or Print name and Title


Signature

1/20/2017
Date

MAIL TO: Office of Pollution Control
515 East Amite Street
Jackson, MS 39201
601-961-5171

OR P. O. Box 2261
Jackson, MS 39225-2261