

# MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos Section, 515 E. Amite Street, Jackson, MS 39201

Operator Project #		Postmark		Date Received (MDEQ use only)		Notification # (MDEQ use only)	
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual)				ORIGINAL			
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation)				DEMOLITION			
III. FACILITY DESCRIPTION (Include building name, number and floor or room number)							
Bldg. Name:							
Address 918 MAPLE STREET							
City: JACKSON			State: MS		Zip: 39203		
Site Location: SAME AS ABOVE					Tel: 601-960-1054		
Building Size 1,196			# of Floors: 1		Age in Years: 70		
Present Use: VACANT			Prior Use: RESIDENTIAL				
IV. FACILITY INFORMATION (Identify owner, removal contractor, and other operator)							
OWNER NAME: OLLIE & LEOLA LOYD							
Address: 1902 PLEASANT							
City: JACKSON			State: MS		Zip: 39203		
Contact: CITY OF JACKSON (CORETTA LAIRD)					Tel: 601-960-1054 OR 601-960-1056		
REMOVAL CONTRACTOR "Asbestos" Bestway Abatement Exp. 11-03-2017							
Address: P.O. Box 88							
City: Edward			State: MS		Zip: 39066		
Contact: Daren Lee					Tel: 601-383-3237		
OTHER OPERATOR: "Demolition" ACA Demolition & Protect Group, LLC							
Address: 120 Hilkraft Place							
City: Jackson			State: MS		Zip: 39211		
Contact: Alton Smith					601-238-0627		
V. IS ASBESTOS PRESENT? (Yes/No) YES, BEIGE & BLACK SHEETROCK IN LIVINGROOM WALL, FRONT ROOM FLOOR TILE							
VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL (Include inspector name and date of inspection): Leah Delahoussaye 8-10-2016							
EPA 600/R-93/116 METHOD USING POLARIZED LIGHT MICROSCOPY; INSPECTOR JOHNNELL SMITH; CERTIFICATION# AB00005134; CERTIFICATION EXPIRATION DATE: 9/11/2016; DATE OF INSPECTION: 7/20/2016							
VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING:				Nonfriable Asbestos Material Not To Be Removed		Indicate Unit of Measurement Below	
1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed				RACM To Be Removed 8% Chrysotile 4% Chrysotile 2 Chrysotile		Category I Category II UNIT 2200 sq ft	
Pipes				Sheetrock living room		Ln Ft: 800 Ln M:	
Surface Area				Living Room Floor		Sq Ft: 144 Sq M:	
Vol RACM Off Facility Component						Cu Ft: Cu M:	
VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start:				July 24, 2017		Complete: July 24, 2017	
IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start:				July 24, 2017		Complete: July 25, 2017	

RECEIVED

JUL 11 2017

Dept. of Environmental Quality

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Track Hoe, Skid Steer and Roll-Off Boxes

XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Bagging, wet method, Plastic cover and Bag

XII. WASTE TRANSPORTER #1

Republic Services

Name: Scott Johnson

Address: 1035 Old Brandon Rd

City: Hattiesburg

State: MS

Zip: 39232

Contact Person: Scott Johnson

Tel: 661-906-4606

WASTE TRANSPORTER #2

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIII. WASTE DISPOSAL SITE Little Dixie Landfill (Republic Services)

Name: Shane Ballard

Address: 1761 E County Line Rd

City: Ridgeland

State: MS

Zip: 39157

Tel: 661-982-9488

XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: CITY OF JACKSON (CORETTA LAIRD)

Title: SUPERVISOR

Authority: COMMANDER JAYE COLEMAN

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XV. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

XVII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Alton Smith

Type or Print Name

(Signature of Owner/Operator)

7/11/2017

(Date)

XVIII. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Alton Smith

Type or Print Name

(Signature of Owner/Operator)

7/11/2017

(Date)



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

http://www.EMSL.com / batonrougelab@emsl.com

EMSL Order: 251604918

Customer ID: COJA62

Customer PO:

Project ID:

Attention: Johnnell Smith  
City of Jackson  
PO Box 17  
Jackson, MS 39205-0017

Phone: (601) 960-1054  
Fax: (601) 960-1700  
Received Date: 08/09/2016 10:00 AM  
Analysis Date: 08/10/2016  
Collected Date: 07/20/2016

Project: 918 Maple Street Case # 2015-2275

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
M-1 251604918-0001	Ceiling Living Room - Sheetrock	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
M-2-Floor Tile 1 251604918-0002	Wall Living Room - Sheetrock	Brown/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
M-2-Mastic 1 251604918-0002A	Wall Living Room - Sheetrock	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
M-2-Floor Tile 2 251604918-0002B	Wall Living Room - Sheetrock	Beige Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
M-2-Mastic 2 251604918-0002C	Wall Living Room - Sheetrock	Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
M-3 251604918-0003	Roof - Shingle	Gray/Black Fibrous Heterogeneous	40% Cellulose	60% Non-fibrous (Other)	None Detected
M-4 251604918-0004	Wall Left Front Room - Sheetrock	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
M-5 251604918-0005	Floor Living Room - Tile	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
M-6-Floor Tile 251604918-0006	Floor Left Front Room - Tile	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
M-6-Mastic 251604918-0006A	Floor Left Front Room - Tile	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
M-7 251604918-0007	Roof - Felt	Black Fibrous Homogeneous	60% Cellulose	40% Non-fibrous (Other)	None Detected

Analyst(s)

Leah Delahoussaye (11)

*Brett Heitzmann*

Brett Heitzmann, Laboratory Manager  
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%.

Samples analyzed by EMSL Analytical, Inc. Baton Rouge, LA NVLAP Lab Code 200375-0, LELAP 01950, TX 300238

Initial report from: 08/10/2016 15:16:49