

# MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: **MDEQ Asbestos Section, 515 E. Amite Street, Jackson, MS 39201**

|   |                       |  |                                |
|---|-----------------------|--|--------------------------------|
| Operator Project #  | Postmark<br>7/21/2017 | Date Received (MDEQ use only)                  | Notification # (MDEQ use only) |
| I. Type of Notification (O=Original R=Revised C=Canceled A= Annual)      O  |                       |  |                                |
| II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation)      R   |                       |  |                                |
| III. FACILITY DESCRIPTION (Include building name, number and floor or room number)      Main Street United Methodist Church                                   |                       |  |                                |
| Bldg. Name: Main Street United Methodist Church   |                       |  |                                |
| Address 712 North Main Street   |                       |  |                                |
| City: Hattiesburg   | State: MS             | Zip: 39401                                     |                                |
| Site Location: Parlor Area- Hallways  |                       | Tel:   |                                |
| Building Size 10,000  | # of Floors: 2        | Age in Years: 75                               |                                |
| Present Use: Church   | Prior Use: Church     |  |                                |
| IV. FACILITY INFORMATION (Identify owner, removal contractor, and other operator)   |                       |  |                                |
| OWNER NAME: Main Street United Methodist Church   |                       |  |                                |
| Address: 712 North Main Street  |                       |  |                                |
| City: Hattiesburg   | State: MS             | Zip: 39401                                     |                                |
| Contact: Amy Smith  | Tel: 601-408-5018     |  |                                |
| REMOVAL CONTRACTOR Specialty Abatement Services, Inc.   |                       |  |                                |
| Address: PO Box 15925   |                       |  |                                |
| City: Hattiesburg   | State: MS             | Zip: 39404                                     |                                |
| Contact: William H. Stamps  | Tel: 601-264-5550     |  |                                |
| OTHER OPERATOR: To Be Determined  |                       |  |                                |
| Address:  |                       |  |                                |
| City:   | State:                | Zip:   |                                |
| Contact:  |                       |  |                                |
| V. IS ASBESTOS PRESENT? (Yes/No)      Yes - Floor tile and mastic   |                       |  |                                |
| VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL (Include inspector name and date of inspection): |                       |  |                                |
| Anthony Bryant - 7/27/2015 - PLM@ EHS - Flooring, mastic, terra cotta tile , plaster, ceiling tiles(fiber glass)  |                       |  |                                |
| VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING:  |                       | Nonfriable Asbestos Material Not To Be Removed |                                |
| 1. Regulated ACM to be Removed<br>2. Category I ACM Not Removed<br>3. Category II ACM Not Removed   |                       | Indicate Unit of Measurement Below             |                                |
| RACM To Be Removed  |                       | Category I                                     | Category II                    |
|   |                       | UNIT   |                                |
| Pipes   |                       |  |                                |
| Surface Area  | 1,100                 |  |                                |
| Vol RACM Off Facility Component   |                       |  |                                |
|   |                       | Ln Ft:   | Ln M:                          |
|   |                       | Sq Ft: X                                       | Sq M:                          |
|   |                       | Cu Ft:   | Cu M:                          |
| VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 8/7/2017   |                       | Complete: 8/18/2017                            |                                |
| IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 5/30/2017   |                       | Complete: 8/30/2017                            |                                |

RECEIVED  
JUL 24 2017  
Dept. of Environmental Quality

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Removal of ACM prior to further renovations

XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Containment will be established with poly critical barriers with negative air. All ACM will be wetted and manually removed. Waste will be placed in clear, labeled, poly bags and placed in properly lined container for disposal.

XII. WASTE TRANSPORTER #1

Name: Specialty Abatement Services, Inc.

Address: PO Box 15925

City: Hattiesburg

State: MS

Zip: 39404

Contact Person: William H. Stamps

Tel: 601-264-5550

WASTE TRANSPORTER #2

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIII. WASTE DISPOSAL SITE

Name: Pine Belt Regional Landfill

Address: Hwy 29 N.

City: Runnelstown

State: MS

Zip: 39465

Tel: 601-545-6676

XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XV. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

All work will stop. MDEQ will be notified.

XVII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Anthony Bryant

Type or Print Name

(Signature of Owner/Operator)

7/21/17

(Date)

XVIII. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Anthony Bryant

Type or Print Name

(Signature of Owner/Operator)

7/21/17

(Date)