

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: **MDEQ Asbestos Section, 515 E. Amite Street, Jackson, MS 39201**

Operator Project #	Postmark	Date Received (MDEQ use only)	Notification # (MDEQ use only)	
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual) O				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation) E				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number)				
Bldg. Name: Baxter Wilson Plant				
Address 770 Kemp Bottom Road				
City: Vicksburg	State: MS	Zip: 39180		
Site Location: Warren County		Tel: (601) 631-6206		
Building Size N/A	# of Floors: 8	Age in Years: 50		
Present Use: Electric Power Plant		Prior Use: Electric Power Plant		
IV. FACILITY INFORMATION (Identify owner, removal contractor, and other operator)				
OWNER NAME: Entergy Mississippi, Inc.				
Address: P.O. Box 1640				
City: Jackson	State: MS	Zip: 39215		
Contact: Timothy R. Stone		Tel: (601) 969-2316		
REMOVAL CONTRACTOR PAC				
Address: 1011 Hwy 139				
City: Monroe	State: LA	Zip: 71203		
Contact: Keith Holland		Tel: 318 345 0889		
OTHER OPERATOR:				
Address:				
City:	State:	Zip:		
Contact:				
V. IS ASBESTOS PRESENT? (Yes/No) Yes				
VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL (Include inspector name and date of inspection):				
Plant Previously Surveyed for Asbestos Material				
VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING:	RACM To Be Removed	Nonfriable Asbestos Material Not To Be Removed		Indicate Unit of Measurement Below
1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed		Category I	Category II	UNIT
Pipes				Ln Ft: Ln M:
Surface Area				Sq Ft: Sq M:
Vol RACM Off Facility Component	46			Cu Ft: X Cu M:
VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 8/28/2017		Complete: 8/29/2017		
IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 8/28/2017		Complete: 8/29/2017		

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

N/A

XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

The following procedures will be used while removing asbestos; wet method, double bagging and glove bagging.

XII. WASTE TRANSPORTER #1

Name: Republic Services

Address: 1035 Old Brandon Road

City: Flowood

State: MS

Zip: 39232

Contact Person: Mike Raley

Tel: (601) 613-8671

WASTE TRANSPORTER #2 N/A

Name: N/A

Address: N/A

City: N/A

State: N/A

Zip: N/A

Contact Person: N/A

Tel: N/A

XIII. WASTE DISPOSAL SITE

Name: BFI Little Dixie Landfill

Address: 1716 N. County Line Road

City: Jackson

State: MS

Zip: 39215

Tel: (601) 613-8671

XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: N/A

Title: N/A

Authority: N/A

Date of Order (MM/DD/YY): N/A

Date Ordered to Begin (MM/DD/YY): N/A

XV. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY): 8/23/2017 @ 11:47 am

Description of the sudden unexpected event: The unit is in a forced outage. Access is needed to replace cabling for power and control equipment.

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

Workers need to access the area adjacent to the asbestos in order to replace vital cable.

XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

N/A

XVII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Timothy R. Stone

Type or Print Name

(Signature of Owner/Operator)

8/28/2017

(Date)

XVIII. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Timothy R. Stone

Type or Print Name

(Signature of Owner/Operator)

8/28/2017

(Date)



Entergy Services, Inc.
P.O. Box 1640
Jackson, MS 39215-1640

August 28, 2017

Mr. Tommy Moody
Office of Pollution Control
P.O. Box 2261
Jackson, MS 39225

Re: Removal of Asbestos Containing Material
Baxter Wilson Plant, Vicksburg, MS

Dear Mr. Moody:

Pursuant to the conversation on August 23, 2017 at 2:30 pm with Martha Hester, the Baxter Wilson Plant was informed that they could begin the emergency asbestos removal activities. Enclosed is the emergency notification for removal of asbestos containing materials from the Baxter Wilson Plant. The unit is in a forced outage. The lagging and asbestos insulation must be removed from the air duct to safely enable replacement of cable. The insulation has been determined to be asbestos containing material. Access is needed in the area in order to replace cabling for power and control equipment vital to plant operation. Asbestos abatement is needed for safe access to the cables and associated equipment.

If you should have any questions or need additional information, please call me at 601-969-2316 or Martha Hester at 601-969-2423.

Respectfully Submitted,

A handwritten signature in black ink that reads "Timothy R. Stone".

Timothy R. Stone
Environmental Support Manager, MS/TX
Entergy Service, Inc.

RECEIVED

AUG 28 2017

Dept. of Environmental Quality