MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: **MDEQ Asbestos Section, 515 E. Amite Street, Jackson, MS 39201**

Operator Project #	Postmark	Date Received (MDEQ use only)	Notification # (MDEQ use only)

I. Type of Notification (O=Original R=Revised C=Canceled A= Annual) Revised

II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation)

III. FACILITY DESCRIPTION (Include building name, number and floor or room number) Housing Units (9)

Bldg. Name: Magnolia Pointe - Northside Renovations

Address (Plc28e See attached address break-down

City: Lumberton	State: MS	Zip: 39455
Site Location: #s: 802, 04, 06, 08, 09, 10, 11, 13 + 16 / See attached		Tel: (601) 408-6161
Building Size 54000 sq ft. (12,000 sq ft. Total)	# of Floors: 1	Age in Years: 30 yrs approx.
Present Use: Residential Housing	Prior Use: Same	

IV. FACILITY INFORMATION (Identify owner, removal contractor, and other operator)

OWNER NAME: MRHA VIII		
Address: 10430 Three Rivers Rd.		
City: Gulfport	State: MS	Zip: 39505
Contact: Mr. Jim Butler		Tel:
REMOVAL CONTRACTOR Southeast Environmental Group, Inc.		
Address: P O Box 433		
City: York	State: AL	Zip: 36925
Contact: Johnny Rodgers		Tel: (205) 392-9308 / 205 499-6739
OTHER OPERATOR:		
Address:		
City: N/A	State:	Zip:
Contact:		

V. IS ASBESTOS PRESENT? (Yes/No) Yes

VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL (Include inspector name and date of inspection): floor tile + mastic to be removed.

VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING: 1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed	RACM To Be Removed	Nonfriable Asbestos Material Not To Be Removed		Indicate Unit of Measurement Below	
		Category I	Category II	UNIT	
Pipes				LnFt:	Ln M:
Surface Area	54000 sq ft.			SqFt:	Sq M:
Vol RACM Off Facility Component	80			CuFt:	Cu M:

VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 9-6-17 Complete: 9-8-17

IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: Complete: 9-8-17

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:
Tile & mastic to be taken up as much in-tact as possible after being wetted down thoroughly.

XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:
Areas to be remoded will be throughly wetted, then soaked continously with a fine waterflow detergent solution until all abatement is complete.

XII. WASTE TRANSPORTER #1 Southeast Environmental Group, Inc.

Name:

Address: PO Box 433

City: York, AL | State: AL | Zip: 36925

Contact Person: Bertha Rodgers | Tel: (205) 392-9308

WASTE TRANSPORTER #2

Name: Waste Pro USA

Address: 480 JM Tatum Industrial Drive

City: Hattiesburg | State: MS | Zip: 39401

Contact Person: Trey Cuevas | Tel: (601) 434-3045

XIII. WASTE DISPOSAL SITE 480 JM Tatum Dr. / Hattie

Name:

Address:

City: | State: | Zip:

Tel:

XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: | Title:

Authority: N/A

Date of Order (MM/DD/YY): | Date Ordered to Begin (MM/DD/YY):

XV. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY): N/A

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:
MDEQ will be notified immediately (as will housing authority) and will await further instructions

XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

XVII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Bertha Rodgers (Type or Print Name) Bertha Rodgers (Signature of Owner/Operator) 9-5-17 (Date)

XVIII. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Bertha Rodgers (Type or Print Name) Bertha Rodgers (Signature of Owner/Operator) 9-5-17 (Date)

Southeast Environmental Group, Inc.
P O Box 433
York, AL 36925
(205) 392-9308 Ph / (205) 392-9309
E-Mail: bertha_floors@yahoo.com

MDEQ
Office of Pollution Control
P O Box 2261
Jackson, MS 39255
(601) 961-5171
Email: tmoody@mdeq.ms.gov

August 14, 2017

Addresses Where Abatement Will Be Performed
Magnolia Pointe – Northside Renovations
Lumberton, MS 39455

- 802 West 10th – 600 Sq. Ft.
- 804 West 10th – 600 Sq. Ft.
- 806 West 10th – 600 Sq. Ft.
- 808 West 10th – 600 Sq. Ft.
- 809 West Hinton – 600 Sq. Ft.
- 910 West 10th – 600 Sq. Ft.
- 811 West Hinton – 600 Sq. Ft.
- 813 West Hinton – 600 Sq. Ft.
- 816 West 10th – 600 Sq. Ft.

(Nine Units Initially)

All addresses in Lumberton, MS