



MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: **MDEQ Asbestos Section, 515 E. Amite Street, Jackson, MS 39201**

RECEIVED
OCT 25 2017
Dept. of Environmental Quality

Operator Project #	Postmark 10/23/17	Date Received (MDEQ use only)	Notification # (MDEQ use only)						
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual) O									
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation) D									
III. FACILITY DESCRIPTION (Include building name, number and floor or room number) Gardiner Center									
Bldg. Name: Dick & Tom's Service Station & R&R Drive Thru									
Address 137 & 141 Leontyne Price Blvd.									
City: Laurel	State: MS	Zip: 39440							
Site Location:			Tel:						
Building Size 3,000 SF total	# of Floors: 1	Age in Years: 75 / 30							
Present Use: Vacant	Prior Use: Service Station / Restaurant								
IV. FACILITY INFORMATION (Identify owner, removal contractor, and other operator)									
OWNER NAME: Kamin Realty									
Address: PO Box 10234									
City: Pittsburgh	State: PA	Zip: 15232							
Contact: Chuck Reali	Tel: 412-661-5237								
REMOVAL CONTRACTOR Specialty Abatement Services, Inc.									
Address: PO Box 15925									
City: Hattiesburg	State: MS	Zip: 39404							
Contact: William H. Stamps	Tel: 601-264-5550								
OTHER OPERATOR: Owner									
Address:									
City:	State:	Zip:							
Contact:									
V. IS ASBESTOS PRESENT? (Yes/No) Yes - Roof Flashing & Pent on Service Station only									
VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL (Include inspector name and date of inspection):									
Anthony Bryant 6/30/17 - PLM - , Floor Coating, plaster , ceiling tiles, caulk , window putty, mastics, Roofing									
VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING:		Nonfriable Asbestos Material Not To Be Removed		Indicate Unit of Measurement Below					
<ol style="list-style-type: none"> 1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed 		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; text-align: center;">RACM To Be Removed</td> <td style="width: 50%;"></td> </tr> <tr> <td style="text-align: center;">Category I</td> <td style="text-align: center;">Category II</td> </tr> </table>		RACM To Be Removed		Category I	Category II	UNIT	
				RACM To Be Removed					
Category I	Category II								
Pipes		Ln Ft:	Ln M:						
Surface Area		260 SF	Sq Ft: X	Sq M:					
Vol RACM Off Facility Component			Cu Ft:	Cu M:					
VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 11/6/2017				Complete: 11/30/2017					
IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 11/6/2017				Complete: 12/30/2017					

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:		
Removal of ACM Roof Flashing and penetrations <i>Prior to Demo by owner</i>		
XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:		
. All ACM will Wetted and manually removed . Waste will be placed in clear , labeled , poly bags and a placed in properly lines container for disposal.		
XII. WASTE TRANSPORTER #1		
Name: Specialty Abatement Services , Inc.		
Address: PO Box 15925		
City: Hattiesburg	State: MS	Zip: 39404
Contact Person: William H. Stamps	Tel: 601-264-5550	
WASTE TRANSPORTER #2		
Name:		
Address:		
City:	State:	Zip:
Contact Person:	Tel:	
XIII. WASTE DISPOSAL SITE		
Name: Pine Belt Regional Landfill		
Address: Hwy 29 N.		
City: Runnelstown	State: MS	Zip: 39465
Tel: 601-545-6676		
XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:		
Name:	Title:	
Authority:		
Date of Order (MM/DD/YY):	Date Ordered to Begin (MM/DD/YY):	
XV. FOR EMERGENCY RENOVATIONS:		
Date and Hour of Emergency (MM/DD/YY):		
Description of the sudden unexpected event:		
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:		
XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:		
All work will stop. MDEQ will be notified.		
XVII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.		
Anthony Bryant		10/23/17
Type or Print Name	(Signature of Owner/Operator)	(Date)
XVIII. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:		
Anthony Bryant		10/23/17
Type or Print Name	(Signature of Owner/Operator)	(Date)