

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: **MDEQ Asbestos Section, 515 E. Amite Street, Jackson, MS 39201**

Operator Project #	Postmark	Date Received (MDEQ use only)	Notification # (MDEQ use only)	
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual) Original Revised				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation) Demolition				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number)				
Bldg. Name:				
Address 988 Flag Chapel Road				
City: Jackson	State: MS	Zip: 39209	RECEIVED NOV - 3 2017	
Site Location: Same as above		Tel: 601-960-1054	MDEQ OPC	
Building Size 3,900	# of Floors: 1	Age in Years: 34		
Present Use: Vacant	Prior Use: Commercial			
IV. FACILITY INFORMATION (Identify owner, removal contractor, and other operator)				
OWNER NAME: Kirat Group LLC				
Address: 100 Green Oak Drive				
City: Clinton	State: MS	Zip: 39056		
Contact: City of Jackson (Coretta Laird)		Tel: 601-960-1054 or 601-960-1056		
REMOVAL CONTRACTOR: "Abestos" Bestway Abatement Exp 11-03-2017				
Address: P.O. Box 88				
City: Edward	State: MS	Zip: 39066		
Contact: Caron Lee		Tel: 601-383-3237		
OTHER OPERATOR: "Demolition" AsA Demolition, Project Group, LLC				
Address: 120 Hillcrest Place				
City: Jackson	State: MS	Zip: 39211		
Contact: Alton Smith 601-338-0627				
V. IS ASBESTOS PRESENT? (Yes/No) Yes, White Floor Tile				
VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL (Include inspector name and date of inspection): Beverly Lorenzana 4/25/2017				
<small>EPA 600/R-93/116 Method using polarized light microscopy; Inspector: Wayne Spires; Certification# ABI00007367; Certification Expiration Date: 1/25/2018; Date of Inspection: 4/13/2017</small>				
VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING:				
1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed	RACM To Be Removed	Nonfriable Asbestos Material Not To Be Removed		Indicate Unit of Measurement Below UNIT
		Category I	Category II	
Pipes				Ln Ft: Ln M:
Surface Area Floor White Tile	2 1/2 Chrysotile			Sq Ft: 40 Sq M:
Vol RACM Off Facility Component				Cu Ft: Cu M:
VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: NOV. 8, 2017 Complete: NOV. 8, 2017				
IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: NOV. 8, 2017 Complete: NOV. 10, 2017				

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Tractor Hoe, Skid Steer and Roll-off Boxes

XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Bagging wet method, plastic cover and bag

XII. WASTE TRANSPORTER #1

Name: Republic Services

Address: 1035 Old Brandon Rd

City: Flowood

State: MS

Zip: 39237

Contact Person: Scott Johnson

Tel: 601-906-4606

WASTE TRANSPORTER #2

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIII. WASTE DISPOSAL SITE Little Dixie Landfill

Name: Shane Ballard

Address: 1716 E County Line Rd

City: Ridgeland

State: MS

Zip: 39157

Tel: 601-982-9488

XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: City of Jackson (Coretta Laird)

Title: Supervisor

Authority: Commander Jaye Coleman

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XV. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLER, PULVERIZED, OR REDUCED TO POWDER:

XVII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Alton Smith
Type or Print Name

[Signature]
(Signature of Owner/Operator)

10/27/2017
(Date)

XVIII. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Alton Smith
Type or Print Name

[Signature]
(Signature of Owner/Operator)

10/27/2017
(Date)



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809
Tel/Fax: (225) 755-1920 / (225) 755-1989
http://www.EMSL.com / batonrougelab@emsl.com

EMSL Order: 251702287
Customer ID: COJA62
Customer PO:
Project ID:

Attention: Wayne Spires
City of Jackson
PO Box 17
Jackson, MS 39205-0017
Phone: (601) 960-1054
Fax: (601) 960-1700
Received Date: 04/21/2017 9:50 AM
Analysis Date: 04/25/2017
Collected Date: 04/13/2017
Project: 988 Flag Chapel Road Case #2015-3349

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
FC-1 251702287-0001	Roof - Shingle	Black Fibrous Homogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
FC-2 251702287-0002	Roof - Felt	Black Fibrous Homogeneous	75% Cellulose	25% Non-fibrous (Other)	None Detected
FC-3 251702287-0003	Ceiling - Sheetrock	White Fibrous Homogeneous	3% Cellulose	97% Gypsum	None Detected
FC-4 251702287-0004	Ceiling - Insulation	Yellow Fibrous Homogeneous	95% Min. Wool	5% Non-fibrous (Other)	None Detected
FC-5-Floor Tile 251702287-0005	Floor Red - Tile	Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
FC-5-Mastic 251702287-0005A	Floor Red - Tile	Black Non-Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (Other)	None Detected
FC-6-Floor Tile 251702287-0006	Floor White - Tile	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
FC-6-Mastic 251702287-0006A	Floor White - Tile	Black Non-Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (Other)	None Detected
FC-7 251702287-0007	Roof Red - Shingle	Red Fibrous Homogeneous	10% Glass	90% Non-fibrous (Other)	None Detected

Analyst(s)

Beverly Lorenzana (9)

Brett Heitzmann, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-liable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%.

Samples analyzed by EMSL Analytical, Inc. Dallas, TX NVLAP Lab Code 600111-0, TX 300456

Initial report from: 04/25/2017 17:08:19