

73601

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos Section, 515 E. Amite Street, Jackson, MS 39201

Operator Project #		Postmark		Date Received (MDEQ use only)		Notification # (MDEQ use only)	
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual)						R	
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation)						D	
III. FACILITY DESCRIPTION (Include building name, number and floor or room number)							
Bldg. Name:				Pearl - Richland Connector Road Project			
Address				1004, 1010, 1012, 1028,1029,1030,1115 South Pearson Road			
City:		Pearl		State:		MS	
Zip:		39208		Age in Years:		25+	
Site Location: 1004, 1010, 1012, 1028,1029,1030,1115 South Pearson Road				Tel:			
Building Size		various		# of Floors:		1 & 2	
Present Use:		Residential		Prior Use:		Residential	
IV. FACILITY INFORMATION (Identify owner, removal contractor, and other operator)							
OWNER NAME:				City of Pearl			
Address:				2420 Old Brandon Road			
City:		Pearl		State:		MS	
Zip:		39208		Tel:		601-932-2262	
Contact:				Donnie Sullivan			
REMOVAL CONTRACTOR				M and M Services, Inc.			
Address:				Post Office Box 68431			
City:		Jackson		State:		MS	
Zip:		39286		Tel:		601-982-8695	
Contact:				Dale McGuffie			
OTHER OPERATOR:				N/A			
Address:				N/A			
City:		N/A		State:		N/A	
Zip:		N/A		Tel:		N/A	
Contact:				N/A			
V. IS ASBESTOS PRESENT? (Yes/No)				Yes			
VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL (Include inspector name and date of inspection):							
Bulk material collection and analysis via EPA 600/R-93/116 utilizing Polarized Light Microscopy, Inspected by Willie J Nester on June 23, 2017.							
VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING:			Nonfriable Asbestos Material Not To Be Removed		Indicate Unit of Measurement Below		
1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed Exterior Siding			RACM To Be Removed		UNIT		
Pipes			Joint Compound & tape		see attached		
Surface Area			Ceiling Texture		see attached		
Vol RACM Off Facility Component							
VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start:				4/30/2018		Complete: 7/31/2018	
IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start:						Complete:	

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Remove asbestos containing building materials.

XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Each work area will be contained in plastic and put under negative pressure to prevent exposure outside the work area. Exterior materials will be removed using wet methods. Workers will don proper protective clothing and respiratory

XII. WASTE TRANSPORTER #1

M and M Services, Inc.

Name: M and M Services, Inc.

Address: Post Office Box 68431

City: Jackson

State: MS

Zip: 39286

Contact Person: Dale McGuffie

Tel: 601-982-8695

WASTE TRANSPORTER #2

N/A

Name: N/A

Address: N/A

City: N/A

State: N/A

Zip: N/A

Contact Person: N/A

Tel: N/A

XIII. WASTE DISPOSAL SITE

Name: Little Dixie Landfill

Address: 1761 County Line Road

City: Ridgeland

State: MS

Zip: 39157

Tel: 601-982-9488

XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: N/A

Title: N/A

Authority: N/A

Date of Order (MM/DD/YY): N/A

Date Ordered to Begin (MM/DD/YY): N/A

XV. FOR EMERGENCY RENOVATIONS:

N/A

Date and Hour of Emergency (MM/DD/YY):

N/A

Description of the sudden unexpected event:

N/A

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

N/A

XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

cease operations and notify MDEQ.

XVII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Dale McGuffie, President

Type or Print Name

(Signature of Owner/Operator)

4/18/2018

(Date)

XVIII. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Dale McGuffie, President

Type or Print Name

(Signature of Owner/Operator)

4/18/2018

(Date)

MDEQ Notification of Asbestos Removal
Pearl, Mississippi

Address		Gray roof cement	Joint compound/tape	textured ceiling	exterior siding	window glaze	floor tile/mastic	Kitech linoleum
1126	Weems Street	100						
101	Industrial Park Road		3200	1400	850			
1115	South Pearson Road		2500	1500	2500			
1004	South Pearson Road				1600			
1029	South Pearson Road		1500		2500	40	800	
1010	South Pearson Road				1200			
1012	South Pearson Road				1200			
1028	South Pearson Road				1200			
1030	South Pearson Road				1200		50	225