

**STATE OF MISSISSIPPI DEMOLITION/RENOVATION NOTIFICATION FORM**

*Please type or print legibly.*

**Incomplete notices will not meet notification requirements.**

**RECEIVED**  
**MAY 10 2018**  
Dept. of Environmental Quality

**I. TYPE OF NOTICE:**       Original       Revision       Canceled  
     Annual       Info. Only

**II. TYPE OF PROJECT:**       Renovation       Demolition  
     Ordered Demolition      ( ) Emergency Renovation

**III. SITE INFORMATION:**    Name N/A  
 Description: One Story Wood Frame  
 Address: 1302 8th Avenue North  
 City: Columbus      County: Lowndes      State: Mississippi      ZIP: 39701  
 Contact Person: Mike Chandler      Telephone: 1-662-329-5121 extension 4109

**IV. OWNER INFORMATION:**    Name: Osie Davenport  
 Full Mailing Address: 101 South Stauffer Dr. Naperville, IL 60540-4133  
 Contact Person: Tomarris Jones      Telephone: 1-662-245-5070

**V. ASBESTOS REMOVAL CONTRACTOR:**    Name: Edward Clay  
 Certification No.: ABC-00005192      Expiration Date: 1/18/2019  
 Full Mailing Address: EAC Environmental 4546 Caledonia-Steens Rd. Caledonia, MS 39740  
 Contact Person: Edward Clay      Telephone: 1-662-386-6386

**VI. CONTRACTOR (Other): Name:** Columbus Fire and Rescue  
 Full Mailing Address: 205 7th Street South Columbus, Mississippi 39701  
 Contact Person: Mike Chandler      Telephone: 1-662-329-5121 extension 4109

**VII. ASBESTOS REMOVAL PROJECT DATES (MM/DD/YY):**  
 Removal Project Start: 04 / 01 / 2018      Removal Project Stop: 04 / 15 / 2018

**VIII. DEMOLITION/RENOVATION PROJECT DATES (MM/DD/YY):**  
 Project Start: 05 / 31 / 2018      Project Stop: 05 / 31 / 2018      Prep. Date: 05 / 01 / 2018

**IX. BUILDING INFORMATION:**      Bldg. Size (SQ FT): 1514      Bldg. Size (LNFT): 44 X 34.5  
    No. of Floors: one      Age in Years: 98 years  
 Present Use: abandoned      Prior Use: residential

**X. ASBESTOS INSPECTION:**  
 Was site inspected to determine presence of asbestos:  Yes       No  
 Inspection Date: 11 / 29 / 2017      Asbestos Present?  Yes       No  
 Inspector: Edward Clay      Cert. No.: ABI-00006706      Expiration Date: 7/20/2018  
 Identify suspect materials sampled: transite, tan linoleum, green linoleum flooring  
 Laboratory Analysis:    TEM \_\_\_\_\_      PLM X      Other \_\_\_\_\_  
 Name of Laboratory: CA Labs

**XI. QUANTITY OF RACM TO BE REMOVED:**  
 Pipes (LN FT) N/A      Surface Area (SQ FT) \_\_\_\_\_  
 Volume of Facility Components(CU FT) 30 square yards

**XII. QUANTITY OF NONFRIABLE ASBESTOS**       NOT REMOVED       TO BE REMOVED:  
 Category I: CAT I NF      Category II: CAT II NF

**XIII. WASTE TRANSPORTER:**    Name: EAC Environmental  
 Full Mailing Address: 4546 Caledonia-Steens Rd. Caledonia, MS 39740  
 Contact Person: Edward Clay      Telephone: 1-662-386-6386

STATE OF MISSISSIPPI DEMOLITION/RENOVATION FORM - CONTINUED

**XIV. WASTE ASBESTOS DISPOSAL SITE:** Name: RO BO Landfill  
Physical Location: 6447 Wahalak Road Scooba, MS 39358  
Full Mailing Address: - SAME -  
Contact Person: Roland Edmonds, Manager Telephone: 1-662-793-4795 office 1-662-361-0300 cell  
\*All asbestos waste should go to a permitted sanitary landfill.

**XV. DISPOSAL SITE FOR DEMOLITION DEBRIS (Other than asbestos):**  
Name: Columbus / Lowndes Landfill  
Physical Location: Armstrong Road  
Full Mailing Address: PO Box 221 Columbus, MS. 39703  
Contact Person: N/A Telephone: N/A  
\*All demolition debris (other than asbestos) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.

**XVI. REMOVAL/RENOVATION PROCEDURES TO BE USED (Check all that apply):**  
 Strip & Removal     Double Bagging     Mechanical Chipping     Component Removal  
 Wrecking Ball     Gross Demolition     Remove Intact     Bulldozer  
 Containment     Glove Bag     Explode     Negative Air  
 Wet Method     Roofing Saw     Other - Explain Below:

**XVII. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK:**  
- Demolition by Fire During Live Burn Training -

**XVIII. PROCEDURES TO BE FOLLOWED IF UNEXPECTED ACM IS FOUND OR NONFRIABLE ACM BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO A POWDER OR SMALL PIECES:**  
- Notify Building Inspection Department -

\*Will MDEQ be notified of any significant changes?  Yes  No

**XIX. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, IDENTIFY THE AGENCY BELOW:**  
Name: N/A Title: \_\_\_\_\_  
Authority: \_\_\_\_\_  
Date of Order: \_\_\_\_\_ Date Demolition to Begin: \_\_\_\_/\_\_\_\_/\_\_\_\_

**XX. EMERGENCY DEMOLITION/RENOVATIONS:** Date of Emergency: \_\_\_\_/\_\_\_\_/\_\_\_\_, Time: \_\_\_\_\_  
Description of the sudden, unexpected event:  
N/A

Explanation of how the event caused unsafe conditions or would cause equipment damage or unreasonable financial burden:  
N/A

**XXI. When asbestos-containing material is present, an individual trained in the provisions of the regulation (40 CFR 61 Subpart M) will be on site during the demolition or renovation and evidence that the required training has been accomplished by this person will be available for inspection during normal business hours.**

I certify that all of the above information is correct.

Mike Chandler Chief of Training  
Type or Print Name & Title

Mike Chandler  
Signature

5/17/18  
Date

MAIL TO: **Office of Pollution Control** Physical Address **515 Amite Street**  
**P.O. Box 2261**  
**Jackson, MS 39225** **Jackson, MS 39201**  
**(601) 961-5171**