

# MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

**Mail notification to: MDEQ Asbestos Section, 515 E. Amite Street, Jackson, MS 39201**

Operator Project # <b>1</b>	Postmark <b>30 Nov 2020</b>	Date Received (MDEQ use only)	Notification # (MDEQ use only)		
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual) <input type="radio"/>					
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation) <b>D</b>					
III. FACILITY DESCRIPTION (Include building name, number and floor or room number) <b>1804 N Mill St</b>					
Bldg. Name: <b>1804 N Mill St</b>					
Address <b>1804 N Mill St</b>					
City: <b>Jackson</b>	State: <b>MS</b>	Zip: <b>39202</b>			
Site Location: <b>1804 N Mill St</b>		Tel: <b>601-613-6992</b>			
Building Size <b>5,000 Sq Ft</b>	# of Floors: <b>1</b>	Age in Years: <b>73</b>			
Present Use: <b>Vacant</b>	Prior Use: <b>Warehouse</b>				
IV. FACILITY INFORMATION (Identify owner, removal contractor, and other operator)					
OWNER NAME: <b>USS Hyde LLC</b>					
Address: <b>1619 N West St</b>					
City: <b>Jackson</b>	State: <b>MS</b>	Zip: <b>39202</b>			
Contact: <b>Rucker Culpepper</b>		Tel: <b>601-613-6992</b>			
REMOVAL CONTRACTOR <b>Millsaps Ave LLC (ABC-00010565)</b>					
Address: <b>802 Hunter Bay</b>					
City: <b>Brandon</b>	State: <b>MS</b>	Zip: <b>39047</b>			
Contact: <b>Rucker Culpepper</b>		Tel: <b>601-613-6992</b>			
OTHER OPERATOR: <b>N/A</b>					
Address:					
City:	State:	Zip:			
Contact:					
V. IS ASBESTOS PRESENT? (Yes/No) <b>Yes. 16 materials tested. Asbestos detected in floor tile, flashing tar, window putty.</b>					
VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL (Include inspector name and date of inspection): <b>Field survey bulk sampling by Paul Anderson Environmental (ABI-00001686). Polarized light microscopy lab analysis by Environmental Hazards Services, LLC. Inspection report dated 10/27/2020. Test samples included wall plaster, drywall, floor tiles (and mastic), ceilings, window putty, brick mortar, exterior coating, roof cores, and roof flashings (at the parapet walls, penetrations, and on wood).</b>					
VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING:					
	RACM To Be Removed	Nonfriable Asbestos Material Not To Be Removed		Indicate Unit of Measurement Below	
		Category I	Category II	UNIT	
1. Regulated ACM to be Removed					
2. Category I ACM Not Removed					
3. Category II ACM Not Removed					
Pipes	0	0	0	Ln Ft: 0	Ln M: 0
Surface Area	Floor Tile	0	0	Sq Ft: 870	Sq M: 80.8
Vol RACM Off Facility Component	Flashing Tar; Window Putty	0	0	Cu Ft: 4	Cu M: 0.11
VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: <b>12/14/20</b> Complete: <b>12/21/20</b>					
IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: <b>12/22/20</b> Complete: <b>01/05/21</b>					

RECEIVED

NOV 30 REC'D

Dept. of Environmental Quality

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

ACM will be removed prior to demolition to avoid any disturbance of asbestos during demolition.

XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Asbestos abatement professionals only will wet ACM with amended water while using negative pressure enclosures, HEPA respirators, gloves, goggles, and Tyvek coveralls and then will promptly double-bag all waste in leak-tight containers using manual tools and a HEPA vacuum. Enclosed waste bags will be transported to a certified asbestos landfill. Air will be tested before during and after asbestos disturbance to ensure compliance with EPA and OSHA.

XII. WASTE TRANSPORTER #1

Name: Rucker Culpepper

Address: 802 Hunter Bay

City: Brandon

State: MS

Zip: 39047

Contact Person: Rucker Culpepper

Tel: 601-613-6992

WASTE TRANSPORTER #2

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIII. WASTE DISPOSAL SITE Republic Services Little Dixie Landfill (BFI Waste Sys of MS, LLC)

Name: Howard Peterson (Landfill Manager)

Address: 1716 County Line Rd

City: Ridgeland

State: MS

Zip: 39157

Tel: 601-982-9488

XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: n/a

Title: n/a

Authority: n/a

Date of Order (MM/DD/YY): n/a

Date Ordered to Begin (MM/DD/YY): n/a

XV. FOR EMERGENCY RENOVATIONS: n/a

Date and Hour of Emergency (MM/DD/YY): n/a

Description of the sudden unexpected event: n/a

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

n/a

XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:  
MDEQ will be notified and consulted prior to removing the discovered ACM in accordance with EPA and OSHA regulations.

XVII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Rucker Culpepper

Type or Print Name

(Signature of Owner/Operator)

11/30/20

(Date)

XVIII. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Rucker Culpepper

Type or Print Name

(Signature of Owner/Operator)

11/30/20

(Date)