

uDef11

AI#9342

STATE OF MISSISSIPPI DEMOLITION/RENOVATION NOTIFICATION FORM

Please type or print legibly.

Incomplete notices will not meet notification requirements.

I. TYPE OF NOTICE:  Original  Revision  Canceled  
 Annual  Info. Only

II. TYPE OF PROJECT:  Renovation  Demolition  
 Ordered Demolition  Emergency Renovation

III. SITE INFORMATION: Name Leaf River Cellulose LLC  
Description: \_\_\_\_\_  
Address: 157 Buck Creek Road  
City: New Augusta County: Perry State: MS ZIP: 39462  
Contact Person: Chris Carroll Telephone: 157 Buck Creek Road, New Augusta, MS 39462

IV. OWNER INFORMATION: Name: Leaf River Cellulose, LLC  
Full Mailing Address: 157 Buck Creek Road, New Augusta, MS 39462  
Contact Person: Chris Carroll Telephone: 601-964-7146

V. ASBESTOS REMOVAL CONTRACTOR: Name: Enviromental Service LLC  
Certification No.: ABC-00001330 Expiration Date: 2-13-23  
Full Mailing Address: 253 Delk Road  
Contact Person: Joe Venus Telephone: 601-408-1005

VI. CONTRACTOR (Other): Name: R&R Sheetmental Inc.  
Full Mailing Address: 25 Sunflower Road Foxworth MS  
Contact Person: Eli Rowell Telephone: 601-467-2831

VII. ASBESTOS REMOVAL PROJECT DATES (MM/DD/YY):  
Removal Project Start: 02 / 28 / 2022 Removal Project Stop: 03 / 03 / 2022

VIII. DEMOLITION/RENOVATION PROJECT DATES (MM/DD/YY):  
Project Start: \_\_\_/\_\_\_/\_\_\_ Project Stop: \_\_\_/\_\_\_/\_\_\_ Prep. Date: \_\_\_/\_\_\_/\_\_\_

IX. BUILDING INFORMATION: Bldg. Size (SQ FT): 210 Bldg. Size (LNFT): \_\_\_\_\_  
No. of Floors: 1 Age in Years: 40  
Present Use: Power Boiler Ash Pit Prior Use: Power Boiler ash pit

X. ASBESTOS INSPECTION:  
Was site inspected to determine presence of asbestos:  Yes  No  
Inspection Date: 2 / 1 / 22 Asbestos Present?  Yes  No  
Inspector: Stuart Horton Cert. No.: \_\_\_\_\_ Expiration Date: \_\_\_\_\_  
Identify suspect materials sampled: Top layer of roof  
Laboratory Analysis: TEM PLM X Other \_\_\_\_\_  
Name of Laboratory: EMSL Analytical, Inc

XI. QUANTITY OF RACM TO BE REMOVED:  
Pipes (LN FT) \_\_\_\_\_ Surface Area (SQ FT) Approximately 75sqft  
Volume of Facility Components(CU FT) .53

XII. QUANTITY OF NONFRIABLE ASBESTOS  NOT REMOVED  TO BE REMOVED:  
Category I: \_\_\_\_\_ Category II: \_\_\_\_\_

XIII. WASTE TRANSPORTER: Name: Republic Services  
Full Mailing Address: 1035 Old Brandon Road  
Contact Person: Scott Johnson Telephone: 601-9014606

RECEIVED

FEB 23 REC'D

STATE OF MISSISSIPPI DEMOLITION/RENOVATION FORM - CONTINUED

XIV. WASTE ASBESTOS DISPOSAL SITE: Name: Pine Belt Regional Solid Waste Management Authority
Physical Location: 5274 Highway 29 S Overt MS
Full Mailing Address: 5274 Highway 29 S MS
Contact Person: Tony Harrison Telephone: 601-545-6676
\*All asbestos waste should go to a permitted sanitary landfill.

XV. DISPOSAL SITE FOR DEMOLITION DEBRIS (Other than asbestos):
Name:
Physical Location:
Full Mailing Address:
Contact Person: Telephone:
\*All demolition debris (other than asbestos) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.

XVI. REMOVAL/RENOVATION PROCEDURES TO BE USED (Check all that apply):
Strip & Removal X Double Bagging Mechanical Chipping Component Removal
Wrecking Ball Gross Demolition X Remove Intact Bulldozer
Containment Glove Bag Explode Negative Air
X Wet Method Roofing Saw Other - Explain Below:

XVII. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK:
Wet, Remove, Double bag, dispose of in proper container.

XVIII. PROCEDURES TO BE FOLLOWED IF UNEXPECTED ACM IS FOUND OR NONFRIABLE ACM BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO A POWDER OR SMALL PIECES:
Wet, notify proper authorities, clean-up and dispose.
\*Will MDEQ be notified of any significant changes? [X] Yes [ ] No

XIX. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, IDENTIFY THE AGENCY BELOW:
Name: Title:
Authority:
Date of Order: Date Demolition to Begin: / /

XX. EMERGENCY DEMOLITION/RENOVATIONS: Date of Emergency: / / Time:
Description of the sudden, unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or unreasonable financial burden:

XXI. When asbestos-containing material is present, an individual trained in the provisions of the regulation (40 CFR 61 Subpart M) will be on site during the demolition or renovation and evidence that the required training has been accomplished by this person will be available for inspection during normal business hours.

I certify that all of the above information is correct.

Charles G. Laporte - VP General Manager

Type or Print Name & Title

Signature: [Handwritten Signature] Date: 02/18/22

Signature Date

MAIL TO: Office of Pollution Control Physical Address 515 Amite Street
P.O. Box 2261 Jackson, MS 39225
Jackson, MS 39225 (601) 961-5171