

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

| | | | | |
|--|--|---|--|-----------|
| MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery | | Postmark (mail only) | Date Received: 3/17/22 | AI Number |
| I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Original | | | | |
| II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation | | | | |
| III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Refinery | | | | |
| Bldg. Name: Chevron Pascagoula Refinery | | | | |
| Address: 250 Industrial Rd | | | | |
| City: Pascagoula | | State: MS | Zip: 39581-3201 | |
| Site Location: 13 Plant - Vessels C1301, C1302, E1307 | | | | Tel: |
| Building Size: | | # of Floors: | Age in Years: 50+ | |
| Present Use: | | Prior Use: | | |
| IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator) | | | | |
| OWNER NAME: Chevron Products Company | | | | |
| Address: 250 Industrial Road | | | | |
| City: Pascagoula | | State: MS | Zip: 39581-3201 | |
| Contact: Benjamin Moore | | | Tel: 228-934-7553 | |
| ASBESTOS REMOVAL CONTRACTOR: Brock Services, LLC #ABC00009559 | | | | |
| Address: 10343 Sam Houston Park Dr. Suite 200 | | | | |
| City: Houston | | State: TX | Zip: 228-990-3739 | |
| Contact: Ken Sherman | | | Tel: | |
| Certification Number: | | | Expiration Date: | |
| OTHER OPERATOR: | | | | |
| Address: | | | | |
| City: | | State: | Zip: | |
| Contact: | | | Tel: | |
| V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): | | | | |
| WAS ASBESTOS PRESENT? (Yes/No): | | | Inspection Date: | |
| Inspector: | | Certification Number: | Expiration Date: | |
| VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: | | | | |
| Bulk sampled and analyzed Analyses performed in accordance with methodologies as outlined in interim Methods for the Determination of Asbestos in Bulk Insulation EPA-600/R-93/116 and Standard Method of Testing for Asbestos Containing Materials by Polarized Light Microscopy ASTM D 22.05 | | | | |
| VII. QUANTITY OF RACM TO BE REMOVED: | | | | |
| Pipes (LN FT): | | Surface Area (SQ FT): 1500 Sq Ft | Volume of Facility Components (CU FT): | |
| VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: | | | | |
| Category I: | | | Category II: | |
| IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 04/04/2022 Complete: 06/03/2022 | | | | |
| X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 04/04/2022 Complete: 06/03/2022 | | | | |

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Removal of asbestos from the following vessels to monitor for corrosion. Vessels affected include C1301, C1302, and E1307

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Strip & Removal, Containment, Wet Method, Double Bagging, Glove Bag, Remove Intact, Negative Air.

XIII. WASTE TRANSPORTER #1

Name: Waste Management of Mississippi - Gulf Coast

Address: Pecan Grove RDF, 9685 Firetower Rd

City: Pass Christian

State: MS

Zip: 39571

Contact Person: Rick Prickett

Tel: 228-832-3144

WASTE TRANSPORTER #2

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: Waste Management of Mississippi - Gulf Coast

Address: Pecan Grove RDF, 9685 Firetower Rd

City: Pass Christian

State: MS

Zip: 39571

Contact Person:

Tel: 228-255-5553

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:

Work will stop. Notifications will be completed as necessary. Proper controls will be instituted.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Benjamin Moore

bemw

Digitally signed by bemw
Date: 2022.03.16 15:49:33 -0500

3/16/2022

Type or Print Name

(Signature of Owner/Operator)

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Benjamin Moore

bemw

Digitally signed by bemw
Date: 2022.03.16 15:49:41 -0500

3/16/2022

Type or Print Name

(Signature of Owner/Operator)

(Date)