

14 Rev 11

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos Section, 515 E. Amite Street, Jackson, MS 39201

| | | | | |
|---|-----------------------------------|--|--------------------------------|------------------------------------|
| Operator Project # | Postmark 4.12.2022 | Date Received (MDEQ use only) 4.13.2022 | Notification # (MDEQ use only) | |
| I. Type of Notification (O=Original R=Revised C=Canceled A= Annual) R = Revision #2 (revision # 1 on 3-02-2022) | | | | |
| II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation) D = Demo | | | | |
| III. FACILITY DESCRIPTION (include building name, number and floor or room number) | | | | |
| Bldg. Name: 3 Vacant Residential Structures | | | | |
| Address 5611, 5643 & 5665 Cockrum Rd. | | | | |
| City: Olive Branch | State: MS | Zip: 38654 | | |
| Site Location: Cockrum Rd. at Sandidge | | Tel: 901-276-5459 | | |
| Building Size 3220,3276 & 3120 Sq. Ft. | # of Floors: 1 | Age in Years: 50 + / - | | |
| Present Use: Vacant | Prior Use: Somebody's home | | | |
| IV. FACILITY INFORMATION (Identify owner, removal contractor, and other operator) | | | | |
| OWNER NAME: Quik Trip Corp. | | | | |
| Address: 4705 South 129th East Ave. | | | | |
| City: Tulsa | State: OK | Zip: 74134 | | |
| Contact: Kyla Rudd | | Tel: 918-615-7233 | | |
| REMOVAL CONTRACTOR Specialty Abatement Services, Inc. | | | | |
| Address: P.O. Box 343012 | | | | |
| City: Memphis | State: TN | Zip: 38184-3012 | | |
| Contact: Dwight Grayson | | Tel: 901-849-7711 | | |
| OTHER OPERATOR: Chandler Demolition Co., Inc. | | | | |
| Address: 1223 North Watkins St. | | | | |
| City: Memphis | State: TN | Zip: 38108 | | |
| Contact: David Chandler | | | | |
| V. IS ASBESTOS PRESENT? (Yes/No) No Specialty Abatement completed removal and disposal of all ACM | | | | |
| VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL (Include inspector name and date of inspection): | | | | |
| Audrey C Price bulk sampling and PLM analytical 10-7-2021 | | | | |
| VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING: | | | | |
| <ol style="list-style-type: none"> Regulated ACM to be Removed Category I ACM Not Removed Category II ACM Not Removed | RACM To Be Removed | Nonfriable Asbestos Material Not To Be Removed | | Indicate Unit of Measurement Below |
| | | Category I | Category II | UNIT |
| Pipes | | | | Ln Ft: Ln M: |
| Surface Area | | | | Sq Ft: Sq M: |
| Vol RACM Off Facility Component | | | | Cu Ft: Cu M: |
| VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: | | | | Complete: |
| IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 5-2-2022 M-F | | | | Complete: 5-31-2022 |

APR 13 2022

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED: **Mechanically demolish STRUCTURES with Hydraulic Excavator**

XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Water will be sprayed from hose to prevent nuisance dust along with prompt clean up of debris

XII. WASTE TRANSPORTER #1 **Previously completed by Specialty Abatement Services Inc. for ACM waste**

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

WASTE TRANSPORTER #2 **Chandler Demolition Co., Inc. C & D waste**

Name: **Chandler Demolition Co., Inc.**

Address: **1223 North Watkins St.**

City: **Memphis**

State: **TN**

Zip: **38108**

Contact Person: **David Chandler**

Tel:

XIII. WASTE DISPOSAL SITE

Name: **Railroad Avenue Disposal**

Address: **11250 MS 178**

City: **Olive Branch**

State: **MS**

Zip: **38654**

Tel: **662-895-7625**

XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: **N/A**

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XV. FOR EMERGENCY RENOVATIONS: **N/A**

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

None

XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:

Cease all work, isolate ACM material in regulated area w/ red asbestos tape/signs, contact MDEQ

XVII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

David Chandler

Type or Print Name

David Chandler
(Signature of Owner/Operator)

4-12-2022

(Date)

XVIII. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

David Chandler

Type or Print Name

(Signature of Owner/Operator)

4-12-2022

(Date)