

Rev

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

| | | | |
|--|------------------------------------|--|-----------|
| MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery | Postmark (mail only) | Date Received 3-7-23 | AI Number |
| I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Revised to Courtesy Notification | | | |
| II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D | | | |
| III. FACILITY DESCRIPTION (Include building name, number and floor or room number): USDA Greenhouse | | | |
| Bldg. Name: Greenhouse 9A | | | |
| Address: 150 Twelve Lane | | | |
| City: Starkville | State: MS | Zip: 39762 | |
| Site Location: Greenhouse 9A | | Tel: | |
| Building Size: 3,398 SF | # of Floors: 1 | Age in Years: Unknown | |
| Present Use: Vacant | Prior Use: Greenhouse | | |
| IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator) | | | |
| OWNER NAME: USDA Ag. Research Service | | | |
| Address: 141 Experiment Station Road | | | |
| City: Stoneville | State: MS | Zip: 38776 | |
| Contact: | | Tel: | |
| ASBESTOS REMOVAL CONTRACTOR: Snyder Environmental & Construction, LLC | | | |
| Address: 7705 Northshore Place | | | |
| City: North Little Rock | State: AR | Zip: 72118 | |
| Contact: Andrew Ables | | Tel: 601-559-2185 | |
| Certification Number: ABC-00009502 | Expiration Date: 9/30/2023 | | |
| OTHER OPERATOR: Snyder Environmental & Construction, LLC | | | |
| Address: 7705 Northshore Place | | | |
| City: North Little Rock | State: AR | Zip: 72118 | |
| Contact: Justin Dixon | | Tel: 501-801-2773 | |
| V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes | | | |
| WAS ASBESTOS PRESENT? (Yes/No): Yes | | Inspection Date: 1/16/2021 | |
| Inspector: Paul Anderson | Certification Number: ABI-00001686 | Expiration Date: 6/24/2023 | |
| VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: | | | |
| PLM Bulk Samples 150 SF of window putty | | | |
| VII. QUANTITY OF RACM TO BE REMOVED: N/A | | | |
| Pipes (LN FT): | Surface Area (SQ FT): 150 SF | Volume of Facility Components (CU FT): | |
| VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: | | | |
| Category I: | | Category II: Window Putty | |
| IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 3/7/2023 | | Complete: 3/17/2023 | |
| X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 3/7/2023 | | Complete: 3/17/2023 | |

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Materials listed to be removed by hand so facility can be demolished. Cat. II non-friable ACM will not be disturbed or made friable. Will be removed by full component removal, in whole pieces. LF of Window Putty

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Materials will be wetted, during and after abatement, properly packaged, labeled and transported to a class 1 landfill for disposal.

XIII. WASTE TRANSPORTER #1

Name: RES

Address: 1041 CR 549

City: Ripley

State: MS

Zip: 38663

Contact Person: Shea Mask

Tel: 662-882-3853

WASTE TRANSPORTER #2

Name: N/A

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: Three Rivers Regional Landfill

Address: 1904 Pontotoc Parkway

City: West Pontotoc

State: MS

Zip: 38863

Contact Person: N/A

Tel: 803-827-2808

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: N/A

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

N/A

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

N/A

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:

Wet the unexpected, make area safe and notify MDEQ.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Barbara McElroy

Type or Print Name

Barbara McElroy

(Signature of Owner/Operator)

3/6/2023

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Barbara McElroy

Type or Print Name

Barbara McElroy

(Signature of Owner/Operator)

3/6/2023

(Date)