



Rev
MAP

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 4-25-23	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): R				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: Clverdale Apartments Community Center				
Address: 900 Williams St. NE				
City: Brookhaven		State: MS	Zip: 39601	
Site Location: Brookhaven		Tel:		
Building Size: approx 1900 sq ft		# of Floors: 1	Age in Years:	
Present Use: community center		Prior Use:		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Brookhaven Housing Authority				
Address: 504 Brookman Drive				
City: Brookhaven		State: MS	Zip: 39601	
Contact: Jeffery Adams		Tel: 601-833-1781		
ASBESTOS REMOVAL CONTRACTOR: Southeast Environmental Group, Inc.				
Address: P.O. Box 433/ 296B 2nd Ave.				
City: York		State: AL	Zip: 36925	
Contact: Bertha Rodgers		Tel: 205-392-9308		
Certification Number: ABC-00001906		Expiration Date: 05/10/2023		
OTHER OPERATOR:				
Address:				
City:		State:	Zip:	
Contact:		Tel:		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): yes				
WAS ASBESTOS PRESENT? (Yes/No): yes		Inspection Date: 04/11/2023		
Inspector: Johnny Rodgers		Certification Number: AB1-00011403	Expiration Date: 04/27/2023	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Analysis by Polarize Light Microscopy . Floor tile 2% chrysotile and Mastic 4% chrysotile. Safety Environmental Lab and consulting, Inc..				
VII. QUANTITY OF RACM TO BE REMOVED: approx 1400 sq ft				
Pipes (LN FT):		Surface Area (SQ FT):	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:		Category II:		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 04/27/2023		Complete: 05/27/2023		
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: N/A		Complete: N/A		

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:		
Removal of old flooring containing ACM will be performed by trained and certified personnel. The ACM will be kept wet throughout the process. The work area will be protected and sealed by using the capsule concept to assure the least to no particles escape.		
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:		
The non-friable ACM will be removed by competent personnel that is trained and knowledgeable in the removal, handling, and disposal of ACM. All work will be done to comply with Federal, State, and local regulations. The work area will be protected and sealed by using the capsule concept to assure the least to no particles escape. The concept of 'keep it wet' will be used throughout the asbestos removal process.		
XIII. WASTE TRANSPORTER #1		
Name: Johnny Rodgers		
Address: 296B 2nd Ave		
City: York	State: AL	Zip: 36925
Contact Person: Bertha Rodgers	Tel: 205-392-9308	
WASTE TRANSPORTER #2		
Name:		
Address:		
City:	State:	Zip:
Contact Person:	Tel:	
XIV. WASTE DISPOSAL SITE		
Name: Kemper County Landfill		
Address: 21211 Hwy 16 East		
City: Dekalb	State: MS	Zip: 39328
Contact Person: Jimmy Thomas	Tel: 601-743-4310	
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:		
Name:	Title:	
Authority:		
Date of Order (MM/DD/YY):	Date Ordered to Begin (MM/DD/YY):	
XVI. FOR EMERGENCY RENOVATIONS:		
Date and Hour of Emergency (MM/DD/YY):		
Description of the sudden unexpected event:		
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:		
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLING, PULVERIZED, OR REDUCED TO POWDER:		
MDEQ will be notified immediately. ACM will be handled same as original.		
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.		
Bertha Rodgers		4/25/2023
Type or Print Name	(Signature of Owner/Operator)	(Date)
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:		
Bertha Rodgers		4/25/2023
Type or Print Name	(Signature of Owner/Operator)	(Date)