

(P)

REV

MAP

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> E-mail <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 7.7.2023	Alt Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):		R=REVISED (DATE)		
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renoivation E=Emer. Renovation):		E=EMER. RENOVATION		
III. FACILITY DESCRIPTION (include building name, number and floor or room number):				
Bldg. Name: DEER CREEK ELEMENTARY SCHOOL				
Address: Old Hwy 61 N. DEER CREEK Cir 300N Deer Creek Dr.				
City: ARCOLA	State: MS	Zip: 38722		
Site Location: DEER CREEK Circle, ARCOLA, MS		Tel: 662-827-5165		
Building Size: 1800 SF	# of Floors: 1	Age in Years: 40+		
Present Use: VACANT For School Break	Prior Use: SCIENCE CLASSROOMS			
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: DEER CREEK Elementary School				
Address: P.O. BOX 376				
City: ARCOLA	State: MS	Zip: 38722		
Contact: MARY Hobart		Tel: 662-827-5165		
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL Services, LLC.				
Address: P.O. BOX 133				
City: DELTA City	State: MS	Zip: 39061		
Contact: Jimmy Bell		Tel: 662-820-2124		
Certification Number: ABC-00001282		Expiration Date: 1/5/2024		
OTHER OPERATOR: DEER CREEK Elementary School (MAINTENANCE Dept.)				
Address: P.O. BOX 376				
City: ARCOLA	State: MS	Zip: 38722		
Contact: MARY Hobart		Tel: 662-827-5165		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES			Inspection Date: 8/1/16	
Inspector: ALBERT L. LOVE	Certification Number: ASZ-00001376	Expiration Date: 1/24/17		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: SAMPLES TAKEN FROM FLOOR TILE/MASTIC, CEILING MATERIALS, ROOF MATERIALS, WINDOW MATERIALS, WALLS, PAINT, INSULATION AND DOORS. AND SUBMITTED TO THE SCIENTIFIC ANALYTICAL LAB, GREENSBORO, NC. THE PLM METHOD WAS USED TO DETECT ASBESTOS PRESENT				
VII. QUANTITY OF RACM TO BE REMOVED: (SCIENCE ROOMS) WALL PANEL (TRANSITE) 1800 SF, ONLY				
Pipes (LN FT): 51	Surface Area (SQ FT): 2,240	Volume of Facility Components (CU FT):		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 5				
Category I: <input checked="" type="checkbox"/>		Category II:		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 7/10/23		Complete: 7/12/23		
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 7/4/23		Complete: 7/30/23		

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:
 USE Method, Containment, Neg-Air, Spas, D-Con unit, Independent Air Monitoring/
 Ten Air Clearance.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT ERRORS OF ASBESTOS AT THE
 DEMOLITION OR RENOVATION SITE: REMOVE ALL CONTENTS AWAY FROM WALLS, CEILING, FLOOR AREA WITH
 6 mil poly OVER WOODS, DOORWAYS, Wet, Remove, Double bag TRASH, WALLS AND JOINTS WITH
 HEPA-VAC, CLEANUP, SPRAY FIBERLOC, MIST HYDRANT.

XIII. WASTE TRANSPORTER #1

Name: W H + D
 Address: P.O. BOX 870
 City: Leland
 State: MS
 Zip: 38756
 Contact Person: Tommy Hendrix
 Tel: 662-826-4184
 WASTE TRANSPORTER #2
 N/A

XIV. WASTE DISPOSAL SITE

Name: Big River Landfill (Republic Services)
 Address: 48 Landfill Rd.
 City: Leland
 State: MS
 Zip: 38756
 Contact Person:
 Tel:

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name:
 Title:
 Contact Person: Melissa Johnson
 Special Unit
 Tel: 601-420-8248
 Date of Order (MANDATORY):
 Date Ordered to Begin (MANDATORY):

XVI. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MANDATORY): 5/8/2023 Flood Rain/Hail Storm
 Description of the sudden unexpected event:
 Weather cause flooding in between classrooms of the
 school. Must remove and before school start for summer school. Requesting early start
 and/or removal of school.
 Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:
 MS Mary Hobart (Head of Schools) 662-822-0362
 662-822-0362

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY
 NONPULVERIZABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:
 CONTAINMENT UNDER CONTAINMENT, NOTIFY OIG/MSDC OF CHANGE. REVISE
 notification form.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE
 ON-SITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY
 THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Type of Firm Name: Jimmy Bell
 Signature of Owner/Operator: Jimmy Bell
 Date: 7/7/23
 Type of Firm Name: Jimmy Bell
 Signature of Owner/Operator: Jimmy Bell
 Date: 7/7/23
 XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT.