

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

MAP

①

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 07-18-2023	Al Number 70371
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): O = ORIGINAL				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R = RENOVATION				
III. FACILITY DESCRIPTION (include building name, number and floor or room number):				
Bldg. Name: South CANAL Subdivision				
Address: 701 South CANAL Street				
City: Tupelo		State: MS	Zip: 38801	
Site Location: 1614 GREEN STREET		Tel: 662-416-3418		
Building Size: 900 sq.		# of Floors: 1	Age in Years: 40 +	
Present Use: VACANT FOR REPAIRS		Prior Use: SINGLE FAMILY 2 bedroom Dwelling		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Tupelo Housing Authority				
Address: 701 South CANAL Street				
City: Tupelo		State: MS	Zip: 38801	
Contact: Tabitha Smith		Tel: 662-842-5122-ext. 2002		
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC				
Address: P.O. BOX 133				
City: Delta City		State: MS	Zip: 39061	
Contact: Jimmy Bell		Tel: 662-820-2124		
Certification Number: ABC-00001282		Expiration Date: 1/5/2024		
OTHER OPERATOR: PAET & SONS CONSTRUCTION, INC.				
Address: 374 CR-7000				
City: BOONEVILLE		State: MS	Zip: 38829	
Contact: CLAYTON PAGE		Tel: 662-416-3418		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES		Inspection Date: Aug. 19, 2011		
Inspector: William J. Young		Certification Number: AB2-00001688	Expiration Date: 9/24/2011	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: SAMPLES TAKEN FROM: SHEETROCK WALLS, CEILING TILE, FLOOR TILE/MASTIC, INSULATION, ROOFING MATERIALS, WINDOW MATERIALS, KITCHEN SINK BOTTOM. ALL MATERIALS SHIPPED TO C.A. LABS, INC., BATON ROUGE, LA. TESTED USING THE PLM METHOD FLOOR TILE/MASTIC CONTAINS ASBESTOS				
VII. QUANTITY OF RACM TO BE REMOVED: FLOOR TILE/MASTIC HALLWAY / 1 BEDROOM ONLY				
Pipes (LN FT): 6	Surface Area (SQ FT): 400 sq.		Volume of Facility Components (CU FT): 6	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 6				
Category I: <input checked="" type="checkbox"/>		Category II: <input type="checkbox"/>		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 8/3/23			Complete: 8/5/23	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 8/8/23			Complete: 11/20/23	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:
Wet method, containment, Neg-Air, D-CON unit, Independent Air monitoring/Air -
CLEARANCE, Double Bag.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE
DEMOLITION OR RENOVATION SITE: PREP SITE, SIGNS, 6 mil poly over windows and doors, Air
VENTS. Wet remove. Double BAG, DYOP TAG, TAPE CLOSE. REMOVE MASTIC, SOLIDIZE, Double Bag.
PLACE ALL BAGS INTO Lined Trailer Dump with TARP. NEPA-VAC, CLEAN, AWAIT Air CLEARANCE.

XIII. WASTE TRANSPORTER #1

Name: BELL ENVIRONMENTAL SERVICES, LLC
Address: P.O. BOX 133
City: Delta City State: MS Zip: 39061
Contact Person: JIMMY BELL Tel: 662-820-2124

WASTE TRANSPORTER #2 N/A

Name:
Address:
City: State: Zip:
Contact Person: Tel:

XIV. WASTE DISPOSAL SITE

Name: THREE RIVER LANDFILL
Address: 1904 PONTOTOC PARKWAY WEST
City: PONTOTOC State: MS Zip: 38863
Contact Person: 662-488-0444 Tel: 662-488-0444

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: N/A

Name: Title:
Authority:
Date of Order (MM/DD/YY): Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):
Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY
NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLER, PULVERIZED, OR REDUCED TO POWDER:
STOP WORK, CONTINUE NEG-AIR, CONTAINMENT, CONTACT OWNER/MDEQ OF CHANGE,
SEND MDEQ REVISED NOTIFICATION.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE
ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY
THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell Type or Print Name Jimmy Bell (Signature of Owner/Operator) 7/18/23 (Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:
Jimmy Bell Type or Print Name Jimmy Bell (Signature of Owner/Operator) 7/18/23 (Date)