



REV

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 01-23-2024	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): R = Revised				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D = Demolition				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: N/A				
Address: 1602 4th Avenue North				
City: Columbus		State: MS.	Zip: 39701	
Site Location: R-1 Residential			Tel: (662) 570-8814	
Building Size: 2,064 square feet		# of Floors: One	Age in Years: 56 years old	
Present Use: Abandoned		Prior Use: Residential		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Mamie Lou and James Turner				
Address: C/O Goldie Turner Smith P.O.Box 8131				
City: Columbus		State: MS.	Zip: 39705	
Contact: Sasha James			Tel: (662) 251-2359	
ASBESTOS REMOVAL CONTRACTOR: EAC Environmental				
Address: 4546 Calsteens Road				
City: Caledonia		State: MS.	Zip: 39740	
Contact: Edward Clay			Tel: (662) 549-1777	
Certification Number: ABC-00005192			Expiration Date: 11/03/2024	
OTHER OPERATOR: Columbus Fire and Rescue				
Address: 72 Airline Road				
City: Columbus		State: MS.	Zip: 39702	
Contact: Duane Hughes			Tel: (662) 570-8814	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes				
WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspection Date: 6/16/2023	
Inspector: Barbara B. Vanlandingham		Certification Number: AB1-00007369	Expiration Date: 6/11/2024	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Black Shingle with Gray Gravel, White Sealant, Green Transite, Brown and Blue Linoleum, White Drywall, White Surfaced White Compound, and Black Textured Surfacing.				
Polarized Light Asbestiform Materials Characterization - 25% chrysolite asbestos exterior siding				
VII. QUANTITY OF RACM TO BE REMOVED: Exterior Siding				
Pipes (LN FT): N/A		Surface Area (SQ FT): 2,064	Volume of Facility Components (CU FT): N/A	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: N/A				
Category I: N/A			Category II: N/A	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 06/26/2023			Complete: 06/26/2023	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 02/20/2024			Complete: 02/21/2024	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:		
Columbus Fire and Rescue will conduct a live burn of this structure for multiple training exercises as identified in the incident action plan (IAP).		
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:		
All asbestos present on this site as determined by testing performed by CA Labs, L.L.C. was removed on 6/26/2023.		
XIII. WASTE TRANSPORTER #1		
Name: City of Columbus Public Works		
Address: 523 Main Street		
City: Columbus	State: MS.	Zip: 39701
Contact Person: Casey Bush	Tel: 662 364-0923	
WASTE TRANSPORTER #2		
Name: N/A		
Address: N/A		
City: N/A	State: N/A	Zip: N/A
Contact Person: N/A	Tel: N/A	
XIV. WASTE DISPOSAL SITE		
Name: RO BO Landfill		
Address: 6447 Wahalak Road		
City: Scooba	State: MS.	Zip: 39358
Contact Person: Roland Edwards, Manager	Tel: 662 793-4795	
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:		
Name: N/A	Title: N/A	
Authority: N/A		
Date of Order (MM/DD/YY): N/A	Date Ordered to Begin (MM/DD/YY): N/A	
XVI. FOR EMERGENCY RENOVATIONS: N/A		
Date and Hour of Emergency (MM/DD/YY): N/A		
Description of the sudden unexpected event: N/A		
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: N/A		
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:		
- Notify Building Inspection Department -		
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.		
Duane Hughes - Fire Chief		23 January 2024
Type or Print Name	(Signature of Owner/Operator)	(Date)
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:		
Duane Hughes - Fire Chief		23 January 2024
Type or Print Name	(Signature of Owner/Operator)	(Date)