MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: Email EMail EHand Delivery	Postmark (mail only)		Data Received 3/26/2024		Al Number		
I. Type of Notification (O=Original R=Revised	I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):						
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):							
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):							
Bldg. Name: Meadowview Apartments							
Address: 100 Brook Road, Baldwyn, MS							
_{City:} Baldwin		State: MS		Zip: 38824			
Site Location: Apartment Units A-F		1		Tel: (601) 924-7632			
Building Size: Approx. 21,115sf		# of Floors: 2		Age in Years: 45+			
Present Use: Apartment Building		Prior Use: Apartment Building					
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)							
OWNER NAME: Gulf Coast Housing Partnership, Inc							
Address: 3304 North State St., Ste. 101							
City: Jackson State: MS		State: MS		_{Zip:} 39216			
Contact: Leah L				Tel: (601) 316-3692			
ASBESTOS REMOVAL CONTRACTOR: ANDERSON ENVIRONMENTAL							
Address: 783 HARRIS STREET							
City: JACKSON	State: MS			_{Zip:} 39202			
Contact: DARYL ANDERSON			_{Tel:} 601-354-4400				
Certification Number: ABC-00002173		Expiratio		on Date: 10-27-24			
OTHER OPERATOR: New Horizon Development							
Address: 149 Concourse Dr, Jackson, MS 39208							
_{City:} Pearl		State: MS		Zip: 39208			
Contact: Nick Provias				_{Tel:} (601) 932-1739			
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No.): Yes							
WAS ASBESTOS PRESENT? (Yes/No): Yes Inspection Date: 09-26-2023					023		
Inspector: Paul Anderson Certification Number: .ABI-00001686 Expiration Date: 6-09-24							
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Floors, walls, ceilings, roofs, windows, pipes							
PLM - EHS Laboratories							
VII. QUANTITY OF RACM TO BE REMOVED: 18,000sf of floor tile and mastic							
Pipes (LN FT): Surface Area (SQ FT): Volume of Facility Components (CU			mponents (CU FT):				
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:							
Category I: Category II:							
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 4-10-24 Complete: 5-30-24							
x, scheduled dates demo/renovation (MM/DD/YY) Start: 4-20-24 Complete: 10-30-24							

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOV.	ATION WORK AN	D METHOD(S) TO BE USED				
Renovation of Apartment Complex	ATION WORK, AN	D WELHOD(2) TO BE 02FD	:			
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEER DEMOLITION OR RENOVATION SITE:	ING CONTROLS T	O BE USED TO PREVENT E	EMISSIONS OF ASBESTOS AT THE			
Area contained, placed under negative air						
XIII. WASTE TRANSPORTER #1			dom bago for diopood.			
Name: Waste Management						
Address: 1649 Highway 15 North, Houston, I	MC 28851					
City: Houston	State: MS	20051				
Contact Person: Dispatch Manager	State: IVIO	Zip: 38851				
WASTE TRANSPORTER #2		Tel: (866) 9	<u> </u>			
Name:						
Address:						
City:	State:					
Contact Person:	State:	Zip:				
XIV. WASTE DISPOSAL SITE		Tel:				
Name: Prairie Bluff Landfill						
Address: 1649 Highway 15 North, Houston, N	VS 38851					
City: Houston	State: MS	Zip: 38851	7to: 38851			
Contact Person: Landfill Manager	Oldio.		(000) 000 4450			
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENC	CY. PLEASE IDEN	101.				
Name:						
Authority:						
Date of Order (MM/DD/YY): Date Ordered to Begin (MM/DD/YY):						
XVI. FOR EMERGENCY RENOVATIONS:		Oldored to Regar to	0):			
Date and Hour of Emergency (MM/DD/YY):						
Description of the sudden unexpected event:						
Evaluation of how the avent arrived and fine and the						
Explanation of how the event caused unsafe conditions or would	cause equipment d	iamage or an unreasonable fi	nancial burden:			
YVII DESCRIPTION OF PROCEDURES TO BE SOLLOWED I	·					
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER: Halt all work and notify the proper authority						
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.						
DARYL ANDERSON	Dins!	Tuch	3-26-24			
	(Signature of owner/O	perator)	(Date)			
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT DARYL ANDERSON	CT: Dust 6	inhor	3-26-24			
Type or Print Name (Signature of Owner/Operator) (Date)						