

REV

# MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 7/17/2024	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):			R = REVISED Address/Location	
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):			D = DEMO	
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: ROSEDALE QALCB, LLC				
Address: 800 - 804 South Main Street				
City: ROSEDALE	State: MS	Zip: 38769		
Site Location: 800 - 804 South Main Street (OLD BANK)	Tel: 662-207-8330			
Building Size: 6,000 SF.	# of Floors: 1	Age in Years: 60 +		
Present Use: VACANT	Prior Use: OFFICE SPACE			
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: City of Rosedale				
Address: 304 Court Street				
City: ROSEDALE	State: MS	Zip: 38769		
Contact: JACK COLMAN	Tel: 662-207-8330			
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC.				
Address: P.O. BOX 133				
City: DELTA City	State: MS	Zip: 39061		
Contact: Jimmy Bell	Tel: 662-820-2124			
Certification Number: ABC-00001282	Expiration Date: 1/5/25		12/15/2024	
OTHER OPERATOR: David Smith Construction, Inc.				
Address: P.O. BOX 91				
City: INVERNESS	State: MS	Zip: 38757		
Contact: MARTIN Smith	Tel: 662-207-8330			
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES			Inspection Date: 9/28/2022	
Inspector: REGINAL SAMPSON	Certification Number: ASI-00001921	Expiration Date: 8/2/23 7/27/2024		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: SAMPLES WERE TAKEN FROM: CEILING TILE, ATTIC INSULATION, WALLS, ROOF MATERIALS, FLOOR TILE/MASTIC, AND SHIPPED TO: EMSL LABS, INC., BATON ROUGE, LA WHERE THEY ANALYSED USING THE PLM METHOD. Results: FLOOR TILE/MASTIC CAME BACK POSITIVE THROUGHOUT THE WAITING ROOM AND BANK-Vault Area.				
VII. QUANTITY OF RACM TO BE REMOVED: APPROXIMATELY 280 SF OF FLOOR TILE/MASTIC (Waiting Room & Bank Vault)				
Pipes (LN FT): 0	Surface Area (SQ FT): 280 SF	Volume of Facility Components (CU FT): 0		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0				
Category I: ✓	Category II:			
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 8/1/24			Complete: 8/5/24	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 8/6/24			Complete: 9/25/24	

52

**XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:**

CONTAINMENT, NEG-Air unit, D-CON unit, WET Method, BAG

**XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:**

PREP SITE: SIGNS, 6 MIL POLY OVER WINDOWS/DOORS  
PLACE NEG. UNITS IN PROPER AREAS VENTING OUT, WET AND REMOVE FLOOR TILE, DOUBLE BAG,  
DROP TAG, TAPE SHUT, REMOVE MASTIC, SOLIDIZE, PLACE INTO DOUBLE BAGS, PLACE ALL BAGS INTO LINED -

**XIII. WASTE TRANSPORTER #1** DUMPSTORY, AWAIR AIR CLEARANCE.

Name: WH & D, INC. (WASTE HAULING AND DISPOSAL)

Address: P.O. BOX 870

City: LELAND

State: MS

Zip: 38756

Contact Person: Tommy Hendrix

Tel: 662-347-0052

WASTE TRANSPORTER #2 N/A

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

**XIV. WASTE DISPOSAL SITE**

Name: Big River Landfill (REPUBLIC)

Address: 52 LANDFILL ROAD

City: LELAND

State: MS

Zip: 38756

Contact Person: ALISHA JOHNSON (SPECIAL WASTE)

Tel: 662 332 7929

**XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:** N/A

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

**XVI. FOR EMERGENCY RENOVATIONS:** N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

**XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:**

STOP ABATEMENT, REMAIN UNDER CONTAINMENT, CONTACT OWNER/MDEQ OF CHARGE.  
FOLLOW MDEQ DIRECTIONS, REVISED NOTIFICATION FORM.

**XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.**

Jimmy Bell

Type or Print Name

(Signature of Owner/Operator)

7/19/24

(Date)

**XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:**

Jimmy Bell

Type or Print Name

(Signature of Owner/Operator)

7/19/24

(Date)