MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ■Email □Mail □Hand Delivery	Postmark (ma	Postmark (mail only)		ceived 1/24/2025	Al Number	
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Original						
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation						
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Nettleton High School						
Bldg. Name: Offices & Library						
Address: 165 Mullen Ave						
_{City:} Nettleton		State: MS		Zip: 38858		
Site Location: Offices & Library				Tel: 662-963-2306		
Building Size: 8000 sqft		# of Floors: 1		Age in Years: 50 +/-		
Present Use: School Offices & Library		Prior Use: School Offices & Library				
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)						
OWNER NAME: Nettleton School District						
Address: 179 Mullen Ave						
_{City:} Nettleton		State: MS		Zip: 38858		
_{Contact:} Ken Byars				Tel: 662-963-215		
ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.						
Address: P.O. Box 343012						
City: Memphis	mphis		State: TN		z _{ip:} 38184-3012	
Contact: Dwight Grayson				Tel: 901-507-1203		
Certification Number: ABC00001660 Wil	Expiration Date: 02/23/2025		5			
OTHER OPERATOR: n/a						
Address:						
City:		State:		Zip:		
Contact:				Tel:		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes						
WAS ASBESTOS PRESENT? (Yes/No): Yes Inspection Date: 10/22/2024					24	
Inspector: Willie Nester Certification Number: ABI-00002244 Expiration Date: 01/24/2025						
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Floor Tile & Mastic Sheetrock/ Joint compound						
Sheetrock/Joint compound						
Roofing, Ceiling Tiles, Caulking, Wood Laminate, cove base						
VII. QUANTITY OF RACM TO BE REMOVED: 1,200 sqft VAT/1,200 sqft Mastic/400 SF Sheetrock Joint Compound						
Pipes (LN FT): n/a	Surface Area (SQ FT): 1,200/1,200/400 Volume of Facility Components (CU FT): n/a					
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: N/A						
Category I: n/a Category II: n/a Category II: n/a						
K. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 02/07/2025 Complete: 02/14/2025						
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 02/07/2025 Complete: 02/14/2025						
Complete.						

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVA	TION WORK, AND METHOD	O(S) TO BE USED:				
Removal of ACM using hand tools and we						
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERI DEMOLITION OR RENOVATION SITE:	NG CONTROLS TO BE USE	D TO PREVENT EMISSIONS OF ASBESTOS AT THE				
Splashguard containment, negative pressure, hand tools, chemical stripper, double bag waste						
XIII. WASTE TRANSPORTER #1 SASI		·				
Name: SASI Memphis						
Address: 4009 Broadway Rd						
_{City:} Bartlett	State: TN	Zip: 38135				
Contact Person: Dwight Grayson		Tel: 901-507-1203				
WASTE TRANSPORTER #2 L&T Services LLC						
Name:L&T Services LLC						
Address: 2170 Highway 51						
_{City:} Hernando	State: MS	Zip: 38632				
Contact Person: Carlton Gibson		Tel: 662-429-7335				
XIV. WASTE DISPOSAL SITE WM The Tunica Landfill						
Name: WM The Tunica Landfill						
Address: 6035 Bowdre Rd						
_{City:} Robinsonville	State: MS	Zip:				
Contact Person: Carlton Gibson	Control	Tel: 901-331-7187				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:						
Name: n/a Title:						
Authority: n/a	, ite.					
n/a						
Date of Order (MM/DD/YY): N/a Date Ordered to Begin (MM/DD/YY):						
XVI. FOR EMERGENCY RENOVATIONS: N/a						
Date and Hour of Emergency (MM/DD/YY): n/a Description of the sudden unexpected event:						
n/a						
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:						
n/a						
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY						
NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:						
All work will cease, workers will be removed from site, MDEQ will be called for an inspection?						
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.						
William Stamps	LEATH A	01/24/25				
Type or Print Name	(Signature of Owner/Operator)	(Date)				
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:						
Dwight Grayson	A Myn	01/24/25				
Type or Print Name (Signature of Owner/Operator) (Date)						