

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 03-06-2025 & 03/11/2025	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): O				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: Residential House				
Address: 1309 MARIA DR.				
City: JACKSON		State: MS	Zip: 39204	
Site Location: Same as above			Tel:	
Building Size: 1,023		# of Floors: 1	Age in Years: 66	
Present Use: abandoned single family dwelling		Prior Use: single family dwelling		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: STATE OF MISS				
Address: P O BOX 136				
City: JACKSON		State: MS	Zip: 39205-0136	
Contact: City of Jackson			Tel: 601-960-1054 or 601-960-2747	
ASBESTOS REMOVAL CONTRACTOR: Forrest Construction LLC				
Address: 591 raymond rd				
City: Jackson		State: MS	Zip: 39204	
Contact: Darius Forrest			Tel: (601) 720-5684	
Certification Number: ABC-00008477			Expiration Date: 8/3/25	
OTHER OPERATOR: SOCRATES GARRETT ENTERPRISES, INC.				
Address: 2659 LIVINGSTON RD				
City: JACKSON		State: MS	Zip: 39213	
Contact: see signature			Tel: 601-209-9199	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES			Inspection Date: 1/23/2024	
Inspector: VINCENT MCDONALD		Certification Number: ABI-00011874	Expiration Date: 10/25/2025	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:				
EPA 600/R-93-/116 BULK POLARIZED LIGHT MICROSCOPY (EAS)				
EXTERIOR BRICK MORTAR, ROOFING SHINGLES, ROOFING FELT PAPER, EXTERIOR VINYL SIDING, SHEETROCK				
VII. QUANTITY OF RACM TO BE REMOVED: Transite/siding				
Pipes (LN FT):		Surface Area (SQ FT): 1,008 sq ft	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I: X			Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 3/17/25 Complete: 3/20/25				
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 3/20/25 Complete: 3/27/25				

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Demolition of Structure with trachoe

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Water, Utility knife, razor scraper, spray bottle, poly sheeting, waste bags, personal protective,

XIII. WASTE TRANSPORTER #1

Name: Forrest Construction LLC (Asbestos)

Address: 591 raymond rd

City: Jackson

State: Ms

Zip: 39204

Contact Person: Darius Forrest

Tel: (601) 720-5684

WASTE TRANSPORTER #2

Name: Madison South Landfill (DEMO)

Address: 229550 N COUNTY LINE RD

City: RIDGELAND

State: MS

Zip: 392157

Contact Person: OFFICE

Tel: 601-981-5577

XIV. WASTE DISPOSAL SITE

Name: Clearview Landfill (ASBESTOS)

Address: 2253 mudline road lake

City: Lake

State: Ms

Zip: 39092

Contact Person: None specific

Tel: 605363240

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: SAMANTHA GRAVES

Title: MANAGER

Authority: City of Jackson

Date of Order (MM/DD/YY): 1/14/2025

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Call mdeq

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLER, PULVERIZED, OR REDUCED TO POWDER:

Call mdeq

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Darius Forrest

Type or Print Name

(Signature of Owner/Operator)

3/3/25

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

JACQUELINE ROSADO (COO)

Type or Print Name

(Signature of Owner/Operator)

3/6/2027

(Date)



Hinds County

MISSISSIPPI
FOUNDED 1821 * POPULATION 248,643

[HindsCountyMs.com](#) [Database](#) [Back](#) [Print Page](#)

Landroll Detail

Parcel Number		Map Reference Number	
633-184		745.00 1 112.00	
		View Map Property Taxes Gis Map	
Subdivision No.		Homestead Exemption Account Numbers	
1878			
Assessed Owner		Assessed Values	
STATE OF MISS		Land Value 0	
		Improvement Value 0	
		Total 0	
Location		Appraised Values	
1309 MARIA DR		Land Value 0	
Legal Description		Improvement Value 0	
LOT 35 WESTGATE PARK SUBN		Total 0	
MATURED FOR 2016 TAXES		Building Info.	
		Type RES	
		Base Area 1,008	
		Adjusted Area 1,023	
		Year Built 1959	
		Deed Info.	
		Book & Page -	
		Date 00/00/0000	
Acreage Info.			
Cultivated Acres	0.00		
Uncultivated Acres	0.00		

[Back](#) [Search](#)





**Environmental
Analytical
Services, LLC**

13201 Northwest Freeway, Suite 520
Houston, Texas 77040
phone 713-343-4017 | fax 713-934-9942
www.easlabs.com | facebook.com/easlabs | info@easlabs.com

**Test: EPA 600/R-93/116
Polarized Light Microscopy**

Client Information:

City of Jackson
200 S President St
Jackson, MS 39201
Phone: 601-960-1054
E-Mail: mcdonaldv@city.jackson.ms.us

Project:

1309 Maria Dr.
CE-22-1275
EAS Job: 24013113
Attn: Vincent
McDonald

Date Analyzed: 02/02/2024 03:16 PM

Date Received: 01/30/2024 09:20 AM

TAT Requested: 3 Days

Microscope: Olympus-CH-40

Sample # Lab ID #	Layer	Sample Description	Asbestos Detected (Yes/No)	Asbestos Mineral Percent	Non-Asbestos Fibers	Non-Fibrous Material
1 24013113.01	A	Gray Granular Brick Mortar Homogeneous	NO	None Detected		Sand / Aggregates 80% Binders 20%
2 24013113.02	A	Black/Brown/Gray Fibrous/Granular/Tar Roofing Shingle Non-Homogeneous	NO	None Detected	Cellulose 20% Fiberglass 20%	Asphaltic Matrix 60%
3 24013113.03	A	Black Fibrous/Tar Felt Paper Homogeneous	NO	None Detected	Cellulose 60%	Adhesive 40%
4 24013113.04	A	Blue/Gray Granular Transite Siding Homogeneous	YES	Chrysotile 40%		Other Non-Fibrous 60%
5 24013113.05	A	Tan/White Fibrous Sheetrock Non-Homogeneous	NO	None Detected	Cellulose 30%	Gypsum 70%

NVLAP Lab Code: 200784-0
TDSHS License No. 300373
LDEQ LELAP Certificate No: 04161, Agency Interest No. 149571

Notes:

Some samples (floor tiles, surfacing, etc.) may contain fibers too small to be detectable by PLM. TEM Chatfield analysis of bulk material is recommended in this case. All asbestos percentages are based on calibrated visual estimates traceable to NIST standards for regulated asbestos types. Analysts' percentages fall within a range of acceptable percentages, depending on the actual concentration of asbestos. This test report relates only to the items tested. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. This report may not be reproduced except in full without permission from Environmental Analytical Services.

These results are submitted pursuant to EAS' current terms of sale, including the company's standard warranty and limitation of liability provisions and no responsibility or liability is assumed for the manner in which the results are used or interpreted. Unless notified in writing to return the samples covered by this report, EAS will store the samples for a period of ninety (90) days before discarding. Percent ranges reported are estimates and not absolute percent range values.

Analyzed By:

Arthur Hernandez

Approved Signatory:

Arthur Hernandez

