## MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ⊠Email □Mail □Hand Delivery	Postmark (mail only)	Date R 1/6	Received /23	Al Number			
I. Type of Notification (O=Original R=Revised	C=Canceled A= Annual): O	R	3.159.18/4				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R							
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):							
Bldg. Name: Smithdale Main Post Office							
Address: 6005 MS Highway 570							
<sub>City:</sub> Smithdale	State: MS	State: MS Zip: 11753-39664-		9664-9998-			
Site Location:	1574 G.			Tel: 601-567-2621			
Building Size: 1,457 SF	# of Floors:	# of Floors: 1		Age in Years: 38			
Present Use: Postal Office	Prior Use:	Prior Use: Unknown					
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)							
OWNER NAME: United States Postal Service							
Address: 401 East South Street							
<sub>City:</sub> Jackson	State: MS		zip: 39201-9470				
Contact: Cindy King (Postmaster)			Tel: 601-876	-3755			
ASBESTOS REMOVAL CONTRACTOR: Snyder Environmental & Construction, LLC							
Address: 7705 Northshore Place							
City: North Little Rock			<sub>Zip:</sub> 72118				
Contact: Justin Dixon			<sub>Tel:</sub> 501-801-2776				
Certification Number: ABC00009502		Expira	Expiration Date: 9/30/2023				
OTHER OPERATOR: N/A							
Address: N/A							
City: N.A	State: N/A	State: N/A		<sub>Zip:</sub> N/A			
Contact: N/A			Tel: N/A				
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes							
WAS ASBESTOS PRESENT? (Yes/No): Yes		Inspect		tion Date: 10/21/1996			
Inspector: Nathaniel C Whitten Certification Number: 643R		Expiration Date: 1/11/1997					
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:							
PLM Bulk Samples							
(approx. 1,532 SF of beige 12x12 floor tile located in box lobby)							
VII. QUANTITY OF RACM TO BE REMOVED:							
Pipes (LN FT):	Surface Area (SQ FT):	ABOT THESE	Volume of Facility	Components (CU FT):			
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1,532 SF							
Category I: Category II: Floor Tile/Mastic							
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 1/23/2023 Complete: 1/24/2023							
x. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: N/A			Complete: N/A				

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:  Materials listed to be removed by hand so facility can be renovated.						
(approx. 1,532 SF of beige 12x12 floor tile located in box lobby)  XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE						
DEMOLITION OR RENOVATION SITE:						
Materials will be wetted, during and after abatement, properly packaged, labeled and transported to a certified Class 1 landfill for disposal.						
XIII. WASTE TRANSPORTER #1 Complete Environmental & Remediation Co. LLC						
Name: Complete Environmental & Remediation Co. LLC						
Address: 37 David Swan Lane						
City: Purvis	State: MS	Zip: 39475				
Contact Person: Kevin Ivy		<sub>Tel:</sub> 601-951-8136				
WASTE TRANSPORTER #2 N/A						
Name: N/A						
Address: N/A						
City: N/A	State: N/A	Zip: N/A				
Contact Person: N/A		Tel: N/A				
XIV. WASTE DISPOSAL SITE Little Dixie Landfill						
Name: Little Dixie Landfill						
Address: 1716 North County Line Road						
City: Jackson	State: MS	Zip: 39201				
Contact Person: N/A		Tel: 601-982-9488				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:						
Name: N/A	me: N/A Title: N/A					
Authority: N/A						
Date of Order (MM/DD/YY): N/A  Date Ordered to Begin (MM/DD/YY): N/A						
XVI. FOR EMERGENCY RENOVATIONS: N/A						
Date and Hour of Emergency (MM/DD/YY): N/A						
Description of the sudden unexpected event:						
N/A						
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:						
N/A						
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:						
Wet the unexpected, make area safe and notify DEQ.						
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.						
Barbara McElory	Barbara McClroy 1/6/2023					
Type or Print Name	(Signature of Owner/Operator)	0	(Date)			
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:  Barbara McClroy 31/6/2023						
Type or Print Name	(Signature of Owner/Operator)		(Date)			