MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: Mail Diland Delivery	Postmark (mail only)	Date Received 2-3-23 Al Number	
I. Type of Notification (O=Original R=Revise	d C=Canceled A= Annual): O	A-3 &3	
II. TYPE OF OPERATION (D=Demo O= Ord		Penavatian): R	
III. FACILITY DESCRIPTION (Include building			
Bldg. Name: Music Hall Bldg b	- marrier rander drid floor of footiff	idiliber).	
Address: 100 Presidnt Cir			
state: Miss state		Zip: 39762	
Site Location: MSU Campus	Oldin.	Tel: 601477 4263	
Building Size: 3,000	# of Floors: 1	Age in Years: > 20	
Present Use: Empty	Prior Use: MUS		
IV. FACILITY INFORMATION (Identify owner,			
OWNER NAME: Mississippi State Ur	niversity	uner operator)	
Address: PO Box 5208			
City: Miss state	MO		
Contact: Nick Dodd	State: MS	Zip: 39762	
SBESTOS REMOVAL CONTRACTOR: Envoironmental Services		Tel: 662 325 1858	
ASBESTOS REMOVAL CONTRACTOR: LITE Address: 253 Delk Road	7011011111e11tal Services	a de la companya de	
City: Hattiesburg	1 110		
Contact: Joe venus	State: MS	Zip: 39401	
		Tel: 6014081005	
ertification Number: 0001330		Expiration Date: Jan 3 202# 4	
OTHER OPERATOR: N/A			
Address:			
State:		Zip:	
Contact;		Tel:	
. WAS SITE INSPECTED TO DETERMINE PE	RESENCE OF ASBESTOS? (Yes/N	yes, assumed	
VAS ASBESTOS PRESENT? (Yes/No): Yes		Inspection Date: 1/22/23	
I. SUSPECT MATERIALS SAMPLED AND PE	Certification Number: 00001353 Expiration Date: Feb 10, 2023 MPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:		
sbestos floor tile and black mas	stic, assumed analysis	HE PRESENCE OF ASBESTOS MATERIAL:	
II. QUANTITY OF RACM TO BE REMOVED:	1,400		
pes (LN FT):	urface Area (SQ FT):	Volume of Facility Components (CU FT):	
II. QUANTITY OF NONFRIABLE ASBESTOS	NOT REMOVED:	P	
II. QUANTITY OF NONFRIABLE ASBESTOS	Cate	egory II: Complete: 2/17/23	

XI RESCRIPTION OF PLANNED DEMOLITION OF PENOV	ATION HOUSE AND				
XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOV. N/A (dont know owner didnt know)	ATION WORK, AND	METHOD(S) TO BE USED:			
YIL DESCRIPTION OF MODE PRACTICES AND ENGINEER					
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEER DEMOLITION OR RENOVATION SITE:		BE USED TO PREVENT EMIS	SIONS OF ASBESTOS AT THE		
Wet material and remove by hand using ha	and tools				
XIII. WASTE TRANSPORTER #1		• 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Name: Environmental Services					
Address: 253 Delk Road					
_{City:} Hattiesburg	State: MS	Zip: 39401			
Contact Person: jOE			Tel: 6014081005		
WASTE TRANSPORTER #2					
Name:N/A					
Address:					
City:	State:	Zip:	Zip:		
Contact Person:		Tel:			
XIV. WASTE DISPOSAL SITE					
Name: Robo landfill					
Address: 6447 Walalask Rd					
city: Scobba	State: MS	Zip. 39358			
Contact Person: Roland		Tel: 662 361 03	00		
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENC	CY, PLEASE IDENTIF	Y THE AGENCY BELOW:			
Name: N/A		Title:			
Authority:					
ate of Order (MM/DD/YY): Date Ordered to Begin (MM/DD/YY):					
XVI. FOR EMERGENCY RENOVATIONS:					
Date and Hour of Emergency (MM/DD/YY):					
Description of the sudden unexpected event:					
Explanation of how the event caused unsafe conditions or would	cause equipment dar	nage or an unreasonable financ	ial burden:		
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLEI	N THE EVENT THAT	UNEXPECTED ASBESTOS IS	FOUND OR PREVIOUSLY		
Stop work call DEQ	J, FULVERIZED, OR	KEDUCED 10 POWDEK:			
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PRO ONSITE DURING THE DEMOLITION OR RENOVATION, AND THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURI	EVIDENCE THAT TH	F RECHIRED TRAINING USE	1, SUBPART M) WILL BE BEEN ACCOMPLISHED BY		
Joe Venus	`	2/3//23			
Type or Print Name	(Signature of Owner/Ope				
XIX: I CERTIFY THAT THE ABOVE INFORMATION IS CORRECTION IS CORRECTION OF THE ABOVE INFORMATION IS CORRECTION.	CT:		2/3/23		
Type or Print Name	(Signature of Ovmer/Operator)		(Date)		