

FEB 10 2023



Rev
MAP

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

FOR AN ENVIRONMENTAL QUALITY

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input type="checkbox"/> Email <input checked="" type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only) 2-8-23	Date Received 2-10-23	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): REVISED (Sections: VIII, IX Dates)				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: Building 4331, Allee Hall				
Address: Corner of H Street and Fischer Street				
City: Keesler Air Force Base		State: MS	Zip: 39534	
Site Location: Building 4331, Allee Hall			Tel: (228)481-4874	
Building Size: approximately 50,000 sq ft		# of Floors: 2	Age in Years: 40+	
Present Use: Educational Building		Prior Use: Educational Building		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Keesler Air Force Base				
Address: 508 L Street				
City: Keesler AFB		State: MS	Zip: 39534	
Contact: Robin Sykes			Tel: (228)337-4504	
ASBESTOS REMOVAL CONTRACTOR: Global Contracting, LLC				
Address: 226 Harry Sones Road				
City: Carriere		State: MS	Zip: 39426	
Contact: Eddie Blossman			Tel: (601)795-3401	
Certification Number: ABC-00001162		Expiration Date: January 9, 2024		
OTHER OPERATOR: Gulf Pacific Contracting				
Address: 750 Sand Path Road				
City: Bonifay		State: Florida	Zip: 32425-7426	
Contact: Jason Howell			Tel: (850)527-6038	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No):				
WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspection Date: 01/04/2022	
Inspector: Charles D. Bingham		Certification Number: ABI-00001348	Expiration Date: 02/10/2023	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: HVAC Duct Insulation and Insulation Mastic. Thermal Systems Pipe Insulation.				
VII. QUANTITY OF RACM TO BE REMOVED: Approximately 3500 Ln Feet				
Pipes (LN FT):		Surface Area (SQ FT): 3500	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:			Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 01/30/2023			Complete: 04/30/2023	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 01/30/2023			Complete: 04/30/2023	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED: Removal of Black HVAC Duct Mastic.		
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: Negative Pressure Containment, Wet Removal Methods, Air Monitoring, and Final Clearance Sampling		
XIII. WASTE TRANSPORTER #1		
Name: Global Contracting, LLC		
Address: 226 Harry Sones Road		
City: Carriere	State: MS	Zip: 39426
Contact Person: Eddie Blossman	Tel: (601)795-3401	
WASTE TRANSPORTER #2		
Name:		
Address:		
City:	State:	Zip:
Contact Person:	Tel:	
XIV. WASTE DISPOSAL SITE		
Name: Waste Management Pecan Grove Landfill		
Address: 9685 Firetower Road		
City: Pass Christian	State: MS	Zip: 39571
Contact Person: Michael Eidt	Tel: (662)448-0773	
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:		
Name:	Title:	
Authority:		
Date of Order (MM/DD/YY):	Date Ordered to Begin (MM/DD/YY):	
XVI. FOR EMERGENCY RENOVATIONS:		
Date and Hour of Emergency (MM/DD/YY):		
Description of the sudden unexpected event:		
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:		
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER: Stop work immediately, contact regulatory authorities wait for approval of resume work.		
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.		
Eddie Blossman		02/07/2023
Type or Print Name	(Signature of Owner/Operator)	(Date)
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:		
Eddie Blossman		02/07/2023
Type or Print Name	(Signature of Owner/Operator)	(Date)