

# MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 2-10-23	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): R=Revised				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D=Demo				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: Georgia Pacific Monticello, LLC				
Address: 604 N A Sandifer Hwy				
City: Monticello		State: MS	Zip: 39654	
Site Location: Pulp Mill Ground Floor/Water Reservoir Tank			Tel: 601-455-1731	
Building Size: 13,500		# of Floors: 1	Age in Years: 40	
Present Use: Industrial		Prior Use: Industrial		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Georgia Pacific Monticello, LLC				
Address: 604 N.A. Sandifer Hwy				
City: Monticello		State: MS	Zip: 39654	
Contact: Heather Jackson			Tel: 601-455-1731	
ASBESTOS REMOVAL CONTRACTOR: The Winter Construction Company				
Address: 3350 Green Pointe Parkway Ste. 200				
City: Norcross		State: GA	Zip: 30092	
Contact: Andrew Holtzapfel			Tel: 404-965-2337	
Certification Number: ABC-00001560			Expiration Date: 04/11/2023	
OTHER OPERATOR: Independence Excavating, Inc.				
Address: 5720 E. Schaaf Road				
City: Independence		State: OH	Zip: 44131	
Contact: Colleen Loredo			Tel: 216-276-3014	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes				
WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspection Date: 12/14/2022	
Inspector: Stephen Knerr		Certification Number: ABI-00011679	Expiration Date: 9/1/2023	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Black Tank Coating, Gaskets - PLM Bulk Samples				
VII. QUANTITY OF RACM TO BE REMOVED:				
Pipes (LN FT):	Surface Area (SQ FT): 33000		Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:			Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 02/20/2023 Complete: 06/09/2023				
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 02/20/2023 Complete: 06/09/2023				

**XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:**

Demolition of tanks and equipment from the plant. Tanks that have black tank coating, the asbestos abatement contractor will remove the coating by wet hand removal methods on the proposed cut lines of the tanks. Remaining coating will be encapsulated. The tanks will be cut where the asbestos was removed into manageable pieces and will be loaded into a double lined container for proper disposal at an asbestos permitted landfill. The entire tanks with asbestos coating will be disposed of at the permitted landfill as asbestos containing material.

**XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:**

Regulate area, trained and MS accredited supervisor/workers, PPE, wet hand removal methods, intact removal methods

**XIII. WASTE TRANSPORTER #1**

Name: Delta Waste Solutions

Address: 5 River Bend Place

City: Flowood

State: MS

Zip: 39232

Contact Person: Raymond Lightfoot

Tel: 502-803-1733

**WASTE TRANSPORTER #2**

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

**XIV. WASTE DISPOSAL SITE**

Name: Republic Services - Little Dixie Landfill

Address: 1716 N County Line Road

City: Ridgeland

State: MS

Zip: 39157

Contact Person: Raymond Lightfoot

Tel: 502-803-1733

**XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:**

Name: NA

Title: NA

Authority: NA

Date of Order (MM/DD/YY): NA

Date Ordered to Begin (MM/DD/YY): NA

**XVI. FOR EMERGENCY RENOVATIONS: NA**

Date and Hour of Emergency (MM/DD/YY): NA

Description of the sudden unexpected event:

NA

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:


NA

**XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:**

Wet material, regulate area, notify owner & MDEQ

**XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.**

Andrew Holtzapfel  
Type or Print Name

  
(Signature of Owner/Operator)

2/10/2023  
(Date)

**XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT**

Heather Owens  
Type or Print Name

  
(Signature of Owner/Operator)

2/10/2023  
(Date)