

## MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

Type of Notification (O=Original R=Revised C=Canceled A= Annual): Revision #1  I. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation  II. FACILITY DESCRIPTION (Include building name, number and floor or room number): University of Mississippi  Bidg. Name: Shoemaker Hall Lab 331 & 329B  Address: 30 University Ave  City: University  State: MS  Zip: 38677  Tel: 901-239-3710  Building Size: Unknown  # of Floors:  Age in Years: 50 +/-	Mail notification to: Mid		**************************************			Al Number	
L TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation, Encourt DESCRIPTION (Include building name, number and floor or room number). University of Mississippi side, Name; Shoemaker Hall Lab 331 & 3298  Address, 30 University V State, MS Zp; 38677  Tel; 901-239-3710  Building Sizer, Unknown # of Floors: Age in years; 50 +/-  Present Use Classroom Building Prior Use; Classroom Bldg  N. FACILITY INFORMATION (Identify cursur, sebestor removal contractor, and other operator)  OWNER NAME, MS Bureau of Building Grounds and Real Property Mgmt  Address; 501 North West St  City, Jackson State; MS Zp; 39201  Contact: Ueff Witt Tal: 901-239-3710  ASBESTOS REMOVAL CONTRACTOR; Specialty Abatement Services, Inc.  Address; P.O. Box 343012  City, Memphis State; TN Zip; 38184-3012  Total: 901-507-1203  Contact: Dwight Grayson Tal: 901-239-2025  OTHER OPERATOR; In/a  Address: City  VMAS STEINSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No); Yes  VMAS ASBESTOS PRESENT? (Yes/No); Yes  VMAS STEINSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No); Yes  VMAS ASBESTOS PRESENT? (Yes/No); Yes  VMAS			Postmark (mail only)			37503	
L TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation, Encourt DESCRIPTION (Include building name, number and floor or room number). University of Mississippi side, Name; Shoemaker Hall Lab 331 & 3298  Address, 30 University V State, MS Zp; 38677  Tel; 901-239-3710  Building Sizer, Unknown # of Floors: Age in years; 50 +/-  Present Use Classroom Building Prior Use; Classroom Bldg  N. FACILITY INFORMATION (Identify cursur, sebestor removal contractor, and other operator)  OWNER NAME, MS Bureau of Building Grounds and Real Property Mgmt  Address; 501 North West St  City, Jackson State; MS Zp; 39201  Contact: Ueff Witt Tal: 901-239-3710  ASBESTOS REMOVAL CONTRACTOR; Specialty Abatement Services, Inc.  Address; P.O. Box 343012  City, Memphis State; TN Zip; 38184-3012  Total: 901-507-1203  Contact: Dwight Grayson Tal: 901-239-2025  OTHER OPERATOR; In/a  Address: City  VMAS STEINSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No); Yes  VMAS ASBESTOS PRESENT? (Yes/No); Yes  VMAS STEINSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No); Yes  VMAS ASBESTOS PRESENT? (Yes/No); Yes  VMAS	I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Revision #1						
II. FACILITY DESCRIPTION (include building name, number and floor or room number): University of Mississisphi  Address: 30 University Ave    Including store   State   MS   Zig: 38677	IL TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation						
State   Stat	III. FACILITY DESCRIPTION (Include building name, number and floor or room number): UNIVERSITY OF MISSISSIPPI						
State: MS   Zip: 38677   Tel: 901-239-3710   State: MS   Zip: 38677   Tel: 901-239-3710   State: MS   Zip: 39-2710   Age in Years: 50 +/- Age in Years: 50	Bldg. Name: Shoemaker Hall Lab 3	31 & 329B					
Site Location: Interior Classrooms (2)  Building Size: Unknown  # of Floors: Age in Years: 50 +/-  Building Size: Unknown  # of Floors: Age in Years: 50 +/-  Building Size: Unknown  # of Floors: Age in Years: 50 +/-  Building Size: Unknown  # of Floors: Age in Years: 50 +/-  Building Size: Unknown  # of Floors: Age in Years: 50 +/-  Building Size: Unknown  # of Floors: Age in Years: 50 +/-  Building Size: Unknown  # of Floors: Age in Years: 50 +/-  Building Size: Unknown  # of Floors: Age in Years: 50 +/-  Building Size: Unknown  # of Floors: Age in Years: 50 +/-  # Building Size: Unknown  # Of Floors: Age in Years: 50 +/-  # Age in Years: 50 +/-	Address: 30 University Ave						
# of Floors: Age in Years: 50 +/- # of F	<sub>City:</sub> University		State: MS				
Present Use: Classroom Building Prior Use: Classroom Bldg  M. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)  OWNER NAME: MS Bureau of Building Grounds and Real Property Mgmt  Address, 501 North West St  City: Jackson State: MS Zip: 39201  Tol: 901-239-3710  Contact: Jeff Witt Tol: 901-239-3710  ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.  Address; P.O. Box 343012  City: Memphis State: TN Zip: 38184-3012  City: Memphis State: TN Zip: 38184-3012  Contact: Dwight Grayson Tol: 901-507-1203  Certification Number: ABC0001660  City: State: Zip:  Contact: V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  Unspector: Lamar Gillilland Certification Number: ABI-00001036 Expiration Date: 02/207/2025  VI. Suspect MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): N/a Surface Area (SQ FT): 1700 sf Volume of Facility Components (CU FT): N/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: N/a  VIII. QUANTITY of NonFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: N/a  VIII. SCHEDULED DATES ASBESTOS REMOVAL (MMMDDYYY) Start: 05/01//24  Complete: 05/03/2024	Site Location: Interior Classrooms (						
IN. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)  OWNER NAME: MS Bureau of Building Grounds and Real Property Mgmt  Address: 501 North West St  City: Jackson State: MS Zip: 39201  Contact: Jeff Witt Tal: 901-239-3710  ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.  Address: P.O. Box 343012  City: Memphis State: TN Zip: 38184-3012  Contact: Dwight Grayson Tal: 901-507-1203  Certification Number: ABC0001660 Expiration Date: 02/23/2025  OTHER OPERATOR: n/a  Address:  City: State: Zip:  Contact: V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No); Yes  WAS ASBESTOS PRESENT? (Yes/No); Yes  Unspector Lamar Gillilland Certification Number: ABI-00001036 Expiration Date: 09/26/2023  VI. Suspect MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Plipes (LN FT): n/a Surface Area (SO FT): 1700 sf Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: 1 sink, 1 fumehood  K. SCHEDULED DATES ASBESTOS REMOVAL (MMMDD/YY) Start: 05/01/24  Complete: 05/03/2024							
OWNER NAME. MS Bureau of Building Grounds and Real Property Mgmt  Address, 501 North West St  City. Jackson State: MS Zip: 39201  Tel: 901-239-3710  ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.  Address: P. O. Box 343012  City: Memphis State: TN Zip: 38184-3012  Contact: Dwight Grayson Certification Number: ABC0001660 Expiration Date: 02/23/2025  OTHER OPERATOR: n/a  Address: City: State: Zip:  V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Unspector Lamar Gilliland Certification Number: ABI-00001036 Expiration Date: 02/207/2025  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipas (LN FT): n/a Surface Area (SQ FT): 1700 sf Volume of Facility Components (CU FT): n/a  WIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: 1 sink, 1 fumehood  X. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024	Present Use: Classroom Building		Prior Use: Classroom Bldg				
Address: 501 North West St  City: Jackson  Contact: Jeff Witt  ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.  Address: P.O. Box 343012  City: Memphis  State: TN  Zip: 38184-3012  Tel: 901-507-1203  Contact: Dwight Grayson  Certification Number: ABC0001660  Expiration Date: 02/23/2025  OTHER OPERATOR: n/a  Address:  City:  State:  Zip:  Contact:  V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Unspector, Lamar Gilliland  Certification Number: ABI-0000136  Expiration Date: 09/26/2023  Inspector, Lamar Gilliland  Certification Number: ABI-00001036  Expiration Date: 02/07/2025  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category II: 1 sink, 1 fumehood  K. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024							
Address: 501 North West St  City: Jackson  Contact: Jeff Witt  ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.  Address: P.O. Box 343012  City: Memphis  State: TN  Zip: 38184-3012  Tel: 901-507-1203  Contact: Dwight Grayson  Certification Number: ABC0001660  Expiration Date: 02/23/2025  OTHER OPERATOR: n/a  Address:  City:  State:  Zip:  Contact:  V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Unspector, Lamar Gilliland  Certification Number: ABI-0000136  Expiration Date: 09/26/2023  Inspector, Lamar Gilliland  Certification Number: ABI-00001036  Expiration Date: 02/07/2025  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category II: 1 sink, 1 fumehood  K. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024							
City: Jackson  Contact: Jeff Witt  Contact: Jeff Witt  ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.  Address: P.O. Box 343012  City: Memphis  Contact: Dwight Grayson  Certification Number: ABC0001660  Certification Number: ABC0001660  Contact: Dwight Grayson  Certification Number: ABC0001660  Contact: Dwight Grayson  Certification Number: ABC0001660  Contact: Date: 02/23/2025  City: State: Zip:  Contact: Tel: V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  U. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Furme Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: 1 sink, 1 fumehood  K, SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024							
Contact: Jeff Witt  ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.  Address: P.O. Box 343012  City: Memphis  Contact: Dwight Grayson  Certification Number: ABC0001660  Certification Number: ABC0001660  Contact: Dwight Grayson  Certification Number: ABC0001660  Certification Number: ABC0001660  Contact:  V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Inspection Date: 09/26/2023  Inspector: Lamar Gillilland  Certification Number: ABI-00001036  Expiration Date: 09/26/2025  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: 1 sink, 1 fumehood  K. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024			State: MS		<sub>Zip:</sub> 39201		
ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.  Address: P.O. Box 343012  City: Memphis	Contact: Jeff Witt				Tel: 901-239-3710		
Address: P.O. Box 343012  Contact: Dwight Grayson  Certification Number: ABC0001660  Certification Number: ABC0001660  Contact: Dwight Grayson  Certification Number: ABC0001660  Contact: Dwight Grayson  Certification Number: ABC0001660  Contact: Zip:  Contact: Tel:  V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Illiand Certification Number: ABI-00001036 Expiration Date: 02/07/2025  W. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a Surface Area (SQ FT): 1700 sf Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  Long Contact: The Presence of Asbestos Removal (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024	ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.						
City: Memphis  Contact: Dwight Grayson  Certification Number: ABC0001660  Certification Number: ABC0001660  Contact:  City:  Contact:  V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  Inspector: MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Viii. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  Lategory I: n/a  Lategory I: n/a  Complete: 05/03/2024	Address: P.O. Box 343012						
Contact: Dwight Grayson  Certification Number: ABC0001660  Certification Number: ABC0001660  Cother Operator: n/a  Address:  City:  Contact:  V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  LX, SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024				State: TN			
Certification Number: ABC0001660  OTHER OPERATOR: n/a  Address:  City:  Contact:  V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category II: n/a  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024			Tel: 901-507-1203		203		
Address:  City:  Contact:  V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  Expiration Date: 02/07/2025  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category II: 1 sink, 1 fumehood  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024		Expiration Date: 02/23/2025		25			
Address:  City:  Contact:  V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Inspection Date: 09/26/2023  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  Expiration Date: 02/07/2025  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category II: 1 sink, 1 fumehood  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024	Octuned on Admission						
Contact:  V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Inspection Date: 09/26/2023  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  Inspector: Lamar Gilliland  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category II: 1 sink, 1 fumehood  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024							
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  LX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024			State:		Zip:		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes  WAS ASBESTOS PRESENT? (Yes/No): Yes  Inspection Date: 09/26/2023  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024				Tel:			
Inspection Date: U9/26/2023  Inspector: Lamar Gilliland  Certification Number: ABI-00001036  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024	V WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes						
VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  Lxpiration Date: 02/07/2025  Expiration Date: 02/07/2025	WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspect	Inspection Date: U9/26/2023		
VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Pipes (IN FT): 05 ASBESTOS NATERIAL: PRESENCE OF ASBESTOS NATERIAL: PRESENCE OF ASBESTOS NATERIAL: PRESENCE OF ASBESTOS NATERIAL:  Plaster, Sink Soundproofing, Pipe Insulation, Fume Hood, Flooring  Bulk sampling using PLM methods  VIII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Volume of Facility Components (CU FT): n/a  Category II: 1 sink, 1 fumehood  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024	Lamar Gilliland Cortification Number: ABI-00001036 Expiration Date: 02/07/2025						
Bulk sampling using PLM methods  VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024	VI SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL.						
VII. QUANTITY OF RACM TO BE REMOVED: 850 sqft VAT, 850 sqft Mastic  Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024	Bulk sampling using PLM methods						
Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  Category I: 1 sink, 1 fumehood  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024	Bain samping asing						
Pipes (LN FT): n/a  Surface Area (SQ FT): 1700 sf  Volume of Facility Components (CU FT): n/a  VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: n/a  Category I: 1 sink, 1 fumehood  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024		ED.		<i>.</i>			
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood  Category I: 1 sink, 1 fumehood  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024							
Category I: 1 SINK, 1 tumenood  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024	Pipes (LN FT): n/a Surface Area (SQ FT): 1700 sf Volume of Facility Components (CU FT): n/a						
Category I: 1 SINK, 1 tumenood  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 05/01/24  Complete: 05/03/2024	VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 1 Sink, 1 Transite lined fumehood						
IX. SCHEDOLLD DATED ADDEDTED HERE	Category I: n/a	ategory I: n/a Category II: 1 SINK, 1 tumenood					
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 05/01/24 Complete: 05/03/2024	IX. SCHEDULED DATES ASBESTOS REF	IA. SCHEDOLLD DATED ADDEDTED KEINSTILL (MILES					
	X. SCHEDULED DATES DEMO/RENOVA	<sub>e:</sub> U5/U3/ZUZ4					

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:						
Removal of ACM using hand tools and well	methods					
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING DEMOLITION OR RENOVATION SITE:  Containment, negative pressure, hand tool						
Containment, negative pressure, nand tool	-,	-				
XIII. WASTE TRANSPORTER #1 SASI	-					
Name: SASI Memphis						
Address: 4009 Broadway Rd						
<sub>City:</sub> Bartlett	State: TN	<sub>Zip:</sub> 38135				
Contact Person: Dwight Grayson		Tel: 901-507-1203				
WASTE TRANSPORTER #2 Waste Management Men	nphis					
Name: Waste Management Memphis						
Address: 3750 Hatcher Circle						
City: Memphis	State: TN	Zip: 38118				
Contact Person: Carlton Gibson		<sub>Tel:</sub> 901-331-7187				
XIV. WASTE DISPOSAL SITE WM The Tunica Landfill						
Name: WM The Tunica Landfill						
Address: 6035 Bowdre Rd						
City: Robinsonville	State: MS	Zip:				
Contact Person: Carlton Gibson		<sub>Tel:</sub> 901-331-7187				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGE	NCY, PLEASE IDENT	IFY THE AGENCY BELOW:				
Name: n/a						
Authority: n/a						
Date of Order (MM/DD/YY): n/a						
XVI. FOR EMERGENCY RENOVATIONS: n/a						
Date and Hour of Emergency (MM/DD/YY): n/a						
Description of the sudden unexpected event:						
n/a		the figure of the state of				
Explanation of how the event caused unsafe conditions or wo	ould cause equipment	damage or an unreasonable financial burden:				
n/a		TO THE PROPERTY OF THE PROPERT				
NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMB	LED, PULVERIZED, 1	AT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY OR REDUCED TO POWDER:				
All work will cease, workers will be removed from site, MDEQ will be called for an inspection						
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE ONSITE DURING THE DEMOLITION OR RENOVATION, A THIS PERSON WILL BE AVAILABLE FOR INSPECTION D	NII EVIDENCE ITAL	S REGULATION (40 CFR PART 61, SUBPART M) WILL BE THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY SINESS HOURS.				
Dwight Grayson	119 NO	04/16/2024				
Type or Print Name	Signature of Owner	Øperator) (Date)				
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS COI William Stamps						
Type or Print Name	(Signature of Owne	r/Operator) (Date)				