

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 10/28/2024	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Revised - Revision #1				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Northwest MS Community College				
Bldg. Name: RC Pugh Library				
Address: 104 Porter St				
City: Senatobia		State: MS	Zip: 38668	
Site Location: Office Spaces/Restrooms, Above Ceiling & Exterior Wdws			Tel: 662-562-3278	
Building Size: 16,030 SF		# of Floors: 1	Age in Years: 70 +/-	
Present Use: Library vacant for renovation		Prior Use: Library		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Bureau of building grounds and real property management				
Address: 501 North west St., Ste 1401 B				
City: Jackson		State: MS	Zip: 39201	
Contact: J. Heath Ferry			Tel: 228-594-2323	
ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.				
Address: P.O. Box 343012				
City: Memphis		State: TN	Zip: 38184-3012	
Contact: William Stamps			Tel: 901-507-1203	
Certification Number: ABC00001660			Expiration Date: 02/23/2025	
OTHER OPERATOR: n/a				
Address:				
City:		State:	Zip:	
Contact:			Tel:	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes				
WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspection Date: 05/25/2023	
Inspector: Jody E Browder		Certification Number: ABI-00007508	Expiration Date: 09/14/23 9/24/2025	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Bulk Sampling PLM Methods: Floor tile & Mastic, Window Caulk, pipe insulation and mudded fittings, roofing, flashing, carpet glue, cove base, drywall, ceiling tiles, leveling compound				
VII. QUANTITY OF RACM TO BE REMOVED: VAT/Mastic 5800 sf, Pipe Joints 30 each				
Pipes (LN FT): 30 LF		Surface Area (SQ FT): 5800/5800 sf, 60ea	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: TO BE REMOVED, Windows 60 each				
Category I: n/a			Category II: Window Frame with Caulk 60 each	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 11/11/2024			Complete: 11/15/2024	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 11/11/2024			Complete: 11/30/2024	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:
Removal of ACM using hand tools and wet methods, Removal of windows intact

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:
Drop Cloths, double bag/wrap waste, hand tools wet methods, hepa vac

XIII. WASTE TRANSPORTER #1 SASI

Name: SASI Memphis

Address: 4009 Broadway Rd

City: Bartlett

State: TN

Zip: 38135

Contact Person: Dwight Grayson

Tel: 901-507-1203

WASTE TRANSPORTER #2 L&T Services, LLC

Name: L&T Services, LLC

Address: P.O. Box 328

City: Hernando

State: MS

Zip: 38632

Contact Person: Carlton Gibson

Tel: 901-331-7187

XIV. WASTE DISPOSAL SITE WM The Tunica Landfill

Name: WM The Tunica Landfill

Address: 6035 Bowdre Rd

City: Robinsonville

State: MS

Zip: 38664

Contact Person: Sandy Pickle

Tel: 662-363-2282

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: n/a

Title:

Authority: n/a

Date of Order (MM/DD/YY): n/a

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: n/a

Date and Hour of Emergency (MM/DD/YY): n/a

Description of the sudden unexpected event:

n/a

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

n/a


XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

All work will cease, workers will be removed from site, MDEQ will be called for an inspection

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

William Stamps

Type or Print Name


(Signature of Owner/Operator)


10/29/24

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Dwight Grayson

Type or Print Name


(Signature of Owner/Operator)

10/29/24

(Date)