## MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ★Email □Mail □Hand Delivery	Postmark (mail only)		Date Received 2/13/2025		Al Number			
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): R								
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R								
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):								
Bldg. Name: Dugan Home								
Address: 26894 E Main Street								
City: West Point		State: MS		Zip: 39773				
Site Location: Hallway & Activity Room				Tel: 662-494-3640				
Building Size: 12,000 S.F.		# of Floors: 1		Age in Years: Over 25				
Present Use: Nursing Home	Prior Use: Same							
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)								
OWNER NAME: Methodist Senior Services								
Address: P.O. Box 1567								
Dity: Tupelo		State: MS		<sub>Zip:</sub> 38802				
Contact: Mr.Tim Barber				<sub>Tel:</sub> 662-844-8977				
ASBESTOS REMOVAL CONTRACTOR: Environmental Evaluation & Control, Inc.								
Address: P.O. Box 5422								
		State: MS		Zip: 39704				
Contact: Ron Robinson			<sub>Tel:</sub> 662-328-2286					
Certification Number: ABC-00007293	Expiration Date		on Date: 03-22-25	ate: 03-22-25				
OTHER OPERATOR: FL Crane & Sons								
Address: 508 South Spring Street								
<sub>City:</sub> Fulton		State: MS		Zip: 38843				
Contact: John Crane				Tel: 662-322-7091				
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes								
WAS ASBESTOS PRESENT? (Yes/No): Yes Inspection			on Date: 02-05-25					
Inspector: Ron Robinson Certification Number: ABI-00001499 Expiration Date: 02-12-25								
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  12" x 12" Floor Tile & Floor Tile Black Mastic								
12 X 12 FIOOL FITE & FIOOL FITE BLACK WASHE								
Environmental Hazard Services, PLM Method								
VII. QUANTITY OF RACM TO BE REMOVED: 3140 S.F. 12" x 12" Floor Tile & Black Mastic								
Pipes (LN FT):	Surface Area (S			Volume of Facility Cor	nponents (CU FT):			
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:								
Category I: Category II:								
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 02-26-25 Complete: 03-01-25								
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 03-03-25 Complete: 03-17-25								

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:							
Removal of asbestos containing materials using wet method.							
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERS DEMOLITION OR RENOVATION SITE:	NG CONTROLS	TO BE USE	TO PREVENT EMISSIONS OF ASBESTOS AT THE				
Strip & Removal, Wet Method, Double Bagging							
XIII. WASTE TRANSPORTER #1							
Name: Waste Pro							
Address: 1600 12th Avenue South							
<sub>City:</sub> Columbus	State: MS		Zip: 39701				
Contact Person: Julie Goodwin			<sub>Tel:</sub> 662-328-5528				
WASTE TRANSPORTER #2							
Name: N/A							
Address:							
City:	State:		Zíp:				
Contact Person:			Tel:				
XIV. WASTE DISPOSAL SITE							
Name: Kemper County Landfill Company, LLC							
Address: 21211 Hwy 16 East							
City: De Kalb	State: MS		<sub>Zip:</sub> 39328				
Contact Person: Jeff Papasan			Tel: 601-743-4310				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:							
Name: N/A	Title:						
Authority:							
Date of Order (MM/DD/YY):	Date Ordered to Begin (MM/DD/YY):						
XVI. FOR EMERGENCY RENOVATIONS:							
Date and Hour of Emergency (MM/DD/YY):							
Description of the sudden unexpected event:							
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:							
TO WE DESCRIPTION OF THE PROPERTY OF THE PROPE		THE HALLYD	FOTED ACRESTOS IS FOLIND OR PREVIOUSLY				
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:							
Contain & seal off work area, wet materials, utilize negative air (HEPA filtered) equipment as							
necessary. Seal asbestos in bags.							
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.							
Ron Robinson	KON K	SULUDA	02-13-25				
Type or Print Name	(Signature of Ow	` .	(Date)				
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRE	IS CORRECT: for lateral 02-13-25						
Type or Print Name	(Signature of Owner/Operator)		(Date)				