

# MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: **MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201**

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received <b>2/20/2025</b>	AI Number <b>30829</b>
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual) <b>Original</b>				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation) <b>Renovations</b>				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number)				
Bldg. Name: <b>Blake Gym, Building 1201</b>				
Address <b>1201 H Streetr</b>				
City: <b>Keesler Air Force Base</b>	State: <b>MS</b>	Zip: <b>39534</b>	County: <b>Harrison</b>	
Site Location: <b>Blake Gym, Building 1201, 1st and 2nd Floor</b>			Tel: <b>(228)377-2907</b>	
Building Size <b>29,723 sq ft</b>	# of Floors: <b>2</b>	Age in Years: <b>40+</b>		
Present Use: <b>Athletic Gym</b>	Prior Use: <b>Athletic Gym</b>			
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: <b>Keesler Air Force Base</b>				
Address: <b>606 Chappie James Boulevard</b>				
City: <b>Keesler AFB</b>	State: <b>MS</b>	Zip: <b>39534</b>		
Contact: <b>Atlas Thomas</b>	Tel: <b>(228)377-2907</b>			
ASBESTOS REMOVAL CONTRACTOR: <b>Global Contracting, LLC</b>				
Address: <b>30 Zora Lane</b>				
City: <b>Poplarville</b>	State: <b>MS</b>	Zip: <b>39470</b>		
Contact: <b>Eddie Blossman</b>	Tel:			
Certification Number: <b>00001162</b>		Expiration Date: <b>12/27/2025</b>		
OTHER OPERATOR: <b>Reasor Building Group</b>				
Address: <b>7100 Plantation Road, Suite 11</b>				
City: <b>Pensacola</b>	State: <b>Florida</b>	Zip: <b>32504</b>		
Contact: <b>Jessica Mercer</b>	Tel: <b>(850)530-9097</b>			
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No):				
WAS ASBESTOS PRESENT? (Yes/No): <b>Yes</b>			Inspection Date:	
Inspector:	Certification Number:	Expiration Date:		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: <b>Owner assumes suspect materials are asbestos containing from past experience.</b>				
VII. QUANTITY OF RACM TO BE REMOVED: <b>310q ft floor tile/black mastic, 135sq ft of black and white duct insulation mastic</b>				
Pipes (LN FT): <b>30 In ft</b>	Surface Area (SQ FT): <b>445</b>	Volume of Facility Components (CU FT):		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:		Category II:		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: <b>03/06/2025</b>			Complete: <b>05/06/2025</b>	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: <b>03/06/2025</b>			Complete: <b>05/06/2025</b>	

**XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:**

Wet removal methods for the removal of the 310 sq ft of floor tile/black mastics, 135 sq ft of black and white HVAC duct insulation with mastic and 30 In ft transite pipe

**XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:**

Negative Pressure Containments, Wet Removal methods, Double bag materials on going air monitoring and final clearance testing.

**XIII. WASTE TRANSPORTER #1** Global Contracting, LLC

Name: Global Contracting, LLC

Address: 30 Zora Lane

City: Poplarville

State: MS

Zip: 39470

Contact Person: Eddie Blossman

Tel: (601)795-3401

**WASTE TRANSPORTER #2**

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

**XIV. WASTE DISPOSAL SITE**

Name: Waste Management-Pecan Grove Landfill

Address: 9685 Firetower Road

City: Pass Christian

State: MS

Zip: 39571

Contact Person: Michael Edit

Tel: (662)448-0773

**XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:**

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

**XVI. FOR EMERGENCY RENOVATIONS:**


Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

**XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:**

Cease work immediate, make proper notifications, wait for approval and direction before returning to work.

**XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.**EDDIE BLOSSMAN  
Type or Print Name  
(Signature of Owner/Operator)02/21/2025  
(Date)**XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:**EDDIE BLOSSMAN  
Type or Print Name  
(Signature of Owner/Operator)02/21/2025  
(Date)