


MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ☒ Email ☐ Mail ☐ Hand Delivery		Postmark (mail only)	Date Received: 3/20/2025	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): R				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: Residential House				
Address: 3521 EDWARDS AVE				
City: JACKSON	State: MS	Zip: 39213		
Site Location: Same as above			Tel:	
Building Size: 1,248	# of Floors: 1	Age in Years: 69		
Present Use: abandoned single family dwelling		Prior Use: single family dwelling		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: BROOME AVERY E				
Address: 2357 MALLORY DR				
City: Jackson	State: MS	Zip: 39213		
Contact: City of Jackson		Tel: 601-960-1054 or 601-960-1066		
ASBESTOS REMOVAL CONTRACTOR: Dennis Love				
Address: 6341 Ashley Drive				
City: JACKSON	State: MS	Zip: 39211		
Contact: Dennis Love		Tel: 601-940-6884		
Certification Number: ABC-0001930		Expiration Date: 8-15-25		
OTHER OPERATOR: Robert Love				
Address: 5822 Canton Park Dr.				
City: Jackson	State: MS	Zip: 39211		
Contact: Robert Love		Tel: 601-331-2828		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES		Inspection Date: 04/12/2024		
Inspector: Robert Brunson	Certification Number: ABI-00008315	Expiration Date: 10/25/2025		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: EPA 600/R-93-/116 BULK POLARIZED LIGHT MICROSCOPY (EMSL) SIDING, SIDING FELT, INSULATION(HOMO), FLOOR TITLE, SHEETROCK (HOMO), SHEETROCK (HOMO), SHINGLE, FELT				
VII. QUANTITY OF RACM TO BE REMOVED: N/A				
Pipes (LN FT): N/A	Surface Area (SQ FT): 385 Cu Ft	Volume of Facility Components (CU FT): 2000 CU CT		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I: N/A		Category II: N/A		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 4/2/2025		Complete: 4/5/2025		
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 4/8/2025		Complete: 4/16/2025		

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED: Demolish and remove remaining dilapidated house, trash, debris. Cut grass and weeds if needed.		
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: Wet Method and Intact.		
XIII. WASTE TRANSPORTER #1		
Name: Robert E. Love		
Address: 5822 Canton Park Dr.		
City: Jackson	State: MS	Zip: 39211
Contact Person: Robert Love		Tel: 601-331-2828
WASTE TRANSPORTER #2		
Name: N/A		
Address:		
City:	State:	Zip:
Contact Person:		Tel:
XIV. WASTE DISPOSAL SITE		
Name: Little Dixie Landfill		
Address: 1716 County Line Rd.		
City: Ridgeland	State: Ms.	Zip: 39157
Contact Person: Samatha		Tel: 601-982-9488
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:		
Name: Samatha		Title: MANAGER
Authority: City of Jackson		
Date of Order (MM/DD/YY): 4/5/2024		Date Ordered to Begin (MM/DD/YY):
XVI. FOR EMERGENCY RENOVATIONS: N/A		
Date and Hour of Emergency (MM/DD/YY): N/A		
Description of the sudden unexpected event:		
N/A		
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:		
N/A		
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER: Contain and seal off work area. Wet materials utilize negative air. Chela filtered equipment as necessary asbestos bags.		
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.		
Dennis Love		3/20/2025
Type or Print Name	(Signature of Owner/Operator)	(Date)
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:		
Robert Love		3/20/2025
Type or Print Name	(Signature of Owner/Operator)	(Date)

24041815



**Environmental
Analytical
Services, LLC**

13201 Northwest Freeway, Suite 520
Houston, Texas 77040
(713) 343-4017 Fax (713) 934-9942
www.easlabs.com, arthur@easlabs.com
facebook.com/easlabs

CHAIN OF CUSTODY

* Job ID: 24041815

Client Name / Address:

CITY OF JACKSON
200 S PRESIDENT ST
JACKSON, MS 39201

Bulk Sample Data

Project Name:

3521 EDWARDS AVE.



City of Jackson

Quantity / Analysis Requested:

8

Project Number:

CE-22-160

EAS PO Number: (if applicable)

Turnaround Time: ☐ 2 Hour ☐ 8 Hour ☐ 24 Hour
☐ 2 Day ☒ 3 Day ☐ 5 Day (Routine) ☐ Other: (Specify) _____

(Note: All turnaround times are based on the date / time the sample is received by the laboratory)

Contact: ROBERT BRUNSON

Phone: 601-960-1054

E-mail: rbrunson@jacksonms.gov / lgrant@city.jackson.ms.us

Special Instructions:

#	Location	Sample Description (or see attached description)
1	EXTERIOR WALL	SIDING
2	EXTERIOR WALL	SIDING FELT
3	KITCHEN CEILING	INSULATION (HOMO)
4	KITCHEN 10X12	FLOOR TILE
5	MASTER BEDROOM WALL 14X22	SHEETROCK (HOMO)
6	HALLWAY CEILING 5X16	SHEETROCK (HOMO)
7	ROOFING	SHINGLE
8	ROOFING	FELT
STRUCTURE APPROXIMATELY 50X40 TOO DANGEROUS TO ENTER REMAINS OF STRUCTURE		

Relinquished By:

Date/Time:

Robert Brunson
4/12/24

Accepted By:

Date/Time:

Ch 4/18/24 2920

Rev 10/12

Like us on **facebook**

Page / of /



Environmental
Analytical
Services, LLC

13201 Northwest Freeway, Suite 520
Houston, Texas 77040
phone 713-343-4017 | fax 713-934-9942
www.easlabs.com | facebook.com/easlabs | info@easlabs.com

**Test: EPA 600/R-93/116
Polarized Light Microscopy**

Client Information:

City of Jackson
200 S President St
Jackson, MS 39201
Phone: 601-960-1054
E-Mail: rbrunson@city.jackson.ms.us

Project:

3521 Edwards Ave.

CE-22-160

EAS Job: 24041815

Attn: Robert Brunson

Date Analyzed: 04/24/2024 05:03 PM

Date Received: 04/18/2024 09:20 AM

TAT Requested: 3 Days

Microscope: PLM Labomed LX
400P

Sample # Lab ID #	Layer	Sample Description	Asbestos Detected (Yes/No)	Asbestos Mineral Percent	Non-Asbestos Fibers	Non-Fibrous Material
1 24041815.01	A	Gray/Tan Fibrous Transite Siding Homogeneous	YES	Chrysotile 40%		Other Non-Fibrous 60%
2 24041815.02	A	Black Fibrous Felt Paper Homogeneous	NO	None Detected	Cellulose 60%	Adhesive 40%
3 24041815.03	A	Pink/Tan Fibrous Insulation Homogeneous	NO	None Detected	Fiberglass 100%	
4 24041815.04	A	Gray/Tan Vinyl Floor Tile Homogeneous	NO	None Detected		Vinyl 100%
4 24041815.04	B	Yellow/Clear Tar Mastic Homogeneous	NO	None Detected	Cellulose 2%	Adhesive 98%

NVLAP Lab Code: 200784-0

TDSHS License No. 300373

LDEQ LELAP Certificate No: 04161, Agency Interest No. 149571

Notes:

Some samples (floor tiles, surfacing, etc.) may contain fibers too small to be detectable by PLM. TEM/Chordfield analysis of bulk material is recommended in this case. All asbestos percentages are based on calibrated visual estimates traceable to NIST standards for regulated asbestos types. Analytical percentages fall within a range of acceptable percentages, depending on the actual concentration of asbestos. This test report relates only to the items tested. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. This report may not be reproduced except in full without permission from Environmental Analytical Services.

These results are submitted pursuant to EAS' current terms of sale, including the company's standard warranty and limitation of liability provisions and no responsibility or liability is assumed for the manner in which the results are used or interpreted. Unless notified in writing to return the samples covered by this report, EAS will store the samples for a period of ninety (90) days before discarding. Percentages reported are estimates and not absolute percent range values.

Analyzed By:

Arthur Hernandez

Approved Signatory:

Arthur Hernandez



**Environmental
Analytical
Services, LLC**

13201 Northwest Freeway, Suite 520
Houston, Texas 77040
phone 713-343-4017 | fax 713-934-9942
www.easlabs.com | facebook.com/easlabs | info@easlabs.com

**Test: EPA 600/R-93/116
Polarized Light Microscopy**

Client Information:

City of Jackson
200 S President St
Jackson, MS 39201
Phone: 601-960-1054
E-Mail: rbrunson@city.jackson.ms.us

Project:

3521 Edwards Ave.

CE-22-160

EAS Job: 24041815

Attn: Robert Brunson

Date Analyzed: 04/24/2024 05:03 PM

Date Received: 04/18/2024 09:20 AM

TAT Requested: 3 Days

Microscope: PLM Labomed LX
400P

Sample # Lab ID #	Layer	Sample Description	Asbestos Detected (Yes/No)	Asbestos Mineral Percent	Non-Asbestos Fibers	Non-Fibrous Material
5 24041815.05	A	Brown/White Fibrous Sheetrock Non-Homogeneous	NO	None Detected	Cellulose 30%	Gypsum 70%
6 24041815.06	A	White Fibrous Texture Homogeneous	NO	None Detected	Cellulose 2%	Binders / CaCO 98%
6 24041815.06	B	Brown/White Fibrous Sheetrock Non-Homogeneous	NO	None Detected	Cellulose 30%	Gypsum 70%
7 24041815.07	A	Black/Gray Fibrous Roofing Shingle Homogeneous	NO	None Detected	Cellulose 20% Fiberglass 20%	Asphaltic Matrix 60%
24041815.08	A	Black Fibrous Roofing Felt Paper Homogeneous	NO	None Detected	Cellulose 60%	Adhesive 40%

NVLAP Lab Code: 200784-0

TDSHS License No. 300373

LDEQ LELAP Certificate No: 04161, Agency Interest No. 149571

Notes:

Some samples (floor tiles, surfacing, etc.) may contain fibers too small to be detectable by PLM. TEM/Chamfield analysis of bulk material is recommended in this case. All asbestos percentages are based on calibrated visual estimates traceable to NIST standards for regulated asbestos types. Analysts' percentages fall within a range of acceptable percentages, depending on the actual concentration of asbestos. This test report relates only to the items tested. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. This report may not be reproduced except in full without permission from Environmental Analytical Services.

These results are submitted pursuant to EAS' current terms of sale, including the company's standard warranty and limitation of liability provisions and no responsibility or liability is assumed for the manner in which the results are used or interpreted. Unless notified in writing to return the samples covered by this report, EAS will store the samples for a period of ninety (90) days before discarding. Percent ranges reported are estimates and not absolute percent range values.

Analyzed By:

Arthur Hernandez

Approved Signatory:

Arthur Hernandez

