

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201 P1

MDEQ Use Only: ☒ Email ☐ Mail ☐ Hand Delivery		Postmark (mail only)	Date Received 5/14/2025	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):		O = original		
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):		D = Demo		
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: Butford SEALS GULF SERVICE STATION (B.E. SEALS ESTATE)				
Address: 56 CATCHINGS RD. 33.07431370687658, -90.79605695910388				
City: Rolling Fork	State: ms	Zip: 39159		
Site Location: 56 CATCHINGS RD., DELTA CITY, MS	Tel: 662-873-1511			
Building Size: 1400 SF	# of Floors: 1	Age in Years: 50 + -		
Present Use: VACANT	Prior Use: SMALL TOWN SERVICE STATION			
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Robert E. Stigall				
Address: 408 SANDY BAYOU RD.				
City: ANQUILLA	State: ms	Zip: 39159		
Contact: Robert E. Stigall	Tel: 662-873-1511			
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC.				
Address: P.O. BOX 133				
City: Delta City	State: ms	Zip: 39061		
Contact: Jimmy Bell	Tel: 662-820-2124			
Certification Number: ABC-00001282	Expiration Date: 12/15/25			
OTHER OPERATOR: H B Trucking Services				
Address: P.O. BOX 205				
City: DELTA CITY	State: ms	Zip: 39061		
Contact: HERBERT BELL JR.	Tel: 662-873-3606			
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): (yes) Complete Inspection				
WAS ASBESTOS PRESENT? (Yes/No): yes		Inspection Date: 5/6/25		
Inspector: PAUL ANDERSON	Certification Number: ABT-00001686	Expiration Date: 5/31/25		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: SAMPLES WERE TAKEN FROM: INSULATION BEHIND WALLS, SHINGLES, DRYWALL WINDOW CAULKING, TJL CEILING, CEILING TEXTURE, ROOFING SHINGLES REAR STORAGE BUILDING, BRICK MANTOR, PIPE - INSULATION. PLM per contractor 5/16/2025				
The Ceiling Texture Located in Living Room AREA CONTAINS ASBESTOS				
VII. QUANTITY OF RACM TO BE REMOVED: 200 SF Ceiling Texture located in Living Room AREA				
Pipes (LN FT): 0	Surface Area (SQ FT): 200 SF	Volume of Facility Components (CU FT): 0		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0				
Category I: ✓	Category II:			
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 5/27/25		Complete: 5/28/25		
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 5/29/25		Complete: 6/29/25		

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Wet Method, REMOVE OVER GROWN WEED WITH TRACKHOE/DOZER, CLEANUP FLOOR, BAG, RAG 6 MIL POLY OVER FLOOR, WET CEILING AND REMOVE ONTO FLOOR. PLACE INTO BAGS. CLEANUP. (Demo Building with Trackhoe)

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: Prep. Living room area / PLACE 6 mil POLY ONTO FLOOR, WET AND REMOVE CEILING ONTO 6 mil POLY ON THE FLOOR, PLACE CEILING ALONG WITH 6 mil POLY INTO DOUBLE BAGS, DROP TAG, TAPE CLOSE, PLACE BAGS INTO LINED DUMPSTER. WET DOWN THE ROOM.

XIII. WASTE TRANSPORTER #1

Name: **Bell Environmental Services, LLC.**

Address: **P.O. BOX 133**

City: **Delta City**

State: **MS**

Zip: **39061**

Contact Person: **Jimmy Bell**

Tel: **662-820-2124**

WASTE TRANSPORTER #2 **N/A**

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: **Big River Landfill (Republic Services).**

Address: **52 Landfill Rd.**

City: **Leland**

State: **MS**

Zip: **38756**

Contact Person: **Willie Christen**

Tel: **662-332-7927**

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: N/A

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER: Stop All Work, Wet Materials Contact Owner and MDEQ of Change. Follow MDEQ Direction

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell

Type or Print Name

Jimmy Bell

(Signature of Owner/Operator)

5/14/25

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Jimmy Bell


Type or Print Name

Jimmy Bell


(Signature of Owner/Operator)

5/14/25


(Date)



0 1 2 3
Scale in Miles
© MapQuest.com, Inc.



(3)





This is the OLD SERVICES station

Water Tower
in Delta →
City.



Catching Road going Thru DELTA city



STATE RD. 434 WEST COMING FROM US HWY 61
ENDING AT DELTA CITY EDGE TURNING INTO CATCHING RD.