

AI: 89327

MSR109614

Rec'd via email:
07/22/2025



MISSISSIPPI DEPARTMENT OF
ENVIRONMENTAL QUALITY

LARGE CONSTRUCTION NOTICE OF INTENT (LCNOI) FOR COVERAGE UNDER THE LARGE CONSTRUCTION STORM WATER GENERAL NPDES PERMIT

INSTRUCTIONS

The Large Construction Notice of Intent (LCNOI) is for coverage under the Large Construction General Permit for land disturbing activities of five (5) acres or greater; or for land disturbing activities, which are part of a larger common plan of development or sale that are initially less than five (5) acres but will ultimately disturb five (5) or more acres. Applicant must be the owner or operator. For construction activities, the operator is typically the prime contractor. The owner(s) of the property and the prime contractor associated with regulated construction activity on the property have joint and severable responsibility for compliance with the Large Construction Storm Water General Permit MSR10.

If the company seeking coverage is a corporation, a limited liability company, a partnership, or a business trust, attach proof of its registration with the Mississippi Secretary of State and/or its Certificate of Good Standing. This registration or Certificate of Good Standing must be dated within twelve (12) months of the date of the submittal of this coverage form. Coverage will be issued in the company name as it is registered with the Mississippi Secretary of State.

Completed LCNOIs should be filed at least thirty (30) days prior to the commencement of construction. Discharge of storm water from large construction activities without written notification of coverage is a violation of state law.

Submittals with this LCNOI must include:

- A site-specific Storm Water Pollution Prevention Plan (SWPPP) developed in accordance with ACT5 of the General Permit
- A detailed site-specific scaled drawing showing the property layout and the features outlined in ACT5 of the General Permit
- A United States Geological Survey (USGS) quadrangle map or photocopy, extending at least one-half mile beyond the facility property boundaries with the site location and outfalls outlined or highlighted. The name of the quadrangle map must be shown on all copies. Quadrangle maps can be obtained from the MDEQ, Office of Geology at 601-961-5523.

Attached & on sheet C143

Additional submittals may include the following, if applicable:

- Appropriate Section 404 documentation from U.S. Army Corps of Engineers
- Appropriate documentation concerning future disposal of sanitary sewage and sewage collection system construction
- Appropriate documentation from the MDEQ Office of Land & Water concerning dam construction and low flow requirements
- Approval from County Utility Authority in Hancock, Harrison, Jackson, Pearl River and Stone Counties
- Antidegradation report for disturbance within Waters of the State

ALL QUESTIONS MUST BE ANSWERED (Answer "NA" if the question is not applicable)

OC

APPLICANT IS THE: OWNER PRIME CONTRACTOR

OWNER CONTACT INFORMATION

OWNER CONTACT PERSON: _____

OWNER COMPANY LEGAL NAME: _____

OWNER STREET OR P.O. BOX: _____

OWNER CITY: _____ STATE: _____ ZIP: _____

OWNER PHONE #: (____) _____ OWNER EMAIL: _____

PREPARER CONTACT INFORMATION

IF NOI WAS PREPARED BY SOMEONE OTHER THAN THE APPLICANT

CONTACT PERSON: _____

COMPANY LEGAL NAME: _____

STREET OR P.O. BOX: _____

CITY: _____ STATE: _____ ZIP: _____

PHONE # () _____ EMAIL: _____

PRIME CONTRACTOR CONTACT INFORMATION

PRIME CONTRACTOR CONTACT PERSON: _____

PRIME CONTRACTOR COMPANY LEGAL NAME: _____

PRIME CONTRACTOR STREET OR P.O. BOX: _____

PRIME CONTRACTOR CITY: _____ STATE: _____ ZIP: _____

PRIME CONTRACTOR PHONE #: (____) _____ PRIME CONTRACTOR EMAIL: _____

FACILITY SITE INFORMATION

FACILITY SITE NAME: _____

FACILITY SITE ADDRESS (If the physical address is not available, please indicate the nearest named road. For linear projects indicate the beginning of the project and identify all counties the project traverses.)

STREET: _____

CITY: _____ STATE: _____ COUNTY: _____ ZIP: _____

FACILITY SITE TRIBAL LAND ID (N/A If not applicable): _____

LATITUDE: ____ degrees ____ minutes ____ seconds LONGITUDE: ____ degrees ____ minutes ____ seconds

LAT & LONG DATA SOURCE (GPS (Please GPS Project Entrance/Start Point) or Map Interpolation): _____

TOTAL ACREAGE THAT WILL BE DISTURBED ¹: _____

IS THIS PART OF A LARGER COMMON PLAN OF DEVELOPMENT? YES NO

IF YES, NAME OF LARGER COMMON PLAN OF DEVELOPMENT: _____
AND PERMIT COVERAGE NUMBER: MSR10 _____

ESTIMATED CONSTRUCTION PROJECT START DATE: _____
 YYYY-MM-DD

ESTIMATED CONSTRUCTION PROJECT END DATE: _____
 YYYY-MM-DD

DESCRIPTION OF CONSTRUCTION ACTIVITY: _____

PROPOSED DESCRIPTION OF PROPERTY USE AFTER CONSTRUCTION HAS BEEN COMPLETED:

SIC Code: _____ **NAICS Code** _____

NEAREST NAMED RECEIVING STREAM: _____

IS RECEIVING STREAM ON MISSISSIPPI'S 303(d) LIST OF IMPAIRED WATER BODIES? (The 303(d) list of impaired waters and TMDL stream segments may be found on MDEQ's web site: http://www.deq.state.ms.us/MDEQ.nsf/page/TWB_Total_Maximum_Daily_Load_Section) YES NO

HAS A TMDL BEEN ESTABLISHED FOR THE RECEIVING STREAM SEGMENT? YES NO

FOR WHICH POLLUTANT:

ARE THERE RECREATIONAL STREAMS, PRIVATE/PUBLIC PONDS OR LAKES WITHIN ½ MILE DOWNSTREAM OF PROJECT BOUNDARY THAT MAY BE IMPACTED BY THE CONSTRUCTION ACTIVITY? YES NO

EXISTING DATA DESCRIBING THE SOIL (for linear projects please describe in SWPPP):

WILL FLOCCULANTS BE USED TO TREAT TURBIDITY IN STORM WATER? YES NO

IF YES, INDICATE THE TYPE OF FLOCCULANT. ANIONIC POLYACRYLIMIDE (PAM)
 OTHER _____

IF YES, DOES THE SWPPP DESCRIBE THE METHOD OF INTRODUCTION, THE LOCATION OF INTRODUCTION AND THE LOCATION OF WHERE FLOCCULATED MATERIAL WILL SETTLE?

IS A SDS SHEET INCLUDED FOR THE FLOCCULATE? YES NO

WILL THERE BE A 50 FT BUFFER BETWEEN THE PROJECT DISTURBANCE AND THE WATERS OF THE STATE? YES NO

IF NOT, PROVIDE EQUIVALENT CONTROL MEASURES IN THE SWPPP.

¹Acreage for subdivision development includes areas disturbed by construction of roads, utilities and drainage. Additionally, a housesite of at least 10,000 ft² per lot (entire lot, if smaller) shall be included in calculating acreage disturbed.

DOCUMENTATION OF COMPLIANCE WITH OTHER REGULATIONS/REQUIREMENTS
 COVERAGE UNDER THIS PERMIT WILL NOT BE GRANTED UNTIL ALL OTHER REQUIRED
 MDEQ PERMITS AND APPROVALS ARE SATISFACTORILY ADDRESSED

IS LCNOI FOR A FACILITY THAT WILL REQUIRE OTHER PERMITS? YES NO

IF YES, CHECK ALL THAT APPLY: AIR HAZARDOUS WASTE PRETREATMENT
 WATER STATE OPERATING INDIVIDUAL NPDES OTHER: _____

IS THE PROJECT REROUTING, FILLING OR CROSSING A WATER CONVEYANCE OF ANY KIND? (If yes, contact the U.S. Army Corps of Engineers' Regulatory Branch for permitting requirements.) YES NO

IF THE PROJECT REQUIRES A CORPS OF ENGINEER SECTION 404 PERMIT, PROVIDE APPROPRIATE DOCUMENTATION THAT:

- The project has been approved by individual permit, or
- The work will be covered by a nationwide permit and NO NOTIFICATION to the Corps is required, or
- The work will be covered by a nationwide or general permit and NOTIFICATION to the Corps is required

IS THE PROJECT REROUTING, FILLING OR CROSSING A STATE WATER CONVEYANCE OF ANY KIND? (If yes, please provide an antidegradation report.) YES NO

IS A LAKE REQUIRING THE CONSTRUCTION OF A DAM BEING PROPOSED? (If yes, provide appropriate approval documentation from MDEQ Office of Land and Water, Dam Safety.) YES NO

IF THE PROJECT IS A SUBDIVISION OR A COMMERCIAL DEVELOPMENT, HOW WILL SANITARY SEWAGE BE DISPOSED? Check one of the following and attach the pertinent documents.

- Existing Municipal or Commercial System. Please attach plans and specifications for the collection system and the associated "Information Regarding Proposed Wastewater Projects" form or approval from County Utility Authority in Hancock, Harrison, Jackson, Pearl River and Stone Counties. If the plans and specifications can not be provided at the time of LCNOI submittal, MDEQ will accept written acknowledgement from official(s) responsible for wastewater collection and treatment that the flows generated from the proposed project can and will be transported and treated properly. The letter must include the estimated flow.
- Collection and Treatment System will be Constructed. Please attach a copy of the cover of the NPDES discharge permit from MDEQ or indicate the date the application was submitted to MDEQ (Date: _____.)
- Individual Onsite Wastewater Disposal Systems for Subdivisions Less than 35 Lots. Please attach a copy of the Letter of General Acceptance from the Mississippi State Department of Health or certification from a registered professional engineer that the platted lots should support individual onsite wastewater disposal systems.
- Individual Onsite Wastewater Disposal Systems for Subdivisions Greater than 35 Lots. A determination of the feasibility of installing a central sewage collection and treatment system must be made by MDEQ. A copy of the response from MDEQ concerning the feasibility study must be attached. If a central collection and wastewater system is not feasible, then please attach a copy of the Letter of General Acceptance from the State Department of Health or certification from a registered professional engineer that the platted lots should support individual onsite wastewater disposal systems.

INDICATE ANY LOCAL STORM WATER ORDINANCE (I.E. MS4) WITH WHICH THE PROJECT MUST COMPLY:

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.



Signature

(or prime contractor)

Date Signed

Printed Name¹

Title

¹This application shall be signed as follows:

- For a corporation, by a responsible corporate officer.
- For a partnership, by a general partner.
- For a sole proprietorship, by the proprietor.

For a municipal, state or other public facility, by principal executive officer, mayor, or ranking elected official

Please submit the LCNOI form to:

**Chief, Environmental Permits Division
MS Department of Environmental Quality, Office of Pollution Control
P.O. Box 2261
Jackson, Mississippi 39225**


Electronically:

<https://www.mdeq.ms.gov/construction-stormwater/>

Revised 3/23/22

MERIDIAN QUADRANGLE

MISSISSIPPI
7.5-MINUTE SERIES



LEGEND

- #1 - $\frac{1}{2}$ MI RADIUS AROUND SITE
- #2 - PROPERTY BOUNDARY
- #3 - PROPOSED BUILDING
- #4 - STORMWATER OUTFALL
- #5 - APPROX. LOCATION OF RECEIVING WATERS:
UNNAMED TRIBUTARY OF CLEAR BRANCH

MERIDIAN NORTH



MERIDIAN SOUTH





Michael Watson
SECRETARY OF STATE

Office of the Secretary of State
Jackson, Mississippi

Certificate of Good Standing

I, MICHAEL WATSON, Secretary of State of the State of Mississippi, and as such, the legal custodian of the records as required by the laws of Mississippi, to be filed in my office, do hereby certify:

That on the 22nd day of June, 2021, the State of Mississippi issued a Charter/ Certificate of Authority to:

QUIKTRIP CORPORATION

That the state of incorporation is Oklahoma.

That the period of duration is perpetual.

That according to the records of this office, Articles of Dissolution or a Certificate of Withdrawal have not been filed.

That according to the records of this office, a current Annual Report has been delivered to the Office of the Secretary of State.

I further certify that all fees, taxes and penalties owed to this state, as reflected in the records of the Secretary of State, have been paid and that the corporation is in existence or has authority to transact business in Mississippi.

That insofar as the records of this office are concerned, the said QuikTrip Corporation is in good standing at this time.

Given under my hand and seal of office
the 31st day of July, 2023

A handwritten signature in black ink that reads "Michael Watson".

Certificate Number: CN23169862

Verify this certificate online at <http://corp.sos.ms.gov/corpcnv/verifycertificate.aspx>



July 17, 2025

CITY OF MERIDIAN

MS Department of Environmental Quality
Office of Pollution Control
Environmental Permits Division
PO Box 2261
Jackson, MS 39225

RE: Utility Will Serve Confirmation – QuikTrip (QT7257)
Jimmie Rodgers Parkway and I-20/59

Mayor
PERCY BLAND, III
(P) 601.485.1927
(F) 601.485.1911

City Council

ELLIOT BREWER
Ward 1

DWAYNE DAVIS
Ward 2

TRACY V. TIMS
Ward 3

ROMANDE WALKER
Ward 4

DUSTIN HILL
Ward 5

COUNCIL CLERK
(P) 601.485.1959
(F) 601.485.1913

City Departments

Chief Administrative Officer
(P) 601.485.1929
(F) 601.485.1911

Community Development
(P) 601.485.1910
(F) 601.484.6813

Finance and Records
(P) 601.485.1946
(F) 601.485.1979

Fire
(P) 601.485.1822
(F) 601.485.1035

Public Safety
(P) 601.484.6890
(F) 601.484.6895

Parks and Recreation
(P) 601.485.1802
(F) 601.485.1851

Police
(P) 601.485.1841
(F) 601.484.6832

Public Works
(P) 601.485.1920
(F) 601.485.1864

To Whom It May Concern:

This letter is to confirm that the City of Meridian will provide potable water and sanitary sewer service to the proposed QuikTrip (QT7257) located at Jimmie Rodgers Parkway and I-20/59, contingent upon the successful completion of all required system improvements as determined by the City.

All water and sewer infrastructure improvements necessary to serve the development are the responsibility of the developer and must be designed and constructed in accordance with the City's current standards, specifications, and applicable regulations. These improvements shall be reviewed and approved by the City prior to construction and must be inspected and accepted by the City before water and sewer service connections will be authorized.

Please be advised that this commitment is subject to the capacity of the City's existing utility systems at the time of connection, and to any changes in local, state or federal regulations that may affect service availability or requirements.

Please feel free to contact me if you have any questions or need additional information.

Sincerely,

David M. Hodge, P.E.
City of Meridian
Public Works Director

DH/ph

WETLAND DELINEATION REPORT

Property:

QuikTrip Store # 7257
Hawkins Crossing Road
Meridian, Mississippi
Lauderdale County
Parcel Number: 08210000000002200
UES Project #: 0740.2400153.0000

Prepared for:

QuikTrip Tulsa
C/o Justin Coons
4705 South 129th East Avenue
Tulsa, Oklahoma 74134
Jcoons@quiktrip.com

Prepared by:

UES
3298 Summit Boulevard, Suite 44
Pensacola, Florida 32503
850.435.9367



Ecological Services & Environmental Permitting

This report contains proprietary, business-confidential and/or privileged material. The information transmitted by this document is intended only for the recipient and represents the work product of UES Professional Solutions, LLC (UES) who owns the information and has provided it to the recipient under terms and conditions. The recipient is authorized by UES to transmit this information to others as necessary to accomplish their objectives. That transmission, however, does not obligate UES to interpret or otherwise consult with additional recipients of the substance of this report.

INTRODUCTION

UES has completed an assessment of the presence of “wetlands” and “other waters” on the property identified above. These terms reflect the classification of environmental resources that are potentially subject to a variety of regulatory protections. These may be promulgated and enforced by multiple agencies at the federal, state, and local levels that have jurisdiction over environmental resources. If our assessment identified wetlands or other waters on the property, the limits of those jurisdictional features were delineated in the field and are projected on the map accompanying this report.

This report, and the attached maps, illustrate the presence and the position of protected resources on the property. Development or use plans that will impact wetlands or other waters will require permits from one or more regulatory agencies prior to construction. For permitting assistance, we encourage you to contact our permitting professionals at Permitting@teamues.com to schedule a consultation.

FEDERAL JURISDICTION

The Federal Water Pollution Control Act of 1948 as amended in 1972 is commonly referred to as The Clean Water Act (CWA) and represents the fundamental protection of “Waters of the United States” (WOTUS) including wetlands and other waters. Regulatory authority under the CWA was granted by Congress to the Environmental Protection Agency (EPA) which sets pollution standards and governs regulatory programs. Practical administration of the permit program for authorizing discharges of “dredged material” into WOTUS is undertaken by the US Army Corps of Engineers (COE).

The procedures for determining the limits of the federal jurisdiction over wetlands and other waters were established in Technical Report Y-87-1, the Corps of Engineers Wetlands Delineation Manual (87 Manual). These procedures are further modified by federal judicial decisions, Regulatory Guidance Letters, and other communications that convey the current status of WOTUS. If CWA wetlands are present on the property, the delineation presented on the attached map was conducted in accordance with the current guidance for determining the extent of WOTUS.

STATE JURISDICTION - MISSISSIPPI

To eliminate unnecessary duplication of efforts among agencies and to streamline the permitting process for routine projects with only minimal impact, the United States Corps of Engineers (COE) Mobile District and the COE Vicksburg District regulate minor structures and activities in waters of the US, in the state of Mississippi and outer continental shelf waters off the coast of Mississippi, within the Regulatory boundaries of the Mobile District and within the Regulatory boundaries of the Vicksburg District in Hancock County under Regional General Permits.

The Coastal Wetlands Protection Act is a policy that favors the preservation of the natural state of the coastal wetlands and their ecosystems and is regulated by the Mississippi Commission on

Marine Resources. No regulated activity shall affect any coastal wetlands without a permit unless excluded in the Mississippi Administrative Code.

LOCAL JURISDICTION

Protection of environmental resources is well established in statutes and regulations at the federal and state levels. However, such also receives attention in local land use decisions. Land development rights are granted and regulated at the local (county or municipal) as governed by Land Development Codes (LDC). Each local jurisdiction has a unique LDC that governs land use and construction. Many LDCs include natural resource protections including those related to wetlands. Often, federal and state protections are augmented by the LDC which limits land uses adjacent to CWA or state wetlands. These usually present as setbacks or buffers typically on the order of 25 to 30-feet.

TECHNICAL INFORMATION

The process of determining the presence of wetlands and establishing their landward extent is a procedure generally referred to as a wetland delineation. Wetland delineations are highly technical and conducted by a skilled environmental professional. Regardless of jurisdiction, three parameters are evaluated in a wetland delineation: plants, soils, and hydrology. This section records and conveys specific technical observations for later use by environmental professionals and regulators in the event permits are sought for wetland impacts:

- 1. General Observations:** The property is undeveloped land located southwest of the intersection of I-20 and Jimmy Rodgers Parkway in a vicinity dominated by transportation corridors and vacant land. The property has been historically filled and graded into a large flat fill pad that slopes down to a maintained lawn. The maintained lawn area adjoins several concrete-constructed drainage swales which drain storm-water toward a wetland system off property to the east. The large fill pad occupies the western portion of the property. Wetlands were not observed on the property or in connection with the constructed drainage ways transecting the eastern portion. Soil onsite consists of loamy fill materials. Hydrology was limited to constructed stormwater swales.
- 2. Vegetation:** The property was dominated by perennial herbaceous groundcover including broomsedge, Canada goldenrod, cogon grass, bahia grass, and Chinese bush clover.
- 3. Soils:** The NRCS soil survey indicates the property is underlain by the Sweatman (non-hydric) soil series. Onsite soil pit excavation revealed mixed loamy fill material throughout the site.
- 4. Hydrology:** Indicators of hydrology included stormwater drainage ditches. No other indicators of hydrology were identified onsite.

WETLAND PERMITTING

If this delineation has identified wetlands on the property that are of a size, shape, or orientation that limit the intended use of the property, a permit or permits from the jurisdictional authority

may be required. This delineation report should be presented to your land development professionals (engineer, builder) for consideration in site planning and accompany any submittal seeking a development order or building permit. Any drawings conveying a site plan should include the wetland jurisdictional boundaries and buffers. If an impact on a wetland or buffer is necessary to develop the site plan, authorization in the form of permits must be obtained from the agencies with jurisdictional authority. UES is particularly skilled at guiding this process. For general information on wetland permitting, please visit <http://www.UES.co/before-you-build/wetland-permitting.php>. For specific information about permitting your project or property, we recommend a permitting consultation which can be scheduled by contacting permitting@teamues.com.

As you review the information in this delineation report and make a decision relating to the subject property, we offer this general guidance as relates to wetland permitting:

As regulators evaluate your proposed land use as depicted on the submitted site plans, they will authorize NO impact if a practicable alternative exists that is less damaging to the aquatic environment. Accordingly, your submitted site plans MUST demonstrate the following to the extent practicable:

- Reasonably avoided all wetland impacts;
- Minimized potential impacts on wetlands; and
- Provide compensation for any remaining unavoidable impacts.

CONCLUSION

UES has completed a wetland delineation within an area identified as “Inspection Boundary” on the attached map. The Inspection Boundary was digitally sourced from local government Geographic Information System (GIS) servers and does not represent a boundary survey conducted by a licensed professional land surveyor. Our delineation data was collected in the field with handheld GPS equipment with sub-meter accuracy capability. We note that site conditions and other factors affect the accuracy of data collected with this technology. Areas and dimensions presented in this report are derived from spatial data generated by UES’s GIS.

Based on our thorough assessment, we have determined that **10.7 acres** of the property is upland with **0.00 acres** of wetlands and other waters within state and federal jurisdiction. As such, any proposal to develop the parcel will not require federal or state permits. We note that these calculations are based on an inspection boundary approximated from the county property appraiser's depiction of the property boundary. An actual boundary survey may result in slightly different calculations.


A wetland delineation performed by an ecological consultant represents the professional opinion of the scientist who performed the work. Only regulatory agencies can establish a legal and binding jurisdictional boundary. Such can be obtained by submitting a permit application and waiting several months for processing. For local government permitting (e.g., building permit) this report should suffice. This report is intended for sole use by the above-listed addressee who

retained UES to provide specific guidance relating to jurisdictional wetlands. This work product is the property of UES and may not be conveyed to or relied upon by another party, other than the recipient's design professionals, without the written consent of UES.

This concludes our assessment of the above-referenced site. We look forward to being of assistance to you again in the future.

SIGNATURE OF ENVIRONMENTAL PROFESSIONAL


I declare that I possess sufficient skill and experience to accurately identify and delineate wetlands. I have conducted and/or reviewed this assessment and support the data and conclusions contained therein.



Mackenzie Devine, MS
Ecological Support Technician
UES

02/13/2025

Date



Jessica Rushing, MS, WPIT
Ecological Consultant – Field Ecologist
UES

02/13/2025

Date

LIST OF EXHIBITS

- Exhibit 1 Wetland Delineation Map


- Exhibit 2 USACE Wetland Data Forms

- Exhibit 3 Data Point Photos

EXHIBIT 1



Ecological Services & Environmental Permitting



I-10

APPROXIMATE ACREAGES
 UPLANDS: 10.7-ACRES
 WETLANDS: 0.00-ACRES

WETLAND DELINEATION MAP LAUDERDALE COUNTY HAWKINS CROSSING ROAD 08210000000002200 QUIKTRIP	LEGEND INSPECTION BOUNDARY DATA POINTS ENGINEERED DRAINAGE	2785.001 JJR		
		2/13/2025		
				THIS IS NOT A SURVEY

EXHIBIT 2



Ecological Services & Environmental Permitting

Project/Site: Hawkins Crossing Road City/County: Meridian/Lauderdale Sampling Date: 11/12/2024
 Applicant/Owner: Quik Trip State: MS Sampling Point: 1
 Investigator(s): Jessica Rushing and Mackenzie Devine Section, Township, Range: 10, 6 North, 16 East
 Landform (hillside, terrace, etc.): fill pad Local relief (concave, convex, none): non Slope (%): 0-1
 Subregion (LRR or MLRA): LRR P, MLRA 133A Lat: 32.376402 Long: -88.655000 Datum: NAD 1983
 Soil Map Unit Name: Sweatmen NWI classification: N/A

Are climatic / hydrologic conditions on the site typical for this time of year? Yes X No (If no, explain in Remarks.)
 Are Vegetation X, Soil X, or Hydrology significantly disturbed? Are "Normal Circumstances" present? Yes X No
 Are Vegetation , Soil , or Hydrology naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes <u> </u> No <u>X</u>	Is the Sampled Area within a Wetland?	Yes <u> </u> No <u>X</u>
Hydric Soil Present?	Yes <u> </u> No <u>X</u>		
Wetland Hydrology Present?	Yes <u> </u> No <u>X</u>		

Remarks:
 The property adjoining I-20 appears to be formed from fill material that has been shaped and graded. The fill pad largely covers the property and drops down to a basin on the eastern portion surrounded by constructed stormwater channels. No wetlands were observed on the property.

HYDROLOGY

Wetland Hydrology Indicators: <u>Primary Indicators (minimum of one is required; check all that apply)</u> <input type="checkbox"/> Surface Water (A1) <input type="checkbox"/> Aquatic Fauna (B13) <input type="checkbox"/> High Water Table (A2) <input type="checkbox"/> Marl Deposits (B15) (LRR U) <input type="checkbox"/> Saturation (A3) <input type="checkbox"/> Hydrogen Sulfide Odor (C1) <input type="checkbox"/> Water Marks (B1) <input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3) <input type="checkbox"/> Sediment Deposits (B2) <input type="checkbox"/> Presence of Reduced Iron (C4) <input type="checkbox"/> Drift Deposits (B3) <input type="checkbox"/> Recent Iron Reduction in Tilled Soils (C6) <input type="checkbox"/> Algal Mat or Crust (B4) <input type="checkbox"/> Thin Muck Surface (C7) <input type="checkbox"/> Iron Deposits (B5) <input type="checkbox"/> Other (Explain in Remarks) <input type="checkbox"/> Inundation Visible on Aerial Imagery (B7) <input type="checkbox"/> Water-Stained Leaves (B9)	<u>Secondary Indicators (minimum of two required)</u> <input type="checkbox"/> Surface Soil Cracks (B6) <input type="checkbox"/> Sparsely Vegetated Concave Surface (B8) <input type="checkbox"/> Drainage Patterns (B10) <input type="checkbox"/> Moss Trim Lines (B16) <input type="checkbox"/> Dry-Season Water Table (C2) <input type="checkbox"/> Crayfish Burrows (C8) <input type="checkbox"/> Saturation Visible on Aerial Imagery (C9) <input type="checkbox"/> Geomorphic Position (D2) <input type="checkbox"/> Shallow Aquitard (D3) <input type="checkbox"/> FAC-Neutral Test (D5) <input type="checkbox"/> Sphagnum Moss (D8) (LRR T, U)
--	--

Field Observations: Surface Water Present? Yes <u> </u> No <u>X</u> Depth (inches): <u> </u> Water Table Present? Yes <u> </u> No <u>X</u> Depth (inches): <u> </u> Saturation Present? Yes <u> </u> No <u>X</u> Depth (inches): <u> </u> (includes capillary fringe)	Wetland Hydrology Present? Yes <u> </u> No <u>X</u>
--	---

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
 The point was taken on the fill pad. Evidence of hydrology was not observed.

VEGETATION (Four Strata) – Use scientific names of plants.

Sampling Point: 1

Tree Stratum (Plot size: _____)	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
	_____ = Total Cover		
	50% of total cover: _____	20% of total cover: _____	

Sapling/Shrub Stratum (Plot size: _____)	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
	_____ = Total Cover		
	50% of total cover: _____	20% of total cover: _____	

Herb Stratum (Plot size: <u>30</u>)	Absolute % Cover	Dominant Species?	Indicator Status
1. <u>Andropogon ternarius</u>	<u>65</u>	<u>Yes</u>	<u>FACU</u>
2. <u>Solidago altissima</u>	<u>15</u>	<u>No</u>	<u>FACU</u>
3. <u>Bothriochloa barbinodis</u>	<u>5</u>	<u>No</u>	<u>FACU</u>
4. <u>Pityopsis graminifolia</u>	<u>5</u>	<u>No</u>	<u>UPL</u>
5. <u>Symphotrichum ericoides</u>	<u>7</u>	<u>No</u>	<u>UPL</u>
6. <u>Lespedeza cuneata</u>	<u>25</u>	<u>Yes</u>	<u>FACU</u>
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____
11. _____	_____	_____	_____
12. _____	_____	_____	_____
	<u>122</u> = Total Cover		
	50% of total cover: <u>61</u>	20% of total cover: <u>25</u>	

Woody Vine Stratum (Plot size: _____)	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
	_____ = Total Cover		
	50% of total cover: _____	20% of total cover: _____	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 0.0% (A/B)

Prevalence Index worksheet:

Total % Cover of:	Multiply by:
OBL species <u>0</u>	x 1 = <u>0</u>
FACW species <u>0</u>	x 2 = <u>0</u>
FAC species <u>0</u>	x 3 = <u>0</u>
FACU species <u>110</u>	x 4 = <u>440</u>
UPL species <u>12</u>	x 5 = <u>60</u>
Column Totals: <u>122</u> (A)	<u>500</u> (B)
Prevalence Index = B/A = <u>4.10</u>	

Hydrophytic Vegetation Indicators:

 1 - Rapid Test for Hydrophytic Vegetation

 2 - Dominance Test is >50%

 3 - Prevalence Index is ≤3.0¹

 Problematic Hydrophytic Vegetation¹ (Explain)

¹Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Four Vegetation Strata:

Tree – Woody plants, excluding vines, 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub – Woody plants, excluding vines, less than 3 in. DBH and greater than 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody Vine – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present?

Yes	<u> </u>	No	<u>X</u>
-----	-----------	----	----------

Remarks: (If observed, list morphological adaptations below.)
 The area appears to be regularly mowed, promoting opportunistic and early successional species.

SOIL

Sampling Point: 1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)								
Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²		
0-14	7.5YR 5/6	100					Loamy/Clayey	fill material

¹Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.

²Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)

- | | |
|--|--|
| <input type="checkbox"/> Histosol (A1) | <input type="checkbox"/> Thin Dark Surface (S9) (LRR S, T, U) |
| <input type="checkbox"/> Histic Epipedon (A2) | <input type="checkbox"/> Barrier Islands 1 cm Muck (S12) |
| <input type="checkbox"/> Black Histic (A3) | (MLRA 153B, 153D) |
| <input type="checkbox"/> Hydrogen Sulfide (A4) | <input type="checkbox"/> Loamy Mucky Mineral (F1) (LRR O) |
| <input type="checkbox"/> Stratified Layers (A5) | <input type="checkbox"/> Loamy Gleyed Matrix (F2) |
| <input type="checkbox"/> Organic Bodies (A6) (LRR P, T, U) | <input type="checkbox"/> Depleted Matrix (F3) |
| <input type="checkbox"/> 5 cm Mucky Mineral (A7) (LRR P, T, U) | <input type="checkbox"/> Redox Dark Surface (F6) |
| <input type="checkbox"/> Muck Presence (A8) (LRR U) | <input type="checkbox"/> Depleted Dark Surface (F7) |
| <input type="checkbox"/> 1 cm Muck (A9) (LRR P, T) | <input type="checkbox"/> Redox Depressions (F8) |
| <input type="checkbox"/> Depleted Below Dark Surface (A11) | <input type="checkbox"/> Marl (F10) (LRR U) |
| <input type="checkbox"/> Thick Dark Surface (A12) | <input type="checkbox"/> Depleted Ochric (F11) (MLRA 151) |
| <input type="checkbox"/> Coast Prairie Redox (A16) (MLRA 150A) | <input type="checkbox"/> Iron-Manganese Masses (F12) (LRR O, P, T) |
| <input type="checkbox"/> Iron Monosulfide (A18) | <input type="checkbox"/> Umbric Surface (F13) (LRR P, T, U) |
| <input type="checkbox"/> Sandy Mucky Mineral (S1) (LRR O, S) | <input type="checkbox"/> Delta Ochric (F17) (MLRA 151) |
| <input type="checkbox"/> Sandy Gleyed Matrix (S4) | <input type="checkbox"/> Reduced Vertic (F18) (MLRA 150A, 150B) |
| <input type="checkbox"/> Sandy Redox (S5) | <input type="checkbox"/> Piedmont Floodplain Soils (F19) (MLRA 149A) |
| <input type="checkbox"/> Stripped Matrix (S6) | <input type="checkbox"/> Anomalous Bright Floodplain Soils (F20) |
| <input type="checkbox"/> Dark Surface (S7) (LRR P, S, T, U) | (MLRA 149A, 153C, 153D) |
| <input type="checkbox"/> Polyvalue Below Surface (S8) | <input type="checkbox"/> Very Shallow Dark Surface (F22) |
| (LRR S, T, U) | (MLRA 138, 152A in FL, 154) |

Indicators for Problematic Hydric Soils³:

- 1 cm Muck (A9) (LRR O)
- 2 cm Muck (A10) (LRR S)
- Coast Prairie Redox (A16) (MLRA 149A)
- Reduced Vertic (F18)
- (outside MLRA 150A, 150B)**
- Piedmont Floodplain Soils (F19) (LRR P, T)
- Anomalous Bright Floodplain Soils (F20)
- (MLRA 153B)**
- Red Parent Material (F21)
- Very Shallow Dark Surface (F22)
- (outside MLRA 138, 152A in FL, 154)**
- Other (Explain in Remarks)

³Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: _____
 Depth (inches): _____

Hydric Soil Present? Yes _____ No X

Remarks:

The soils appear to have been disturbed by the addition of fill material

AGENCY DISCLOSURE NOTIFICATION

The public reporting burden for this collection of information, OMB Control Number 0710-0024, is estimated to average 30 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or burden reduction suggestions to the Department of Defense, Washington Headquarters Services, at whs.mc-alex.esd.mbx.dd-dod-information-collections@mail.mil. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. **PLEASE DO NOT RETURN YOUR REQUEST TO THE ABOVE EMAIL.**

PRIVACY ACT STATEMENT

Authorities: Rivers and Harbors Act, Section 10, 33 USC 403; Clean Water Act, Section 404, 33 USC 1344; Marine Protection, Research, and Sanctuaries Act, Section 103, 33 USC 1413; Regulatory Programs of the Corps of Engineers; Final Rule 33 CFR 320-332. Principal Purpose: Information provided on this form will be used in evaluating the application for a permit. Routine Uses: This information may be shared with the Department of Justice and other federal, state, and local government agencies, and the public and may be made available as part of a public notice as required by Federal law. Submission of requested information is voluntary, however, if information is not provided the permit application cannot be evaluated nor can a permit be issued. One set of original drawings or good reproducible copies which show the location and character of the proposed activity must be attached to this application (see sample drawings and/or instructions) and be submitted to the District Engineer having jurisdiction over the location of the proposed activity. An application that is not completed in full will be returned. System of Record Notice (SORN). The information received is entered into our permit tracking database and a SORN has been completed (SORN #A1145b) and may be accessed at the following website: <http://dpcl.d.defense.gov/Privacy/SORNsIndex/DOD-wide-SORN-Article-View/Article/570115/a1145b-ce.aspx>

Project/Site: Hawkins Crossing Road City/County: Meridian/Lauderdale Sampling Date: 11/12/2024
 Applicant/Owner: Quik Trip State: MS Sampling Point: 2
 Investigator(s): Jessica Rushing and Mackenzie Devine Section, Township, Range: 10, 6 North, 16 East
 Landform (hillside, terrace, etc.): fill pad Local relief (concave, convex, none): non Slope (%): 2-5
 Subregion (LRR or MLRA): LRR P, MLRA 133A Lat: 32.376561 Long: -88.654533 Datum: NAD 1983
 Soil Map Unit Name: Sweatmen NWI classification: N/A

Are climatic / hydrologic conditions on the site typical for this time of year? Yes X No (If no, explain in Remarks.)
 Are Vegetation X, Soil X, or Hydrology significantly disturbed? Are "Normal Circumstances" present? Yes X No
 Are Vegetation , Soil , or Hydrology naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes <u> </u> No <u>X</u>	Is the Sampled Area within a Wetland?	Yes <u> </u> No <u>X</u>
Hydric Soil Present?	Yes <u> </u> No <u>X</u>		
Wetland Hydrology Present?	Yes <u> </u> No <u>X</u>		

Remarks:
 The property adjoining I-20 appears to be formed from fill material that has been shaped and graded. The fill pad largely covers the property and drops down to a basin on the eastern portion surrounded by constructed stormwater channels. No wetlands were observed on the property.

HYDROLOGY

Wetland Hydrology Indicators: <u>Primary Indicators (minimum of one is required; check all that apply)</u> <input type="checkbox"/> Surface Water (A1) <input type="checkbox"/> Aquatic Fauna (B13) <input type="checkbox"/> High Water Table (A2) <input type="checkbox"/> Marl Deposits (B15) (LRR U) <input type="checkbox"/> Saturation (A3) <input type="checkbox"/> Hydrogen Sulfide Odor (C1) <input type="checkbox"/> Water Marks (B1) <input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3) <input type="checkbox"/> Sediment Deposits (B2) <input type="checkbox"/> Presence of Reduced Iron (C4) <input type="checkbox"/> Drift Deposits (B3) <input type="checkbox"/> Recent Iron Reduction in Tilled Soils (C6) <input type="checkbox"/> Algal Mat or Crust (B4) <input type="checkbox"/> Thin Muck Surface (C7) <input type="checkbox"/> Iron Deposits (B5) <input type="checkbox"/> Other (Explain in Remarks) <input type="checkbox"/> Inundation Visible on Aerial Imagery (B7) <input type="checkbox"/> Water-Stained Leaves (B9)	<u>Secondary Indicators (minimum of two required)</u> <input type="checkbox"/> Surface Soil Cracks (B6) <input type="checkbox"/> Sparsely Vegetated Concave Surface (B8) <input checked="" type="checkbox"/> Drainage Patterns (B10) <input type="checkbox"/> Moss Trim Lines (B16) <input type="checkbox"/> Dry-Season Water Table (C2) <input type="checkbox"/> Crayfish Burrows (C8) <input type="checkbox"/> Saturation Visible on Aerial Imagery (C9) <input type="checkbox"/> Geomorphic Position (D2) <input type="checkbox"/> Shallow Aquitard (D3) <input type="checkbox"/> FAC-Neutral Test (D5) <input type="checkbox"/> Sphagnum Moss (D8) (LRR T, U)
--	---

Field Observations: Surface Water Present? Yes <u> </u> No <u>X</u> Depth (inches): <u> </u> Water Table Present? Yes <u> </u> No <u>X</u> Depth (inches): <u> </u> Saturation Present? Yes <u> </u> No <u>X</u> Depth (inches): <u> </u> (includes capillary fringe)	Wetland Hydrology Present? Yes <u> </u> No <u>X</u>
--	---

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
 The point was taken at the base of the fill pad slope. A stormwater drainage channel filled with rip rap was observed upgrade from this point.

VEGETATION (Four Strata) – Use scientific names of plants.

Sampling Point: 2

Tree Stratum (Plot size: _____)	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
	_____ = Total Cover		
	50% of total cover: _____	20% of total cover: _____	

Sapling/Shrub Stratum (Plot size: <u>30</u>)	Absolute % Cover	Dominant Species?	Indicator Status
1. <i>Salix nigra</i>	2	Yes	OBL
2. <i>Morella cerifera</i>	5	Yes	FAC
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
	7 = Total Cover		
	50% of total cover: <u>4</u>	20% of total cover: <u>2</u>	

Herb Stratum (Plot size: <u>30</u>)	Absolute % Cover	Dominant Species?	Indicator Status
1. <i>Imperata cylindrica</i>	90	Yes	FACU
2. <i>Lespedeza cuneata</i>	35	Yes	FACU
3. <i>Sesbania vesicaria</i>	15	No	FAC
4. <i>Solidago canadensis</i>	2	No	FACU
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____
11. _____	_____	_____	_____
12. _____	_____	_____	_____
	142 = Total Cover		
	50% of total cover: <u>71</u>	20% of total cover: <u>29</u>	

Woody Vine Stratum (Plot size: _____)	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
	_____ = Total Cover		
	50% of total cover: _____	20% of total cover: _____	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 50.0% (A/B)

Prevalence Index worksheet:

Total % Cover of:	Multiply by:
OBL species <u>2</u>	x 1 = <u>2</u>
FACW species <u>0</u>	x 2 = <u>0</u>
FAC species <u>20</u>	x 3 = <u>60</u>
FACU species <u>127</u>	x 4 = <u>508</u>
UPL species <u>0</u>	x 5 = <u>0</u>
Column Totals: <u>149</u> (A)	<u>570</u> (B)
Prevalence Index = B/A = <u>3.83</u>	

Hydrophytic Vegetation Indicators:

 1 - Rapid Test for Hydrophytic Vegetation

 2 - Dominance Test is >50%

 3 - Prevalence Index is ≤3.0¹

 Problematic Hydrophytic Vegetation¹ (Explain)

¹Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Four Vegetation Strata:

Tree – Woody plants, excluding vines, 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub – Woody plants, excluding vines, less than 3 in. DBH and greater than 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody Vine – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present?

Yes	<u> </u>	No	<u>X</u>
-----	-----------	----	----------

Remarks: (If observed, list morphological adaptations below.)
 The area appears to be regularly mowed, promoting opportunistic and early successional species.

SOIL

Sampling Point: 2

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)								
Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²		
0-2	7.5YR 4/3	100					Loamy/Clayey	
2-6	7.5YR 4/4	100					Loamy/Clayey	
6-14	7.5YR 4/4	100					Loamy/Clayey	

¹Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.

²Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)

- Histosol (A1)
- Histic Epipedon (A2)
- Black Histic (A3)
- Hydrogen Sulfide (A4)
- Stratified Layers (A5)
- Organic Bodies (A6) (LRR P, T, U)
- 5 cm Mucky Mineral (A7) (LRR P, T, U)
- Muck Presence (A8) (LRR U)
- 1 cm Muck (A9) (LRR P, T)
- Depleted Below Dark Surface (A11)
- Thick Dark Surface (A12)
- Coast Prairie Redox (A16) (MLRA 150A)
- Iron Monosulfide (A18)
- Sandy Mucky Mineral (S1) (LRR O, S)
- Sandy Gleyed Matrix (S4)
- Sandy Redox (S5)
- Stripped Matrix (S6)
- Dark Surface (S7) (LRR P, S, T, U)
- Polyvalue Below Surface (S8) (LRR S, T, U)
- Thin Dark Surface (S9) (LRR S, T, U)
- Barrier Islands 1 cm Muck (S12) (MLRA 153B, 153D)
- Loamy Mucky Mineral (F1) (LRR O)
- Loamy Gleyed Matrix (F2)
- Depleted Matrix (F3)
- Redox Dark Surface (F6)
- Depleted Dark Surface (F7)
- Redox Depressions (F8)
- Marl (F10) (LRR U)
- Depleted Ochric (F11) (MLRA 151)
- Iron-Manganese Masses (F12) (LRR O, P, T)
- Umbric Surface (F13) (LRR P, T, U)
- Delta Ochric (F17) (MLRA 151)
- Reduced Vertic (F18) (MLRA 150A, 150B)
- Piedmont Floodplain Soils (F19) (MLRA 149A)
- Anomalous Bright Floodplain Soils (F20) (MLRA 149A, 153C, 153D)
- Very Shallow Dark Surface (F22) (MLRA 138, 152A in FL, 154)

Indicators for Problematic Hydric Soils³:

- 1 cm Muck (A9) (LRR O)
- 2 cm Muck (A10) (LRR S)
- Coast Prairie Redox (A16) (MLRA 149A)
- Reduced Vertic (F18) (outside MLRA 150A, 150B)
- Piedmont Floodplain Soils (F19) (LRR P, T)
- Anomalous Bright Floodplain Soils (F20) (MLRA 153B)
- Red Parent Material (F21)
- Very Shallow Dark Surface (F22) (outside MLRA 138, 152A in FL, 154)
- Other (Explain in Remarks)

³Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: _____
 Depth (inches): _____

Hydric Soil Present? Yes _____ No X

Remarks:

The soils appear to have been disturbed by the addition of fill material

AGENCY DISCLOSURE NOTIFICATION

The public reporting burden for this collection of information, OMB Control Number 0710-0024, is estimated to average 30 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or burden reduction suggestions to the Department of Defense, Washington Headquarters Services, at whs.mc-alex.esd.mbx.dd-dod-information-collections@mail.mil. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. **PLEASE DO NOT RETURN YOUR REQUEST TO THE ABOVE EMAIL.**

PRIVACY ACT STATEMENT

Authorities: Rivers and Harbors Act, Section 10, 33 USC 403; Clean Water Act, Section 404, 33 USC 1344; Marine Protection, Research, and Sanctuaries Act, Section 103, 33 USC 1413; Regulatory Programs of the Corps of Engineers; Final Rule 33 CFR 320-332. Principal Purpose: Information provided on this form will be used in evaluating the application for a permit. Routine Uses: This information may be shared with the Department of Justice and other federal, state, and local government agencies, and the public and may be made available as part of a public notice as required by Federal law. Submission of requested information is voluntary, however, if information is not provided the permit application cannot be evaluated nor can a permit be issued. One set of original drawings or good reproducible copies which show the location and character of the proposed activity must be attached to this application (see sample drawings and/or instructions) and be submitted to the District Engineer having jurisdiction over the location of the proposed activity. An application that is not completed in full will be returned. System of Record Notice (SORN). The information received is entered into our permit tracking database and a SORN has been completed (SORN #A1145b) and may be accessed at the following website: <http://dpcl.d.defense.gov/Privacy/SORNsIndex/DOD-wide-SORN-Article-View/Article/570115/a1145b-ce.aspx>

Project/Site: Hawkins Crossing Road City/County: Meridian/Lauderdale Sampling Date: 11/12/2024
 Applicant/Owner: Quik Trip State: MS Sampling Point: 3
 Investigator(s): Jessica Rushing and Mackenzie Devine Section, Township, Range: 10, 6 North, 16 East
 Landform (hillside, terrace, etc.): lower elevation Local relief (concave, convex, none): concave Slope (%): 2-5
 Subregion (LRR or MLRA): LRR P, MLRA 133A Lat: 32.376417 Long: -88.654441 Datum: NAD 1983
 Soil Map Unit Name: Sweatmen NWI classification: N/A

Are climatic / hydrologic conditions on the site typical for this time of year? Yes X No (If no, explain in Remarks.)
 Are Vegetation X, Soil X, or Hydrology significantly disturbed? Are "Normal Circumstances" present? Yes X No
 Are Vegetation , Soil , or Hydrology naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes <u>X</u> No <u> </u>	Is the Sampled Area within a Wetland?	Yes <u> </u>	No <u>X</u>
Hydric Soil Present?	Yes <u> </u> No <u>X</u>			
Wetland Hydrology Present?	Yes <u> </u> No <u>X</u>			

Remarks:
 The property adjoining I-20 appears to be formed from fill material that has been shaped and graded. The fill pad largely covers the property and drops down to a basin on the eastern portion surrounded by constructed stormwater channels. No wetlands were observed on the property.

HYDROLOGY

Wetland Hydrology Indicators: <u>Primary Indicators (minimum of one is required; check all that apply)</u> <input type="checkbox"/> Surface Water (A1) <input type="checkbox"/> Aquatic Fauna (B13) <input type="checkbox"/> High Water Table (A2) <input type="checkbox"/> Marl Deposits (B15) (LRR U) <input type="checkbox"/> Saturation (A3) <input type="checkbox"/> Hydrogen Sulfide Odor (C1) <input type="checkbox"/> Water Marks (B1) <input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3) <input type="checkbox"/> Sediment Deposits (B2) <input type="checkbox"/> Presence of Reduced Iron (C4) <input type="checkbox"/> Drift Deposits (B3) <input type="checkbox"/> Recent Iron Reduction in Tilled Soils (C6) <input type="checkbox"/> Algal Mat or Crust (B4) <input type="checkbox"/> Thin Muck Surface (C7) <input type="checkbox"/> Iron Deposits (B5) <input type="checkbox"/> Other (Explain in Remarks) <input type="checkbox"/> Inundation Visible on Aerial Imagery (B7) <input type="checkbox"/> Water-Stained Leaves (B9)	<u>Secondary Indicators (minimum of two required)</u> <input type="checkbox"/> Surface Soil Cracks (B6) <input type="checkbox"/> Sparsely Vegetated Concave Surface (B8) <input type="checkbox"/> Drainage Patterns (B10) <input type="checkbox"/> Moss Trim Lines (B16) <input type="checkbox"/> Dry-Season Water Table (C2) <input type="checkbox"/> Crayfish Burrows (C8) <input type="checkbox"/> Saturation Visible on Aerial Imagery (C9) <input type="checkbox"/> Geomorphic Position (D2) <input type="checkbox"/> Shallow Aquitard (D3) <input type="checkbox"/> FAC-Neutral Test (D5) <input type="checkbox"/> Sphagnum Moss (D8) (LRR T, U)
--	--

Field Observations: Surface Water Present? Yes <u> </u> No <u>X</u> Depth (inches): <u> </u> Water Table Present? Yes <u> </u> No <u>X</u> Depth (inches): <u> </u> Saturation Present? Yes <u> </u> No <u>X</u> Depth (inches): <u> </u> (includes capillary fringe)	Wetland Hydrology Present?	Yes <u> </u>	No <u>X</u>
--	-----------------------------------	-----------------	-------------

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
 The point was taken below the fill pad slope in a graded area.

VEGETATION (Four Strata) – Use scientific names of plants.

Sampling Point: 3

Tree Stratum (Plot size: <u>30</u>)	Absolute % Cover	Dominant Species?	Indicator Status
1. <u>Populus deltoides</u>	<u>35</u>	<u>Yes</u>	<u>FAC</u>
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
	<u>35</u> =Total Cover		
	50% of total cover: <u>18</u>	20% of total cover: <u>7</u>	

Sapling/Shrub Stratum (Plot size: <u>30</u>)	Absolute % Cover	Dominant Species?	Indicator Status
1. <u>Populus deltoides</u>	<u>20</u>	<u>Yes</u>	<u>FAC</u>
2. <u>Liquidambar styraciflua</u>	<u>1</u>	<u>No</u>	<u>FAC</u>
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
	<u>21</u> =Total Cover		
	50% of total cover: <u>11</u>	20% of total cover: <u>5</u>	

Herb Stratum (Plot size: <u>30</u>)	Absolute % Cover	Dominant Species?	Indicator Status
1. <u>Symphotrichum ericoides</u>	<u>15</u>	<u>Yes</u>	<u>UPL</u>
2. <u>Sesbania vesicaria</u>	<u>5</u>	<u>No</u>	<u>FAC</u>
3. <u>Andropogon glomeratus</u>	<u>10</u>	<u>Yes</u>	<u>FACW</u>
4. <u>Juncus effusus</u>	<u>2</u>	<u>No</u>	<u>OBL</u>
5. <u>Cortaderia selloana</u>	<u>1</u>	<u>No</u>	<u>FACU</u>
6. <u>Rubus trivialis</u>	<u>5</u>	<u>No</u>	<u>FACU</u>
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____
11. _____	_____	_____	_____
12. _____	_____	_____	_____
	<u>38</u> =Total Cover		
	50% of total cover: <u>19</u>	20% of total cover: <u>8</u>	

Woody Vine Stratum (Plot size: _____)	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
	_____ =Total Cover		
	50% of total cover: _____	20% of total cover: _____	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 75.0% (A/B)

Prevalence Index worksheet:

Total % Cover of:	Multiply by:
OBL species <u>2</u>	x 1 = <u>2</u>
FACW species <u>10</u>	x 2 = <u>20</u>
FAC species <u>61</u>	x 3 = <u>183</u>
FACU species <u>6</u>	x 4 = <u>24</u>
UPL species <u>15</u>	x 5 = <u>75</u>
Column Totals: <u>94</u> (A)	<u>304</u> (B)
Prevalence Index = B/A = <u>3.23</u>	

Hydrophytic Vegetation Indicators:

 1 - Rapid Test for Hydrophytic Vegetation

X 2 - Dominance Test is >50%

 3 - Prevalence Index is ≤3.0¹

 Problematic Hydrophytic Vegetation¹ (Explain)

¹Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Four Vegetation Strata:

Tree – Woody plants, excluding vines, 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub – Woody plants, excluding vines, less than 3 in. DBH and greater than 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody Vine – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes X No _____

Remarks: (If observed, list morphological adaptations below.)
 The area appears to be regularly mowed, promoting opportunistic and early successional species. Stormwater drainage has encouraged obligate species in this area.

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)								
Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²		
0-7	7.5YR 4/6	100					Loamy/Clayey	
7-14	10YR 5/2	100					Loamy/Clayey	

¹Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.

²Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)

- Histosol (A1)
- Histic Epipedon (A2)
- Black Histic (A3)
- Hydrogen Sulfide (A4)
- Stratified Layers (A5)
- Organic Bodies (A6) (LRR P, T, U)
- 5 cm Mucky Mineral (A7) (LRR P, T, U)
- Muck Presence (A8) (LRR U)
- 1 cm Muck (A9) (LRR P, T)
- Depleted Below Dark Surface (A11)
- Thick Dark Surface (A12)
- Coast Prairie Redox (A16) (MLRA 150A)
- Iron Monosulfide (A18)
- Sandy Mucky Mineral (S1) (LRR O, S)
- Sandy Gleyed Matrix (S4)
- Sandy Redox (S5)
- Stripped Matrix (S6)
- Dark Surface (S7) (LRR P, S, T, U)
- Polyvalue Below Surface (S8) (LRR S, T, U)
- Thin Dark Surface (S9) (LRR S, T, U)
- Barrier Islands 1 cm Muck (S12) (MLRA 153B, 153D)
- Loamy Mucky Mineral (F1) (LRR O)
- Loamy Gleyed Matrix (F2)
- Depleted Matrix (F3)
- Redox Dark Surface (F6)
- Depleted Dark Surface (F7)
- Redox Depressions (F8)
- Marl (F10) (LRR U)
- Depleted Ochric (F11) (MLRA 151)
- Iron-Manganese Masses (F12) (LRR O, P, T)
- Umbric Surface (F13) (LRR P, T, U)
- Delta Ochric (F17) (MLRA 151)
- Reduced Vertic (F18) (MLRA 150A, 150B)
- Piedmont Floodplain Soils (F19) (MLRA 149A)
- Anomalous Bright Floodplain Soils (F20) (MLRA 149A, 153C, 153D)
- Very Shallow Dark Surface (F22) (MLRA 138, 152A in FL, 154)

Indicators for Problematic Hydric Soils³:

- 1 cm Muck (A9) (LRR O)
- 2 cm Muck (A10) (LRR S)
- Coast Prairie Redox (A16) (MLRA 149A)
- Reduced Vertic (F18) (outside MLRA 150A, 150B)
- Piedmont Floodplain Soils (F19) (LRR P, T)
- Anomalous Bright Floodplain Soils (F20) (MLRA 153B)
- Red Parent Material (F21)
- Very Shallow Dark Surface (F22) (outside MLRA 138, 152A in FL, 154)
- Other (Explain in Remarks)

³Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: _____
 Depth (inches): _____

Hydric Soil Present? Yes _____ No X

Remarks:

The soils appear to have been disturbed by the addition of fill material.

AGENCY DISCLOSURE NOTIFICATION

The public reporting burden for this collection of information, OMB Control Number 0710-0024, is estimated to average 30 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or burden reduction suggestions to the Department of Defense, Washington Headquarters Services, at whs.mc-alex.esd.mbx.dd-dod-information-collections@mail.mil. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. **PLEASE DO NOT RETURN YOUR REQUEST TO THE ABOVE EMAIL.**

PRIVACY ACT STATEMENT

Authorities: Rivers and Harbors Act, Section 10, 33 USC 403; Clean Water Act, Section 404, 33 USC 1344; Marine Protection, Research, and Sanctuaries Act, Section 103, 33 USC 1413; Regulatory Programs of the Corps of Engineers; Final Rule 33 CFR 320-332. Principal Purpose: Information provided on this form will be used in evaluating the application for a permit. Routine Uses: This information may be shared with the Department of Justice and other federal, state, and local government agencies, and the public and may be made available as part of a public notice as required by Federal law. Submission of requested information is voluntary, however, if information is not provided the permit application cannot be evaluated nor can a permit be issued. One set of original drawings or good reproducible copies which show the location and character of the proposed activity must be attached to this application (see sample drawings and/or instructions) and be submitted to the District Engineer having jurisdiction over the location of the proposed activity. An application that is not completed in full will be returned. System of Record Notice (SORN). The information received is entered into our permit tracking database and a SORN has been completed (SORN #A1145b) and may be accessed at the following website: <http://dpcl.d.defense.gov/Privacy/SORNsIndex/DOD-wide-SORN-Article-View/Article/570115/a1145b-ce.aspx>

Project/Site: Hawkins Crossing Road City/County: Meridian/Lauderdale Sampling Date: 11/12/2024
 Applicant/Owner: Quik Trip State: MS Sampling Point: 4
 Investigator(s): Jessica Rushing and Mackenzie Devine Section, Township, Range: 10, 6 North, 16 East
 Landform (hillside, terrace, etc.): lower elevation Local relief (concave, convex, none): concave Slope (%): 2-5
 Subregion (LRR or MLRA): LRR P, MLRA 133A Lat: 32.376340 Long: -88.654165 Datum: NAD 1983
 Soil Map Unit Name: Sweatmen NWI classification: N/A

Are climatic / hydrologic conditions on the site typical for this time of year? Yes No (If no, explain in Remarks.)
 Are Vegetation , Soil , or Hydrology significantly disturbed? Are "Normal Circumstances" present? Yes No
 Are Vegetation , Soil , or Hydrology naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Is the Sampled Area within a Wetland?	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Hydric Soil Present?	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>		Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Wetland Hydrology Present?	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>		Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>

Remarks:
 The property adjoining I-20 appears to be formed from fill material that has been shaped and graded. The fill pad largely covers the property and drops down to a basin on the eastern portion surrounded by constructed stormwater channels. No wetlands were observed on the property.

HYDROLOGY

Wetland Hydrology Indicators: <u>Primary Indicators (minimum of one is required; check all that apply)</u> <input type="checkbox"/> Surface Water (A1) <input type="checkbox"/> Aquatic Fauna (B13) <input type="checkbox"/> High Water Table (A2) <input type="checkbox"/> Marl Deposits (B15) (LRR U) <input type="checkbox"/> Saturation (A3) <input type="checkbox"/> Hydrogen Sulfide Odor (C1) <input type="checkbox"/> Water Marks (B1) <input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3) <input type="checkbox"/> Sediment Deposits (B2) <input type="checkbox"/> Presence of Reduced Iron (C4) <input type="checkbox"/> Drift Deposits (B3) <input type="checkbox"/> Recent Iron Reduction in Tilled Soils (C6) <input type="checkbox"/> Algal Mat or Crust (B4) <input type="checkbox"/> Thin Muck Surface (C7) <input type="checkbox"/> Iron Deposits (B5) <input type="checkbox"/> Other (Explain in Remarks) <input type="checkbox"/> Inundation Visible on Aerial Imagery (B7) <input type="checkbox"/> Water-Stained Leaves (B9)	<u>Secondary Indicators (minimum of two required)</u> <input type="checkbox"/> Surface Soil Cracks (B6) <input type="checkbox"/> Sparsely Vegetated Concave Surface (B8) <input type="checkbox"/> Drainage Patterns (B10) <input type="checkbox"/> Moss Trim Lines (B16) <input type="checkbox"/> Dry-Season Water Table (C2) <input type="checkbox"/> Crayfish Burrows (C8) <input type="checkbox"/> Saturation Visible on Aerial Imagery (C9) <input type="checkbox"/> Geomorphic Position (D2) <input type="checkbox"/> Shallow Aquitard (D3) <input type="checkbox"/> FAC-Neutral Test (D5) <input type="checkbox"/> Sphagnum Moss (D8) (LRR T, U)
--	--

Field Observations: Surface Water Present? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Depth (inches): _____ Water Table Present? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Depth (inches): _____ Saturation Present? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Depth (inches): _____ (includes capillary fringe)	Wetland Hydrology Present? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
--	---

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
 The point was taken below the fill pad in a maintained lawn.

VEGETATION (Four Strata) – Use scientific names of plants.

Sampling Point: 4

<u>Tree Stratum</u> (Plot size: <u>30</u>)	Absolute % Cover	Dominant Species?	Indicator Status	
1. _____	_____	_____	_____	Dominance Test worksheet: Number of Dominant Species That Are OBL, FACW, or FAC: <u>0</u> (A) Total Number of Dominant Species Across All Strata: <u>1</u> (B) Percent of Dominant Species That Are OBL, FACW, or FAC: <u>0.0%</u> (A/B)
2. _____	_____	_____	_____	
3. _____	_____	_____	_____	
4. _____	_____	_____	_____	
5. _____	_____	_____	_____	
6. _____	_____	_____	_____	
7. _____	_____	_____	_____	
8. _____	_____	_____	_____	
_____ = Total Cover				Prevalence Index worksheet: Total % Cover of: _____ Multiply by: _____ OBL species <u>0</u> x 1 = <u>0</u> FACW species <u>0</u> x 2 = <u>0</u> FAC species <u>0</u> x 3 = <u>0</u> FACU species <u>105</u> x 4 = <u>420</u> UPL species <u>0</u> x 5 = <u>0</u> Column Totals: <u>105</u> (A) <u>420</u> (B) Prevalence Index = B/A = <u>4.00</u>
50% of total cover: _____		20% of total cover: _____		
<u>Sapling/Shrub Stratum</u> (Plot size: <u>30</u>)	Absolute % Cover	Dominant Species?	Indicator Status	
1. _____	_____	_____	_____	
2. _____	_____	_____	_____	
3. _____	_____	_____	_____	
4. _____	_____	_____	_____	
5. _____	_____	_____	_____	
6. _____	_____	_____	_____	
7. _____	_____	_____	_____	
8. _____	_____	_____	_____	
_____ = Total Cover				
50% of total cover: _____		20% of total cover: _____		
<u>Herb Stratum</u> (Plot size: <u>30</u>)	Absolute % Cover	Dominant Species?	Indicator Status	
1. <u>Paspalum notatum</u>	<u>100</u>	<u>Yes</u>	<u>FACU</u>	
2. <u>Plantago lanceolata</u>	<u>5</u>	<u>No</u>	<u>FACU</u>	
3. _____	_____	_____	_____	
4. _____	_____	_____	_____	
5. _____	_____	_____	_____	
6. _____	_____	_____	_____	
7. _____	_____	_____	_____	
8. _____	_____	_____	_____	
9. _____	_____	_____	_____	
10. _____	_____	_____	_____	
11. _____	_____	_____	_____	
12. _____	_____	_____	_____	
_____ = Total Cover				
50% of total cover: <u>53</u>		20% of total cover: <u>21</u>		
<u>Woody Vine Stratum</u> (Plot size: _____)	Absolute % Cover	Dominant Species?	Indicator Status	
1. _____	_____	_____	_____	
2. _____	_____	_____	_____	
3. _____	_____	_____	_____	
4. _____	_____	_____	_____	
5. _____	_____	_____	_____	
_____ = Total Cover				
50% of total cover: _____		20% of total cover: _____		

¹Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Four Vegetation Strata:
Tree – Woody plants, excluding vines, 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.
Sapling/Shrub – Woody plants, excluding vines, less than 3 in. DBH and greater than 3.28 ft (1 m) tall.
Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.
Woody Vine – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No X

Remarks: (If observed, list morphological adaptations below.)
 The area appears to be regularly mowed and maintained for lawn grasses.

SOIL

Sampling Point: 4

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)								
Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²		
0-2	7.5YR 4/2	100					Loamy/Clayey	
2-14	10YR 5/8	100					Loamy/Clayey	

¹Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.

²Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)

- Histosol (A1) Thin Dark Surface (S9) (LRR S, T, U)
- Histic Epipedon (A2) Barrier Islands 1 cm Muck (S12)
- Black Histic (A3) **(MLRA 153B, 153D)**
- Hydrogen Sulfide (A4) Loamy Mucky Mineral (F1) (LRR O)
- Stratified Layers (A5) Loamy Gleyed Matrix (F2)
- Organic Bodies (A6) (LRR P, T, U) Depleted Matrix (F3)
- 5 cm Mucky Mineral (A7) (LRR P, T, U) Redox Dark Surface (F6)
- Muck Presence (A8) (LRR U) Depleted Dark Surface (F7)
- 1 cm Muck (A9) (LRR P, T) Redox Depressions (F8)
- Depleted Below Dark Surface (A11) Marl (F10) (LRR U)
- Thick Dark Surface (A12) Depleted Ochric (F11) (MLRA 151)
- Coast Prairie Redox (A16) (MLRA 150A) Iron-Manganese Masses (F12) (LRR O, P, T)
- Iron Monosulfide (A18) Umbric Surface (F13) (LRR P, T, U)
- Sandy Mucky Mineral (S1) (LRR O, S) Delta Ochric (F17) (MLRA 151)
- Sandy Gleyed Matrix (S4) Reduced Vertic (F18) (MLRA 150A, 150B)
- Sandy Redox (S5) Piedmont Floodplain Soils (F19) (MLRA 149A)
- Stripped Matrix (S6) Anomalous Bright Floodplain Soils (F20)
- Dark Surface (S7) (LRR P, S, T, U) **(MLRA 149A, 153C, 153D)**
- Polyvalue Below Surface (S8) Very Shallow Dark Surface (F22)
- (LRR S, T, U) (MLRA 138, 152A in FL, 154)**

Indicators for Problematic Hydric Soils³:

- 1 cm Muck (A9) (LRR O)
- 2 cm Muck (A10) (LRR S)
- Coast Prairie Redox (A16) (MLRA 149A)
- Reduced Vertic (F18)
- (outside MLRA 150A, 150B)**
- Piedmont Floodplain Soils (F19) (LRR P, T)
- Anomalous Bright Floodplain Soils (F20)
- (MLRA 153B)**
- Red Parent Material (F21)
- Very Shallow Dark Surface (F22)
- (outside MLRA 138, 152A in FL, 154)**
- Other (Explain in Remarks)

³Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: _____
 Depth (inches): _____

Hydric Soil Present? Yes _____ No X

Remarks:

The soils appear to have been disturbed and maintained for lawn.

AGENCY DISCLOSURE NOTIFICATION

The public reporting burden for this collection of information, OMB Control Number 0710-0024, is estimated to average 30 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or burden reduction suggestions to the Department of Defense, Washington Headquarters Services, at whs.mc-alex.esd.mbx.dd-dod-information-collections@mail.mil. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. **PLEASE DO NOT RETURN YOUR REQUEST TO THE ABOVE EMAIL.**

PRIVACY ACT STATEMENT

Authorities: Rivers and Harbors Act, Section 10, 33 USC 403; Clean Water Act, Section 404, 33 USC 1344; Marine Protection, Research, and Sanctuaries Act, Section 103, 33 USC 1413; Regulatory Programs of the Corps of Engineers; Final Rule 33 CFR 320-332. Principal Purpose: Information provided on this form will be used in evaluating the application for a permit. Routine Uses: This information may be shared with the Department of Justice and other federal, state, and local government agencies, and the public and may be made available as part of a public notice as required by Federal law. Submission of requested information is voluntary, however, if information is not provided the permit application cannot be evaluated nor can a permit be issued. One set of original drawings or good reproducible copies which show the location and character of the proposed activity must be attached to this application (see sample drawings and/or instructions) and be submitted to the District Engineer having jurisdiction over the location of the proposed activity. An application that is not completed in full will be returned. System of Record Notice (SORN). The information received is entered into our permit tracking database and a SORN has been completed (SORN #A1145b) and may be accessed at the following website: <http://dpcl.d.defense.gov/Privacy/SORNsIndex/DOD-wide-SORN-Article-View/Article/570115/a1145b-ce.aspx>

EXHIBIT 3



Ecological Services & Environmental Permitting



Photograph No. 1 – View of the typical vegetation at Data Point 1



Photograph No. 2 – View of the typical vegetation at Data Point 2



Photograph No.3 – View of the typical vegetation of Data Point 3



Photograph No. 4 – View of the typical vegetation of Data Point 4